



DEPARTMENT OF THE AIR FORCE  
HEADQUARTERS UNITED STATES AIR FORCE  
BOLLING AFB DC 20332-6188

FEB 11 1989

10 FEB 1989

REPLY TO AFOMS/ SGPR  
ATTN OF: BROOKS AFB, TEXAS 78235-5000


SUBJECT: Request for Exception from Six Month Leak Test Requirement USAF  
Radioactive Material Permit No. 04-09951-1AFP

TO: USNRC, Region IV  
ATTN: Mr. D. Blair Spitzberg  
611 Ryan Plaza, Suite 1000  
Arlington TX 76011

1. The 1155 Technical Operation Division at McClellan AFB CA is currently authorized nine strontium 90 Titanate (one model 25 A at 98 kCi, one model E at 79 kCi, and seven model Fs at 81 kCi each) and one strontium 90 orthotitanate (model 100F at 250 kCi), radiothermoelectric generators (RTGs) manufactured by Teledyne Energy Systems. The RTGs are used at an unmanned facility at five sites, each with two RTGs in the vicinity of Benchmark Monty, Burnt Mountain AK for the generation of electricity. These sites are 16.5 miles E/NE of Christian AK and 65 miles north of Ft. Yukon AK (latitude N67 25'06'' and longitude W144 36'11'') and are contained in locked, fenced, contained and secure areas. Access to the sites can only be practically accomplished by air.

2. The current leak test condition is six months and has been carried out thus far during late spring and early fall. However, with this schedule, there have been problems in obtaining safe air transportation of personnel to the sites due to unpredictable and inclement weather conditions. We do not believe that the incremental radiation safety value attained by performing six month leak tests offsets the endangerment to human life presented by attempting air travel during unpredictable and inclement weather conditions which prevail most of the year at the sites. Request NRC grant an exception to the six month leak test requirement, allowing leak tests and physical inventories to be made annually during the few months of most stable weather conditions which occur in summer.

3. Any questions or comments regarding the above should be addressed to this office at commercial telephone number (512) 536-3331 or in writing.

  
DAVID G. WOOD, COL, USAF, BSC  
Executive Secretary,  
USAF Radioisotope Committee  
Office of the Surgeon General

cc: HQ USAF/SGP  
HQ AFLC/SGBE  
1155 TOD/DLS

BLB

89-295



DEPARTMENT OF THE AIR FORCE  
 HEADQUARTERS UNITED STATES AIR FORCE  
 BOLLING AFB DC 20332-6188

LN 42-23539-01AF  
 DN 030-28641

10 FEB 1988

REPLY TO AFOMD SGPR  
 ATTN OF: BROOKS AFIL TEXAS 78235-6000

SUBJECT: Request for Exception from Six Month Leak Test Requirement USAF  
 Radioactive Material Permit No. 04-09951-1AFP

TO: USNRC, Region IV  
 ATTN: Mr. D. Blair Spitzberg  
 611 Ryan Plaza, Suite 1000  
 Arlington TX 76011

1. The 1155 Technical Operation Division at McClellan AFB CA is currently authorized nine strontium 90 Titanate (one model 25 A at 98 kCi, one model E at 79 kCi, and seven model Fs at 81 kCi each) and one strontium 90 orthotitanate (model 100F at 250 kCi), radiothermoelectric generators (RTGs) manufactured by Teledyne Energy Systems. The RTGs are used at an unmanned facility at five sites, each with two RTGs in the vicinity of Benchmark Monty, Burnt Mountain AK for the generation of electricity. These sites are 16.5 miles E/NE of Christian AK and 65 miles north of Ft. Yukon AK (latitude N67 26'06'' and longitude W144 36'11'') and are contained in locked, fenced, contained and secure areas. Access to the sites can only be practically accomplished by air.

2. The current leak test condition is six months and has been carried out thus far during late spring and early fall. However, with this schedule, there have been problems in obtaining safe air transportation of personnel to the sites due to unpredictable and inclement weather conditions. We do not believe that the incremental radiation safety value attained by performing six month leak tests offsets the endangerment to human life presented by attempting air travel during unpredictable and inclement weather conditions which prevail most of the year at the sites. Request NRC grant an exception to the six month leak test requirement, allowing leak tests and physical inventories to be made annually during the few months of most stable weather conditions which occur in summer.

3. Any questions or comments regarding the above should be addressed to this office at commercial telephone number (512) 636-3331 or in writing.

DAVID G. WOOD, Col., USAF, BSC  
 Executive Secretary,  
 USAF Radioisotope Committee  
 Office of the Surgeon General

cc: HQ USAF/SGP  
 HQ AFLC/SGBE  
 1155 TOD/DLS

FEE EXEMPT

46 2436

8903210558 890306  
 REG4 LIC30  
 42-23539-01AF PNU