

Form TI-1 Case Resolution

Case Status	<input type="checkbox"/> Open	<input checked="" type="checkbox"/> Closed
RCODE: __64051__		
Region: __1__		
OLD - Complete Name, Address, Contact, Phone Number: Brooks Foods U.S. Route 36 Mount Summit, IN 47361 Contact: Bill Pattison		
NEW - Complete Name, Address, Contact, Phone Number: Hoopeston Foods, Inc. 215 W. Washington Street P.O. Box 405 Hoopeston, IL Contact: Ted Goodner 217-283-7771, x221		
Agreement State Licensee? (Double Check)	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No
Moved to an Agreement State?	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No
Describe Follow-up: (Telephone, Internet, Chamber of Commerce, Other) None		
Describe Communication with Registration Vendor: Contacted Michelle Alvarado at Industrial Dynamics (310-257-2202) who confirmed that the devices had been transferred via Industrial Dynamics and that the transfer was included in the appropriate report to the NRC.		
Vendor Follow-up Action: None		
Final Action Taken:		
Cause of Bad Address/Lesson Learned:		

Form TI-2: Device Information

RCODE: 64051_____								
ID	Model Number	Serial Number	Isotope	Activity (mCi)	Sold Date	Vendor	Status (A or N)	Comments
1	FT-12	64051	²⁴¹ Am	100	19752	1586-70GL	A	
2	FT-50C	5567	²⁴¹ Am	100	19934	1586-70GL	A	
For additional GLD's received by the licensee identified during the inspection:								
ID	Model Number	Serial Number	Isotope	Activity	Sold Date	Vendor	How obtained	Comments

Status Codes:

A - Source accounted for

N - Source not accounted for

Form TI-3: General Licensee Inspection Documentation

RCODE: <u>64051</u>	
General Licensee Information:	
<input type="checkbox"/>	Check Box if Current Complete Name, Mailing Address, Contact, and Phone Number is Same as Provided by ORNL. If not, include correct information below:
<input type="checkbox"/>	Hoopeston Foods, Inc. 215 W. Washington Street P.O. Box 405 Hoopeston, IL Contact: Ted Goodner 217-283-7771, x221
Results of inspection: (check the appropriate boxes)	
<input type="checkbox"/>	The general licensee of record is located at the address of record and
<input type="checkbox"/>	all GLD are accounted for
<input type="checkbox"/>	<u>not</u> all GLD are accounted for
<input type="checkbox"/>	The general licensee of record is <u>not</u> located at the address of record, however GLD are being used under new ownership at the address of record and
<input type="checkbox"/>	all GLD are accounted for
<input type="checkbox"/>	<u>not</u> all GLD are accounted for
<input type="checkbox"/>	The general licensee of record is <u>not</u> located at the address of record, however they are using GLD at another location and
<input type="checkbox"/>	all GLD are accounted for
<input type="checkbox"/>	<u>not</u> all GLD are accounted for;
X	Neither the general licensee of record nor the facility operated by the general licensee are located at the address of record and the site has been abandoned or is being used for an alternate purpose.
<input type="checkbox"/>	Other: (explain)
Gauge Information:	
ID	For each gauge for which status is unaccounted for (see last column of Form TI-2), provide any conclusions about location of the gauge:
<input type="checkbox"/>	
<input type="checkbox"/>	

The sources were transferred, via the vendor, to another facility.

Inspector: Keith Brown, Health Physicist
Nuclear Materials Safety Branch 2

Approved By: John D. Kinneman, Chief
Nuclear Materials Safety Branch 2