ML020560571.txt

LICENSEE: ROSEMONT AEROSPACE INCORPORATED

SITE: ROSEMONT AEROSPACE INCORPORATE

DOCKET:

EVENT DATE: 05-04-93

RX TYPE:

VENDORS:

EVENT TIME: 00:00

NOTIFY DATE: 05-04-93

EMERGENCY CLASS: N/A REGION: 3 STATE: MN TIME: 17:33

OPS OFFICER: GREG SCARFO

10 CFR SECTION: CDEF 21.21(b)(2) DEFECTS/NONCOMPLIANCE

A PART 21 REPORT WAS RECEIVED BY THE OPERATIONS CENTER FROM ROSEMONT AEROSPACE INCORPORATED OF EDEN PRAIRIE, MN, REGARDING FOUR PRESSURE TRANSMITTERS THAT WERE ASSEMBLED AND SHIPPED TO LICENSEES WITH INCORRECT FLANGE O-RINGS. ROSEMONT IS IDENTIFYING AND NOTIFYING THE LICENSEES AFFECTED. IT IS NOT KNOWN WHETHER THESE TRANSMITTERS ARE UTILIZED IN SAFETY SYSTEMS.