

LICENSEE: IOWA ELECTRIC LIGHT & POWER CO.  
 SITE: DUANE ARNOLD 1 EN NUMBER:26137  
 DOCKET: 05000331 EVENT DATE: 09-28-93  
 RX TYPE: BWR EVENT TIME: 15:31  
 VENDORS: GE-4 NOTIFY DATE: 09-28-93  
 EMERGENCY CLASS: N/A REGION: 3 STATE: IA TIME: 17:50  
 OPS OFFICER: JACK LEWIS  
 10 CFR SECTION: AIND 50.72(b)(2)(iii)(D) ACCIDENT MITIGATION  
 UNIT SCRAM RX INIT INITIAL MODE CURR CURRENT MODE  
 CODE CRIT PWR PWR  
 1 N N 0 COLD SHUTDOWN 0 COLD SHUTDOWN

-POSSIBILITY OF BOTH DIESELS BEING INOPERABLE DURING FUEL MOVEMENT-

BETWEEN AUGUST 7 AND AUGUST 11, 1993 THE LICENSEE WAS MOVING FUEL AND THE "A" DIESEL GENERATOR WAS OUT OF SERVICE FOR MAINTENANCE.

ON 9/22/93 THE LICENSEE PERFORMED A LOOP LOCA TEST, WHICH DETERMINED THAT THE OUTPUT BREAKER ON THE "B" DIESEL GENERATOR WOULD NOT CLOSE IN, THIS WOULD RENDER THE "B" DIESEL GENERATOR INOPERABLE.

BASED ON THE ABOVE INFORMATION, A REVIEW BY THE LICENSEE DETERMINED THAT BOTH DIESEL GENERATORS WOULD HAVE BEEN INOPERABLE DURING THE TIME PERIOD THAT FUEL WAS BEING MOVED.

THE LICENSEE INFORMED THE NRC RESIDENT INSPECTOR.