



**UNITED STATES
NUCLEAR REGULATORY COMMISSION
REGION IV
611 RYAN PLAZA DRIVE, SUITE 400
ARLINGTON, TEXAS 76011-8064**

March 4, 2002

William T. Cottle, President and
Chief Executive Officer
STP Nuclear Operating Company
P.O. Box 289
Wadsworth, Texas 77483

**SUBJECT: ANNUAL ASSESSMENT - SOUTH TEXAS PROJECT ELECTRIC GENERATING
STATION (REPORT 50-498, 499/02-01)**

Dear Mr. Cottle:

On February 13, 2002, the NRC staff completed its end-of-cycle plant performance assessment of South Texas Project Electric Generating Station. The end-of-cycle review for South Texas Project Electric Generating Station involved the participation of all technical divisions in evaluating performance indicators for the most recent quarter and inspection results for the period from April 1 through December 31, 2001. The purpose of this letter is to inform you of our assessment of your safety performance during this period and our plans for future inspections at your facility. This will provide you an opportunity to prepare for these inspections and to inform us of any planned inspections which may conflict with your plant activities.

As discussed in our previous annual assessment letter, dated May 29, 2001, this inspection and assessment cycle consisted of three quarters (i.e., the second, third, and fourth quarters of Calendar Year 2001) instead of the usual four quarters. This change was implemented in order to align the inspection and assessment cycle with the calendar year beginning on January 1, 2002.

Overall, South Texas Project Electric Generating Station operated in a manner that preserved public health and safety, and fully met all cornerstone objectives. Plant performance for the most recent quarter, as well as the first two quarters of the assessment cycle, was within the Licensee Response Column of the NRC's Action Matrix. This is based on all inspection findings being classified as having very low safety significance (Green) and all performance indicators indicating performance at a level requiring no additional NRC oversight (Green). Therefore, we plan to conduct only baseline inspections at your facility through December 28, 2002, with two exceptions. The scheduled replacement of the Unit 2 steam generators is a major and infrequent activity that will receive additional inspection. Consequently, some baseline and additional inspection resources will be focused on the steam generator replacement activity. The additional inspection will be conducted in accordance with NRC Inspection Procedure 50001, "Steam Generator Replacement Inspection." Also, inspection will be conducted on Unit 2 in accordance with Temporary Instruction 2515/145, "Circumferential Cracking of Reactor Pressure Vessel Head Penetration Nozzles (NRC Bulletin 2001-01)."

Immediately following the terrorist attacks on the World Trade Center and the Pentagon, the NRC issued safeguards advisories recommending that nuclear power plant licensees go to the highest level of security, and all promptly did so. With continued uncertainty about the possibility of additional terrorist activities, the Nation's nuclear power plants, including South Texas Project Electric Generating Station, remain at a high level of security. On February 25, 2002, the NRC issued an Order to all nuclear power plant licensees, requiring them to take certain additional interim compensatory measures to address the generalized high-level threat environment. These additional compensatory requirements will provide the NRC with reasonable assurance that public health and safety and the common defense and security continue to be adequately protected in the current generalized high-level threat environment. These requirements will remain in effect pending notification from the Commission that a significant change in the threat environment occurs or until the Commission determines that other changes are needed following a more comprehensive re-evaluation of current safeguards and security programs. To date we have monitored STP Nuclear Operating Company's actions in response to the terrorist attacks through a series of audits. With the issuance of the Order, we will evaluate STP Nuclear Operating Company's compliance with these interim requirements.

The enclosed inspection plan details the inspections scheduled through March 31, 2003. The inspection plan is provided to minimize the resource impact on your staff and to allow for scheduling conflicts and personnel availability to be resolved in advance of inspector arrival onsite. Routine resident inspections are not listed due to their ongoing and continuous nature. The last 6 months of the inspection plan are tentative and may be revised at the Midcycle Review meeting.

In accordance with 10 CFR 2.790 of the NRC's "Rules of Practice," a copy of this letter and its enclosure will be made available electronically for public inspection in the NRC Public Document Room or from the Publicly Available Records (PARS) component of NRC's document system (ADAMS). ADAMS is accessible from the NRC Web site at <http://www.nrc.gov/reading-rm/adams.html> (the Public Electronic Reading Room).

If circumstances arise which cause us to change this inspection plan, we will contact you to discuss the change as soon as possible. Please contact me at (817) 860-8148 with any questions you may have regarding this letter or the inspection plan.

Sincerely,

/RA/

William D. Johnson, Chief
Project Branch A
Division of Reactor Projects

Dockets: 50-498, 50-499
Licenses: NPF-76, NPF-80

Enclosure:

South Texas Project Electric
Generating Station Inspection/Activity Plan

cc w/enclosure:

J. J. Sheppard, Vice President
Engineering & Technical Services
STP Nuclear Operating Company
P.O. Box 289
Wadsworth, Texas 77483

S. M. Head, Manager, Licensing
Nuclear Quality & Licensing Department
STP Nuclear Operating Company
P.O. Box 289, Mail Code: N5014
Wadsworth, Texas 77483

A. Ramirez/C. M. Canady
City of Austin
Electric Utility Department
721 Barton Springs Road
Austin, Texas 78704

M. T. Hardt/W. C. Gunst
City Public Service Board
P.O. Box 1771
San Antonio, Texas 78296

D. G. Tees/R. L. Balcom
Houston Lighting & Power Company
P.O. Box 1700
Houston, Texas 77251

Jon C. Wood
Matthews & Branscomb
112 E. Pecan, Suite 1100
San Antonio, Texas 78205

A. H. Gutterman, Esq.
Morgan Lewis
1111 Pennsylvania Avenue NW
Washington, DC 20004

C. A. Johnson/R. P. Powers
AEP - Central Power and Light Company
P.O. Box 289, Mail Code: N5022
Wadsworth, Texas 77483

INPO
Records Center
700 Galleria Parkway
Atlanta, Georgia 30339-5957

Richard A. Ratliff, Chief
Bureau of Radiation Control
State of Texas
1100 West 49th Street
Austin, Texas 78756

Jim Calloway
Public Utility Commission
William B. Travis Building
P.O. Box 13326
1701 North Congress Avenue
Austin, Texas 78701-3326

John L. Howard, Director
Environmental and Natural Resources Policy
Office of the Governor
P.O. Box 12428
Austin, Texas 78711-3189

Greg Westmoreland, Judge
Matagorda County
Matagorda County Courthouse
1700 Seventh Street
Bay City, Texas 77414

Charles Martinez, Jr.
Mayor, City of Bay City
City Hall
1901 Fifth Street
Bay City, Texas 77414

Robert McMahon
Mayor, City of Palacios
P.O. Box 845
Palacios City Hall
Palacios, Texas 77465

James Mitchell, Sheriff
Matagorda County
2323 Avenue E
Bay City, Texas 77414

STP Nuclear Operating Company

-5-

Federal Emergency Management Agency
Ron Castleman, Regional Director
Region VI, Federal Center
800 North Loop 288
Denton, Texas 76201-3698

Roger Mulder
State Energy Conservation Office
111 E 17th Street, Room 1114
Austin, Texas 78711

Electronic distribution by RIV:

Regional Administrator **(EWM)**

DRP Director **(KEB)**

DRS Director **(ATH)**

Senior Resident Inspector **(NFO)**

Branch Chief, DRP/A **(DNG)**

Senior Project Engineer, DRP/A **(KMK)**

Staff Chief, DRP/TSS **(PHH)**

RITS Coordinator **(NBH)**

B. Henderson, PAO **(BWH)**

W. A. Maier, RSLO **(WAM)**

C. J. Gordon **(CJG)**

DRS Branch Chiefs **(GMG, ATG, CSM)**

W. D. Travers, EDO **(WDT)**

M. Johnson, Chief, NRR/DIPM/IIPB **(MRJ1)**

R. K. Frahm, PPR Program Manager, NRR/DIPM/IIPB **(RKF)**

B. A. Boger, Associate Dir. for Inspection and Programs **(BAB2)**

B. W. Sheron, Associate Dir. for Project Licensing and Technical Analysis **(BWS)**

J. Shea, Chief, Regional Operations Staff, OEDO **(JWS1)**

S. Richards, NRR Project Director **(SAR)**

R. Gramm, Chief, Section 1, NRR/DLPM **(RAG)**

J. Nakoski, NRR Project Manager **(JAN1)**

RidsNrrDipmlipb

Hard Copy:

Records Center, INPO

S:\DRP\DRPDIR\EOC 2002\Assessment Letters\STP.wpd

RIV:C:DRP/A	D:DRS	D:DRP	For signature	
DNGGraves;df	ATHowell	KEBrockman	WDJohnson	
/RA/	/RA/	/RA/	/RA/	
For review	2/27/02	3/4/02	3/4/02	

OFFICIAL RECORD COPY

T=Telephone

E=E-mail

F=Fax

South Texas Project
Inspection / Activity Plan
03/01/2002 - 03/30/2003

Unit Number	Inspection Activity	Title	No. of Staff on Site	Planned Dates		Inspection Type
				Start	End	
	SGINSP1 - SG REPLACEMENT INSPECTION PERIOD 1		2			
2	IP 50001	Steam Generator Replacement Inspection		03/17/2002	06/15/2002	Other Routine
	EMB - STP STEAM GENERATOR REPL 50.59 INSP		1			
2	IP 7111102	Evaluation of Changes, Tests, or Experiments		04/08/2002	04/12/2002	Baseline Inspections
	PSB-S1 - ACCESS AUTH/CONTROL, SEC PLAN, AND PIV		1			
1, 2	IP 7113001	Access Authorization Program (Behavior Observation Only)		04/15/2002	04/19/2002	Baseline Inspections
1, 2	IP 7113002	Access Control (Search of Personnel, Packages, and Vehicles: Identification and Authorizati		04/15/2002	04/19/2002	Baseline Inspections
1, 2	IP 7113004	Security Plan Changes		04/15/2002	04/19/2002	Baseline Inspections
1, 2	IP 71151	Performance Indicator Verification		04/15/2002	04/19/2002	Baseline Inspections
	EMB - TRIENNIEL FIRE PROTECTION INSPECTION		4			
1, 2	IP 7111105T	Fire Protection		05/20/2002	05/24/2002	Baseline Inspections
	SGINSP2 - SG REPLACEMENT INSPECTION PERIOD 2		2			
2	IP 50001	Steam Generator Replacement Inspection		06/16/2002	09/21/2002	Other Routine
	TM-RP-P - RP TEAM INSPECTION PUBLIC		4			
1, 2	IP 7112103	Radiation Monitoring Instrumentation		06/17/2002	06/21/2002	Baseline Inspections
1, 2	IP 7112201	Radioactive Gaseous and Liquid Effluent Treatment and Monitoring Systems		06/17/2002	06/21/2002	Baseline Inspections
1, 2	IP 7112202	Radioactive Material Processing and Transportation		06/17/2002	06/21/2002	Baseline Inspections
1, 2	IP 7112203	Radiological Environmental Monitoring Program		06/17/2002	06/21/2002	Baseline Inspections
	PSB-EP1 - EP EXERCISE BASELINE INSPECTION		3			
1, 2	IP 7111401	Exercise Evaluation		07/08/2002	07/12/2002	Baseline Inspections
1, 2	IP 7111404	Emergency Action Level and Emergency Plan Changes		07/08/2002	07/12/2002	Baseline Inspections
1, 2	IP 71151	Performance Indicator Verification		07/08/2002	07/12/2002	Baseline Inspections
	RP-3 - ALARA		1			
1, 2	IP 7112102	ALARA Planning and Controls		07/15/2002	07/19/2002	Baseline Inspections
	EMB - PERM MODS		2			
1, 2	IP 7111117B	Permanent Plant Modifications		08/12/2002	08/16/2002	Baseline Inspections
	SGINSP3 - SG REPLACEMENT INSPECTION PERIOD 3		2			
2	IP 50001	Steam Generator Replacement Inspection		09/22/2002	12/21/2002	Other Routine
	RP-1 - ACRSA AND PIV		1			
1, 2	IP 7112101	Access Control to Radiologically Significant Areas		10/21/2002	10/25/2002	Baseline Inspections
1, 2	IP 71151	Performance Indicator Verification		10/21/2002	10/25/2002	Baseline Inspections
	EMB - ISI UNIT 2		1			
2	IP 7111108	Inservice Inspection Activities		11/04/2002	11/08/2002	Baseline Inspections

This report does not include INPO and OUTAGE activities.
This report shows only on-site and announced inspection procedures.

South Texas Project
Inspection / Activity Plan
03/01/2002 - 03/30/2003

Unit Number	Inspection Activity	Title	No. of Staff on Site	Planned Dates		Inspection Type
				Start	End	
	TI 145-2 - TI 2515/145 UNIT 2		2			
2	IP 2515/145	Circumferential Cracking of Reactor Pressure Vessel Head Penetration Nozzles (NRC Bulletin :		11/04/2002	11/08/2002	Safety Issues
	EMB - ISI/SG - UNIT 2		1			
2	IP 7111108	Inservice Inspection Activities		12/09/2002	12/13/2002	Baseline Inspections
	EMB - BIENNIAL MR INSPECTION		1			
1, 2	IP 7111112B	Maintenance Rule Implementation		01/13/2003	01/17/2003	Baseline Inspections
	RP-4 - ALARA(4)		1			
1, 2	IP 7112102	ALARA Planning and Controls		01/13/2003	01/17/2003	Baseline Inspections
	OB-PIR - STP PIR INSPECTION		4			
1, 2	IP 71152	Identification and Resolution of Problems		02/24/2003	03/14/2003	Baseline Inspections
	EMB - HEAT SINKS		1			
1, 2	IP 7111107B	Heat Sink Performance		03/10/2003	03/14/2003	Baseline Inspections

This report does not include INPO and OUTAGE activities.
This report shows only on-site and announced inspection procedures.