

PATHFINDER

 A Cogema Resources Company

April 1, 2002

Mr. Melvyn N. Leach, Chief
Fuel Cycle Licensing Branch
Division of Fuel Cycle Safety and Safeguards
Office of Nuclear Material Safety and Safeguards
U. S. Nuclear Regulatory Commission
11545 Rockville Pike
Rockville, Maryland 20852-2738

Re: **Submittal of the Shirley Basin Annual Groundwater Corrective Action Report
License No. SUA-442, Docket No. 40-6622**

Dear Mr. Leach:

Enclosed please find two copies of the annual report on the groundwater corrective action program at the Shirley Basin mill and tailings site. This report is submitted in response to the requirement of license condition 47D. Please contact me if there are any questions regarding the report.

Sincerely,




T. W. Hardgrove
Operations Manager

Enclosure

Cc: C. L. Cain, USNRC Region IV
Ken Schreuder, Wyoming DEQ/SHWD
D. L. Wichers
J. R. Blaise
Hydro-Engineering w/o encl.

NMSS01 Public.



HYDROLOGIC MONITORING FOR SHIRLEY BASIN'S TAILINGS
SEEPAGE CONTROL PLAN