

November 13, 1996

Mr. E. E. Fitzpatrick, Vice President  
Indiana Michigan Power  
Nuclear Generation Group  
500 Circle Drive  
Buchanan, MI 49107

SUBJECT: DONALD C. COOK NUCLEAR PLANT, UNIT NOS. 1 AND 2 - CORRECTION TO  
AMENDMENT NOS. 212 AND 197 RE: OPERATIONS SUPERINTENDENT  
REQUIREMENTS IN ADMINISTRATIVE CONTROLS OF TECHNICAL  
SPECIFICATIONS (TAC NOS. M94873 AND M94874)

Dear Mr. Fitzpatrick:

On October 29, 1996, the Commission issued Amendment Nos. 212 and 197 to Facility Operating License Nos. DPR-58 and No. DPR-74 for the Donald C. Cook Nuclear Plant, Unit Nos. 1 and 2, respectively. The amendments consisted of changes to the administrative controls section of the technical specifications to change the operator license requirements for operations management.

TS page 6-2 for both Units 1 and 2 inadvertently included a section that had been previously deleted by Amendment Nos. 208 and 192 issued March 11, 1996, on fire protection and detection systems.

Copies of the corrected TS page TS 6-2 for Unit Nos. 1 and 2 are enclosed.

If you have any questions on this action, please call me at 301/415-3017.

Sincerely,

ORIGINAL SIGNED BY: John B. Hickman

John B. Hickman, Project Manager  
Project Directorate III-3  
Division of Reactor Projects - III/IV  
Office of Nuclear Reactor Regulation

Docket Nos. 50-315 and 50-316

Enclosures: Corrected TS page 6-2 (2 pages)

cc w/encls: See next page

DOCUMENT NAME: G:\DCCOOK\C094873.COR

To receive a copy of this document, indicate in the box: "C" = Copy without attachment/enclosure "E" = Copy with attachment/enclosure "N" = No copy

|        |                     |   |                           |   |  |
|--------|---------------------|---|---------------------------|---|--|
| OFFICE | LA:PD33             | E | PM:PD33                   | E |  |
| NAME   | DFoster-Cursen      |   | JHickman: <i>JHickman</i> |   |  |
| DATE   | 11/6/96 <i>df-c</i> |   | 11/13/96                  |   |  |

OFFICIAL RECORD COPY

*DFol*  
*11*

180024

9611180246 961113  
PDR ADOCK 05000315  
PDR

**NRC FILE CENTER COPY**



UNITED STATES  
NUCLEAR REGULATORY COMMISSION  
WASHINGTON, D.C. 20555-0001

November 13, 1996

Mr. E. E. Fitzpatrick, Vice President  
Indiana Michigan Power  
Nuclear Generation Group  
500 Circle Drive  
Buchanan, MI 49107

SUBJECT: DONALD C. COOK NUCLEAR PLANT, UNIT NOS. 1 AND 2 - CORRECTION TO  
AMENDMENT NOS. 212 AND 197 RE: OPERATIONS SUPERINTENDENT  
REQUIREMENTS IN ADMINISTRATIVE CONTROLS OF TECHNICAL  
SPECIFICATIONS (TAC NOS. M94873 AND M94874)

Dear Mr. Fitzpatrick:


On October 29, 1996, the Commission issued Amendment Nos. 212 and 197 to Facility Operating License Nos. DPR-58 and No. DPR-74 for the Donald C. Cook Nuclear Plant, Unit Nos. 1 and 2, respectively. The amendments consisted of changes to the administrative controls section of the technical specifications to change the operator license requirements for operations management.

TS page 6-2 for both Units 1 and 2 inadvertently included a section that had been previously deleted by Amendment Nos. 208 and 192 issued March 11, 1996, on fire protection and detection systems.

Copies of the corrected TS page TS 6-2 for Unit Nos. 1 and 2 are enclosed.

If you have any questions on this action, please call me at 301/415-3017.

Sincerely,

  
John B. Hickman, Project Manager  
Project Directorate III-3  
Division of Reactor Projects - III/IV  
Office of Nuclear Reactor Regulation

Docket Nos. 50-315 and 50-316

Enclosures: Corrected TS page 6-2 (2 pages)

cc w/encls: See next page

Mr. E. E. Fitzpatrick  
Indiana Michigan Power Company

Donald C. Cook Nuclear Plant

cc:

Regional Administrator, Region III  
U.S. Nuclear Regulatory Commission  
801 Warrenville Road  
Lisle, Illinois 60532-4351

Mr. Steve J. Brewer  
Indiana Michigan Power  
Nuclear Generation Group  
500 Circle Drive  
Buchanan, Michigan 49107

Attorney General  
Department of Attorney General  
525 West Ottawa Street  
Lansing, Michigan 48913

Township Supervisor  
Lake Township Hall  
P.O. Box 818  
Bridgman, Michigan 49106

Al Blind, Site Vice President  
Donald C. Cook Nuclear Plant  
1 Cook Place  
Bridgman, Michigan 49106

U.S. Nuclear Regulatory Commission  
Resident Inspector's Office  
7700 Red Arrow Highway  
Stevensville, Michigan 49127

Gerald Charnoff, Esquire  
Shaw, Pittman, Potts and Trowbridge  
2300 N Street, N. W.  
Washington, DC 20037

Mayor, City of Bridgman  
Post Office Box 366  
Bridgman, Michigan 49106

Special Assistant to the Governor  
Room 1 - State Capitol  
Lansing, Michigan 48909

Drinking Water and Radiological  
Protection Division  
Michigan Department of  
Environmental Quality  
3423 N. Martin Luther King Jr Blvd  
P. O. Box 30630 CPH Mailroom  
Lansing, Michigan 48909-8130

DATED: November 13, 1996

**CORRECTION TO:**

AMENDMENT NO. 212 TO FACILITY OPERATING LICENSE NO. DPR-58-D. C. COOK-UNIT 1  
AMENDMENT NO. 197 TO FACILITY OPERATING LICENSE NO. DPR-74-D. C. COOK-UNIT 2

**DISTRIBUTION**

Docket File (Docket Nos. 50-315/50-316)

PUBLIC

PDIII-3 Reading

J. Roe

D. Foster-Curseen

G. Marcus

J. Hickman (2)

OGC

G. Hill, IRM (4)

C. Grimes, O-11F23

J. Arildsen

ACRS

L. Miller, RIII

## 6.0 ADMINISTRATIVE CONTROLS

---

### 6.2 ORGANIZATION (Continued)

#### FACILITY STAFF

6.2.2 The Facility organization shall be subject to the following:

- a. Each on duty shift shall be composed of at least the minimum shift crew composition shown in Table 6.2-1.
- b. At least one licensed Operator shall be in the control room when fuel is in the reactor. In addition, while the unit is in Mode 1, 2, 3, or 4, at least one licensed Senior Operator shall be in the control room.
- c. An individual\* qualified in radiation protection procedures shall be on site when fuel is in the reactor.
- d. All CORE ALTERATIONS shall be directly supervised by a licensed Senior Operator trained or qualified in refueling and CORE ALTERATIONS (SO-CA) who has no other concurrent responsibilities during this operation.
- e. The amount of overtime worked by plant staff members performing safety-related functions must be limited in accordance with NRC Policy Statement on working hours (Generic Letter 82-12).
- f. The Shift Supervisor, Assistant Shift Supervisor, and Unit Supervisor shall hold a Senior Operator License.
- g. The Operations Superintendent must hold or have held a Senior Operator License at Cook Nuclear Plant or a similar reactor, or have been certified for equivalent senior operator knowledge. If the Operations Superintendent does not hold a Senior Operator License, then a line (v. staff) operations middle manager shall hold a Senior Operator License for the purposes of directing operational activities.

---

\* The unexpected absence, for a period of time not to exceed 2 hours, of the on-site individual qualified in radiation protection procedures is permitted provided immediate action is taken to fill the required position.

6.2 ORGANIZATION (Continued)

FACILITY STAFF

6.2.2 The Facility organization shall be subject to the following:

- a. Each on duty shift shall be composed of at least the minimum shift crew composition shown in Table 6.2-1.
- b. At least one licensed Operator shall be in the control room when fuel is in the reactor. In addition, while the unit is in Mode 1, 2, 3, or 4, at least one licensed Senior Operator shall be in the control room.
- c. An individual\* qualified in radiation protection procedures shall be on site when fuel is in the reactor.
- d. All CORE ALTERATIONS shall be directly supervised by a licensed Senior Operator trained or qualified in refueling and CORE ALTERATIONS (SO-CA) who has no other concurrent responsibilities during this operation.
- e. The amount of overtime worked by plant staff members performing safety-related functions must be limited in accordance with NRC Policy Statement on working hours (Generic Letter 82-12).
- f. The Shift Supervisor, Assistant Shift Supervisor, and Unit Supervisor shall hold a Senior Operator License.
- g. The Operations Superintendent must hold or have held a Senior Operator License at Cook Nuclear Plant or a similar reactor, or have been certified for equivalent senior operator knowledge. If the Operations Superintendent does not hold a Senior Operator License, then a line (v. staff) operations middle manager shall hold a Senior Operator License for the purposes of directing operational activities.

---

\* The unexpected absence, for a period of time not to exceed 2 hours, of the on-site individual qualified in radiation protection procedures is permitted provided immediate action is taken to fill the required position.