

Department of Energy

Washington, DC 20585

QA: QA

APR 25 2002

J. S. Martin Bechtel SAIC Company, LLC 1180 Town Center Drive, M/S 280 Las Vegas, NV 89144

VERIFICATION OF CORRECTIVE ACTIONS AND CLOSURE OF DEFICIENCY REPORT (DR) BSC-02-D-087

The Office of Quality Assurance staff has evaluated the corrective actions of DR BSC-02-D-087 and determined the results to be satisfactory. As a result, the DR is considered closed.

Ram Murthy, Acting Director Office of Quality Assurance

If you have any questions, please contact either James Blaylock at (702) 794-1420 or William J. Glasser at (702) 794-5014.

OQA:JB-1084

Enclosure:

DR BSC-02-D-087

nmsson

cc w/encl:-

N. K. Stablein, NRC, Rockville, MD

Robert Latta, NRC, Las Vegas, NV

S. W. Lynch, State of Nevada, Carson City, NV

Engelbrecht von Tiesenhausen, Clark County, Las Vegas, NV

H. R. Cox, BSC, Mercury, NV, M/S 755

S. H. Horton, BSC, Las Vegas, NV

C. A. Humphries-Alder, BSC, Las Vegas, NV, M/S 280

R. P. Keele, BSC, Las Vegas, NV, M/S 280

D. T. Krisha, BSC, Las Vegas, NV

D. M. Kunihiro, BSC, Las Vegas, NV

Richard Powe, BSC, Las Vegas, NV, M/S 280

T. J. Wall, BSC, Las Vegas, NV

R. L. Weeks, BSC, Las Vegas, NV, M/S 280

W. J. Glasser, NQS, Las Vegas, NV

D. G. Opielowski, NQS, Las Vegas, NV

J. R. Dyer, DOE/YMSCO, Las Vegas, NV

C. E. Hampton, DOE/YMSCO, Las Vegas, NV

D. G. Horton, DOE/YMSCO, Las Vegas, NV

J. M. Replogle, DOE/YMSCO, Las Vegas, NV

B. M. Terrell, DOE/YMSCO, Las Vegas, NV

ORIGINAL MIS IS A BED STAM

OFFICE OF CIVILIAN RADIOACTIVE WASTE MANAGEMENT U.S. DEPARTMENT OF ENERGY WASHINGTON, D.C.

TO BUILDING
B. ✓ DEFICIENCY REPORT
CORRECTIVE ACTION REPORT
NO. BSC-02-D-087
PAGE 1 OF

	CHILLIAN OF ENTEROL	1.		
WAS	HINGTON, D.C.		PAGE 1 OF	QA: X QA
DEFICIENCY/COR	RECTIVE ACTION RE	PORT	D60	3/12/02
1. Controlling Document:		2. Related Re	eport No.:	
YAP-15.1Q, Rev 1, ICN 1		N/A		
3. Responsible Organization:	4. Discussed With:			
Yucca Mountain Project Office	Howard Cox, Richard Weeks			
 Requirement: QA RECORDS The documents listed in Subsections 7.1 and 7.2 shall be c "Records Management Requirements and Responsibilities" 	ollected and maintained as QA or applicable implementing p	Records in a rocedures.	eccordance with	YAP-17.1Q,
7.1 LIFETIME RECORDS Each Q and non-Q NCR, and continuation pages.				
7.2 NONPERMANENT RECORDS None.				
6. Description of Condition: Contrary to the above requirement, there is no objective ev	vidence of the following NCRs	being submitt	ted to the recor	ds system:
REECO-95-0029 - written by J. Constable on 6/12/95				
YMSCO-95-0128 - written by D. Holliday on 5/25/95.				•
7. Initiator: Cynthia Humphyles-Alder Miles Markhair Challe Date 3/11/02	9. Does a stop work co ☐ Yes ☑ No If Yes, Check One:	ndition exist?	(Not required for	or a DR)
19. Recommended Actions:				
NONE				
			·	
11. QA Review: QAR WILLIAM J. GLASSON Date 4-1-02 13. DOQA Issuance Approval:	12. Response Due Da 10 working da	te: ys from i	ssuance	
·	Signature James Bl	aylock +	n Date 4	/4/02
22. Corrective Actions, Verified		by:		'.
QAR William 5. Blasson Date 4/24/0	23. Closure Approved DOQA James B	Loughort	to Date 4/	125/02
while AP-16 10 1		()		Rev. 12/20/1999

				•
Submittal Page 1 of 2 2. Check if Amended ☐ Check if also Initial Response ✓ 3. Extended Processing	RADIOACTIVE WA U.S. DEPARTM	OF CIVILIAN ASTE MANAGEMENT ENT OF ENERGY	1. DR/CAR NO. PAGE	BSC-02-D-087 OF QA: QA
No Yes (If yes, submit Extended Processing request)	WASHIN	GTON, D.C.		
	PORTICORRECTIVE A	CTION DEPORT COM	DI ETT	
4. Extent of Condition: (Amended	response will be required if all l	CTION REPORT COM	PLE IE RESP	PONSE
[c c)				
The YMP has had two NCR tracki LotusNotes database). As part of to to verify that the YMP Records Pr verification was that two of the tot NCRs are addressed as follows: (c	ne Licensing Support Network occassing Center contained copial of 1,137 NCRs were missing	effort a record verification acti	vity was conducte	d. The activity was
5. Impact: (Provide an impact state	ement relative to waste isolation	and safety, and impact to oth	er work if any)	
Based on the facts that NCR YMS removal of the rejected drain from missing hardcopies of these NCRs.	the ESF site it is determined the	v the initiator and the initiator of	SENICD DEECO O	5-0029 verified the solation due to the
6. Remedial Actions: (Document al	I actions necessary to address	the results of the Extent of Cou	ndition)	
The record copy of the 'Ymas2' No this DR.	,		modica with a no	,
7. Root Cause (For a significar	nt CAQ, attach results of forma	root cause determination prep	ared in accordance	ce with AP-16 4Q)
✓ Apparent Cause			and an accordance	70 Will 70 10.4Q)
The NCR tracking process, in its earecords may be lost or destroyed.	arly years, did not provide a rec	lundant system to capture copie	es of NCR hardco	pies for cases wher
8. Action to Preclude Recurrence: (Address those actions necessi	ary to prevent the identified cau	ise from recurring)
The evolution of the NCR tracking in use, although it is a Non-Q datab scanned into this database at variou destroyed.	database has provided the remarkable ase, provides for a secondary.	edy to preclude recurrence of the redundant source for obtain	his condition. The	database currently
9. Due Date for Completion of Corre	active Action:	Ido December 161		
04/24/02	SCHVE ACHORI.	1	A Marture	4/19/02 Date
NOTA SIGNIFICANT CONDITION	Partially Accept Reject	12. QAM Concurrence:		
Printed Name Signatur			Blombol fr	4/23/02 Date
P-16.1Q.8				

Rev. 03/25/2002

Submittal	Page	2	of	2

OFFICE OF CIVILIAN RADIOACTIVE WASTE MANAGEMENT U.S. DEPARTMENT OF ENERGY WASHINGTON, D.C.

▼	DR/CAR/QO
	swo

NO. BSC-02-D-087 PAGE OF

QA: QA

CONDITION ADVERSE TO QUALITY CONTINUATION PAGE

Block 4 Extent of Condition (Continued):

Item 1) NCR YMSCO-95-128: The following statement is from the individual that was the Kiewit/Parsons Brinkerhoff (K/PB) Quality Control Manager at the time of the alleged nonconformance and was directly involved in the resolution.

"On the date of issuance of NCR YMSCO-95-0128 a DOE Office of Quality Assurance (OQA) Representative (the author of the NCR) visited the ESF site. During the visit he observed K/PB personnel conducting Tracer Water testing. Based on this observation, the OQA Representative applied a Hold Tag on the Tracer Water system and initiated the subject NCR in the belief that K/PB personnel conducting the testing were not properly authorized for the activity.

Upon presenting the NCR to the K/PB QC Manager (the undersigned) a discussion was held wherein the OQA Representative was shown that K/PB had an approved Quality Assurance Program and that the personnel conducting the tests had been properly trained and qualified to the applicable procedure. The OQA Representative then removed the Hold Tag and invalidated the NCR."

Howard Cox Date

According to the 'Ymas2' Non conformance Report Log, this NCR was reviewed for final closure on 10/01/95. It is unknown what happened to the original NCR hardcopy after final closure.

Item 2) NCR REECO-95-0029: The following information was obtained from the 'Ymas2' Non conformance Report Log::

- The NCR was apparently issued for a Non-Q item. There are no 'Q' drains at the ESF.
- The disposition was Reject/Scrap with the requirement to "return and reorder"
- The NCR was issued, dispositioned, concurred with by the initiator, the disposition verified by the initiator, and subsequently closed on the same date (06/12/95).

It is unknown what happened to the original NCR hardcopy after final closure.

JDMIπai Page/_ or _/_	
	OFFICE OF CIVILIAN
-	RADIOACTIVE WASTE MANAGEMEN

NT U.S. DEPARTMENT OF ENERGY WASHINGTON, D.C.

DR/CAR/QO
swo

NO. BSC-02-D-087 PAGE OF

QA: QA

CONDITION ADVERSE TO QUALITY CONTINUATION PAGE

Block 22 Verification of Corrective Action

The majority of statements on the response to this DR/CAR are generally an explanation of investigation results or explanation of the conditions described by the missing NCRs. In order to provide a link reference to this DR/CAR, only one action is necessary to close this deficiency as described in the remedial actions of the complete response.

Remedial action: The record copy of the "Ymas2" Non-conformance Report Log, MOL 19991202.0314, will be annotated with a note that will refer to this DR.

Verified that a supplemental record to the referenced MOL number has been prepared and submitted on 4/24/02. This submittal provides supplemental pages that link the original submittal to this DR/CAR.

Based on the above, this DR/CAR is considered closed.

Meany Slasser 4/24/02 liam J. Glasser QAR

AP-16.1Q.2

Rev. 03/25/2002