Robert G. Byram Senior Vice President and Chief Nuclear Officer PPL Susquehanna, LLC
Two North Ninth Street
Allentown, PA 18101-1179
Tel. 610.774.7502 Fax 610.774.6092
rgbyram@pplweb.com



U.S. Nuclear Regulatory Commission Attn: Document Control Desk Mail Station OP1-17 Washington, DC 20555

SUSQUEHANNA STEAM ELECTRIC STATION CLARIFICATION TO RELIEF REQUEST NO. RR-25 REQUEST FOR AUTHORIZATION TO USE CODE CASE N-516-2 FOR SUSQUEHANNA SES UNITS 1&2 PLA-5450

Docket No. 50-387 and 50-388

References:

- 1) PLA-5416, R. G. Byram (PPL) to USNRC Document Control Desk, "Proposed Relief Request No. RR-25 Request for Authorization to use Code Case N-516-2 for Susquehanna SES Units 1&2", dated January 2, 2002.
- 2) Letter, NRC to R. G. Byram (PPL), "Susquehanna Steam Electric Station, Units 1 and 2 Relief Request for Authorization to use Code Case N-516-2 as an Alternative to the ASME Code, Section XI, Requirements (TAC Nos. MB3722 and MB3723)", dated February 21, 2002.

The purpose of this letter is to provide clarification of the ISI Code of record for Susquehanna Steam Electric Station (SSES).

In a letter dated January 2, 2002, PPL requested authorization to use Code Case N-516-2 at the Susquehanna SES Units [Reference 1]. Within the letter, PPL identified that the 1992 Edition of ASME Section XI, IWA-4000, with the 1992 Addenda provides the requirements for performing repairs and replacements. The NRC approved use of Code Case N-516-2 at SSES in a Safety Evaluation Report (SER) dated February 21, 2002 [Reference 2]. Sections 1.0 and 2.1 of the SER state that the 1992 Edition of the ASME Code with the 1992 Addenda is the ISI Code of record for Susquehanna Steam Electric Station, Units 1 and 2.

PPL's request did not intend to imply that the Code of record for <u>all</u> Code components is the 1992 Edition with the 1992 Addenda as is stated in the SER. For Class 1, 2 and 3 components, the 1989 Edition of the ASME Code is the Code of record. For Class MC and CC components, the 1992 Edition with the 1992 Addenda is the Code of record.

This clarification was discussed with our NRC Project Manager on February 5, 2002. If you have any questions, please contact Mr. Duane L. Filchner at (610) 774-7819.

Sincerely,

cc:

NRC Region I

Mr. S. L. Hansell, NRC Sr. Resident Inspector Mr. T. G. Colburn, NRC Sr. Project Manager

bcc:	R. L. Anderson	NUCSB3
	M. H. Crowthers	GENA61
	R. E. Day	NUCSA1
	D. L. Filchner	GENA61
	E. B. Gerlach	NUCSB3
	T. L. Harpster	GENA61
	C. D. Markley	NUCSA4
	J. M. Oddo	GENA61
	J. E. O'Sullivan	NUCSB3
	R. D. Pagodin	GENA63
	B. L. Shriver	NUCSB3
	M. W. Simpson	GENA12
	B. M. Swoyer	GENA62
	H. L. Webb	GENA62
	A. J. Wrape	GENA62
	ANII	NUCSB3
	NRA Files	GENA61
	Nuclear Records	GENA62
	Attn: P. Brown	