

May 28, 2002

Mr. J. A. Price  
Vice President - Nuclear Technical Services - Millstone  
Dominion Nuclear Connecticut, Inc.  
c/o Mr. David A. Smith  
Rope Ferry Road  
Waterford, CT 06385

SUBJECT: BULLETIN 2002-01, "REACTOR PRESSURE VESSEL HEAD DEGRADATION AND REACTOR COOLANT PRESSURE BOUNDARY INTEGRITY," 15-DAY RESPONSE FOR MILLSTONE NUCLEAR POWER STATION, UNIT NO. 2 (TAC NO. MB4555)

Dear Mr. Price:

On March 18, 2002, the staff issued Bulletin 2002-01, "Reactor Pressure Vessel Head Degradation and Reactor Coolant Pressure Boundary Integrity," to the industry requesting that addressees provide information related to the structural integrity of the reactor coolant pressure boundary, including the reactor pressure vessel head, and the extent to which inspections have been undertaken to satisfy applicable regulatory requirements. Bulletin 2002-01 also required licensees to provide the basis for concluding that plans for future inspections of the reactor coolant pressure boundary will satisfy applicable regulatory requirements at their respective pressurized water reactor (PWR) plants. All addressees were requested to respond to Items 1.A. through E. within 15 days of the Bulletin's issuance, or to provide a written response to the NRC in accordance with the provisions of Title 10, Section 50.54(f), of the *Code of Federal Regulations* (10 CFR 50.54(f)) if they are unable to provide the information, or they cannot meet the requested completion dates.

You provided your 15-day Bulletin response by letter dated April 2, 2002. The staff finds that you have provided the requested information, and has concluded that your plant does not appear to have conditions similar to those which lead to the degradation at Davis-Besse. However, the staff may issue questions to confirm or verify the information that was provided in your 15-day response to Bulletin 2002-01.

J. Price

- 2 -

Your letter dated April 2, 2002, also provided the response to Item 2 of the Bulletin (30-day after plant restart response). In addition, your letter dated May 16, 2002, provided the response to Item 3 of the Bulletin (60-day response). We will complete a full review of your response to Bulletin 2002-01 after we review your responses to Items 2 and 3 of the Bulletin. If you have any questions, please contact me at (301) 415-1420.

Sincerely,

*/RA/*

Richard B. Ennis, Senior Project Manager, Section 2  
Project Directorate I  
Division of Licensing Project Management  
Office of Nuclear Reactor Regulation

Docket No. 50-336

cc: See next page

J. Price

- 2 -

Your letter dated April 2, 2002, also provided the response to Item 2 of the Bulletin (30-day after plant restart response). In addition, your letter dated May 16, 2002, provided the response to Item 3 of the Bulletin (60-day response). We will complete a full review of your response to Bulletin 2002-01 after we review your responses to Items 2 and 3 of the Bulletin. If you have any questions, please contact me at (301) 415-1420.

Sincerely,

*/RA/*

Richard B. Ennis, Senior Project Manager, Section 2  
Project Directorate I  
Division of Licensing Project Management  
Office of Nuclear Reactor Regulation

Docket No. 50-336

cc: See next page

DISTRIBUTION:

PUBLIC	SRichards	WBateman	OGC
PDI-2 Reading	JClifford	SCoffin	ACRS
EMCB Reading	REnnis	ALee	
SBloom	TClark	CCowgill, RGN-I	

ACCESSION NUMBER: ML021410178

OFFICE	PDI-2/PM	PDI-2/LA	EMCB/LPM	PDI-2/SC
NAME	REnnis	TClark	SBloom	JClifford
DATE	5/22/02	5/22/02	5/22/02	5/28/02

OFFICIAL RECORD COPY

Millstone Nuclear Power Station  
Unit 2

cc:

Ms. L. M. Cuoco  
Senior Nuclear Counsel  
Dominion Nuclear Connecticut, Inc.  
Rope Ferry Road  
Waterford, CT 06385

Edward L. Wilds, Jr., Ph.D.  
Director, Division of Radiation  
Department of Environmental Protection  
79 Elm Street  
Hartford, CT 06106-5127

Regional Administrator, Region I  
U.S. Nuclear Regulatory Commission  
475 Allendale Road  
King of Prussia, PA 19406

First Selectmen  
Town of Waterford  
15 Rope Ferry Road  
Waterford, CT 06385

Charles Brinkman, Manager  
Washington Nuclear Operations  
ABB Combustion Engineering  
12300 Twinbrook Pkwy, Suite 330  
Rockville, MD 20852

Senior Resident Inspector  
Millstone Nuclear Power Station  
c/o U.S. Nuclear Regulatory Commission  
P.O. Box 513  
Niantic, CT 06357

Mr. W. R. Matthews  
Vice President and Senior Nuclear  
Executive - Millstone  
Dominion Nuclear Connecticut, Inc.  
Rope Ferry Road  
Waterford, CT 06385

Ernest C. Hadley, Esquire  
P.O. Box 1104  
West Falmouth, MA 02574-1104

Mr. P. J. Parulis  
Manager - Nuclear Oversight  
Dominion Nuclear Connecticut, Inc.  
Rope Ferry Road  
Waterford, CT 06385

Mr. D. A. Christian  
Senior Vice President - Nuclear Operations  
and Chief Nuclear Officer  
Innsbrook Technical Center - 2SW  
5000 Dominion Boulevard  
Glen Allen, VA 23060

Mr. C. J. Schwarz  
Director - Nuclear Station Operations  
and Maintenance  
Dominion Nuclear Connecticut, Inc.  
Rope Ferry Road  
Waterford, CT 06385

Mr. John Markowicz  
Co-Chair  
Nuclear Energy Advisory Council  
9 Susan Terrace  
Waterford, CT 06385

Mr. Evan W. Woollacott  
Co-Chair  
Nuclear Energy Advisory Council  
128 Terry's Plain Road  
Simsbury, CT 06070

Mr. D. A. Smith  
Manager - Licensing  
Dominion Nuclear Connecticut, Inc.  
Rope Ferry Road  
Waterford, CT 06385

Ms. Nancy Burton  
147 Cross Highway  
Redding Ridge, CT 00870

Millstone Nuclear Power Station  
Unit 2

cc:

Mr. G. D. Hicks  
Director - Nuclear Station Safety and Licensing  
Dominion Nuclear Connecticut, Inc.  
Rope Ferry Road  
Waterford, CT 06385

Mr. J. A. Price  
Site Vice President - Millstone  
c/o Mr. David A. Smith  
Dominion Nuclear Connecticut, Inc.  
Rope Ferry Road  
Waterford, CT 06385

Mr. S. E. Scace  
Director - Nuclear Engineering  
Dominion Nuclear Connecticut, Inc.  
Rope Ferry Road  
Waterford, CT 06385

Mr. M. J. Wilson  
Manager - Nuclear Training  
Dominion Nuclear Connecticut, Inc.  
Rope Ferry Road  
Waterford, CT 06385