Undated

VNDATED

٤

PROPOSED AGE A FOR CONFERENCE ON NUCLEAR PLAN, SITE PROBLEMS WITH TENTATIVE SPEAKERS AS OF

MARCH 3, 1959

Saturday	-	May 2:				
12:30 P.H.				Tour MTR-ETR and EBE-I and BORAL		
Sunday		May 3	<b>,</b> 1		· ·	
11:00 <b>L.N.</b>				Tour Construction Sites, KBR-II, SPERT-II Fluor Area and FET		
Monday	-	May 4	ł			
8:30	to	9:00	A.H.	Introduction Welcome Announcemen Allan C. Johnson Dr.F. Weber J. R. Horan		
9:00	to	12:30	A.N.	Reactor Concepts	E. W. Davidson, Chairman	
9:30 10:00 10:15 10:45 11:15	to to to to to		A.M. A.M. A.M. A.M. A.M.	Break Boiling Water	Glenn Boyer Jay Powell Bill Allred Ken Cempbell Heyer Novick	
1:30	to	3:00	P.N.	Panel on Basis for	Discharge E. C. Anderson, Chairman G. L. Yoels, M.D. Clint Powell Duncan Holaday NGRP Representative	
	to	4:15	P.M.	Break Discharge Criteria	Nelson Panel	
					Iltis Tsivoglou Staps Representative AEC Representative	

<u>Tuesday - May 5</u> :	Discharge Evaluation (Source	) J. J. Sabo, Chairman
8:30 to 8:50 A.M. 8:55 to 9:15 A.M. 9:20 to 9:40 A M		Bill Boone Bill King John Donnelly
9:45 to 10:00 A.M.	Shippingport Liquid Waste	Harward
10:00 to 10:20 A.N. 10:15 to 10:30 A.M.	MTR Fission Break Monitor	John Sommers
10:30 to 12:00 A.M.	Analytical Methods	
· ·	10:30 to 11:00 Sill   11:00 to 11:30 Strand   11:30 to 12:00 General Di	scussion
1:30 to 4:45 P.M.	Environmental Monitoring Nor	mal Operation R. D. Coleman; Chairman
1:30 to 1:50 P.M.	Site Survey Activities - NRTS Griffiths	
2:00 to 2:20 P.M.	Ecology Activities - NRTS	French
	Telemetering - NRTS	Wilhelmson `
3:00 to 3:15 P.M.		
3:15 to 4:05 P.M.		
4:15 to 4:35 P.M.		
4:45 to 5:30 P.M.	Organisation of Work Groups	

Wednesday - May 6: All Day Work Groups

	TOPIC	CONDUCTED BY	PLACE
1. 2. 3. 4. 5. 7. 8.	Reactor Hasard Reports Shipping PHS Techniques Biological Monitoring General Area Monitoring R/A Wastes Analysis Instrumentation	Nelson Batie-Patterson Sabo French Griffiths Schmals Sill Welhelmson	CF 615 CF-626 CF-626 CF-646 CF-613 CF-613 CF-646 CF-646
9.	Stack and Fission Break Monitors	Sommers	MTR

· ·	- 3 -	
Thursday - May 7:	Pre-Operational Surveys	J. J. Sabo, Chairman
8:30 to 8:50 A.M.	Position	Bill Herris
8:50 to 9:10 A.M.	Position and Arial Surveys	G. V. Beard
	Shippinpert Survey	Dave Harvard
9:30 to 9:50 A.N.	Maritime Commission Harbor	
,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	Survey	Ralph Longaker
9:50 to 10:20 A.M.		
10:10 to 10:30 A.M.		Abe Goldin
10:30 to 10:45 A.M.		
10.15 to 12.00 A.M.	Fanel - Abova Members +	Br. French
TOTAL DO TRION REAL		6. BII
4-20 4- 0-20 D M	Burdmannatal Bulate and	
1130 to 2130 F.M.	Environmental Safety and Emergency Plans	Dade Noeller, Chairman
	n an	
1:30 to 2:00 P.M.	General Environmental	
·	Safety	Jee Fitzgerald
2:00 to 2:30 P.M.	Disaster and Emergency Plans	John Horan
	n de la companya de l Nomena de la companya	
2:30 to 5:30 P.M.	Waste Disposal	
2130 to 2150 P.M.	MATS Activities of Phillips	I. V. McCaslin
2150 to 3110 P.M.	High Level Maste Glacination	
3:10 to 3:30 P.M.		
	Soll Criteria for Burial	Their
3150 to 410 7.34	Public Health Services	
SPT and and a	Philosophy	
4110 to 4:30 T.H.	ARS Developments in Washe	
	Bandling	
4130 to 3130 K.M.	Waste Disposal Fazel	
· · · · · · · · · · · · · · · · · · ·		
	· · · ·	
	4.	
Friday - May 8:	Accident Problem and Emergency	TEG. Tertill,
And the Western Concerns of the State of the	Assistance	C. Iral
8:30 to 8:50 A.N.	Current Shipment Regulations	
	Procedures	- Ed Pattérson
9:00 to 9:20 A.M.	Energy Manilering Teens	1 lond for the
9:30 to 9:50 A.H.		A AMAT NA
10:00 to 10:15 A.M.	Break	
10:15 to 11:45 A.N.	Local Regulations, Inspection	
	AND I CAREELINE AND ANDII DE LLO	
10:15 to 10:35 A.M.	Operation of IDC Intepegtion	
10:35 to 31:05 1.M.		
41:15 to 11:35 A.M.	Lotivisies of States Last and	
• • • • • • • • • • • • • • • • • • •	Division of Lisensing and ap	
•		
·	Work Group Reports a na 10100	T. C. MARTIN PT
		A Length Gin 1 rann
		- Alter - Al

. .....

1997 1997

\_\_\_\_\_

-----

• •