

Region I NMSS Licensee Event Report

Licensee **AGILENT TECHNOLOGIES**
 Event Description **Notice of Gen License Device w/High Removable Activity**

License # **07-28762-02G** Docket # **03002988** MLER-RI **2002-024**
 Event Date **5/3/2002** Report Date **5/3/2002**

1. REPORTING REQUIREMENT

- | | | | |
|-------------------------------------|------------------------------|--------------------------|--------------------------------|
| <input type="checkbox"/> | 10 CFR 20.2201 Theft or Loss | <input type="checkbox"/> | 10 CFR 35.33 Misadministration |
| <input type="checkbox"/> | 10 CFR 20.2203 30 Day Report | <input type="checkbox"/> | License Condition |
| <input type="checkbox"/> | 10 CFR 30.50 Report | | |
| <input checked="" type="checkbox"/> | Other 10 CFR 31.5 | | |

2. REGION I RESPONSE

- | | | | |
|--------------------------|-------------------------------|-------------------------------------|---------------------------|
| <input type="checkbox"/> | Immediate Site Inspection | Inspector/Date | |
| <input type="checkbox"/> | Special Inspection | Inspector/Date | |
| <input type="checkbox"/> | Telephone Inquiry | Inspector/Date | |
| <input type="checkbox"/> | Preliminary Report | <input type="checkbox"/> | Daily Report |
| <input type="checkbox"/> | Information Entered in RI Log | <input checked="" type="checkbox"/> | Review at next inspection |
| <input type="checkbox"/> | Report referred to: | | |

3. REPORT EVALUATION

- | | | | |
|-------------------------------------|------------------------|-------------------------------------|--|
| <input checked="" type="checkbox"/> | Description of Event | <input checked="" type="checkbox"/> | Corrective Actions |
| <input checked="" type="checkbox"/> | Levels of RAM Involved | <input type="checkbox"/> | Calculations Adequate |
| <input type="checkbox"/> | Cause of Event | <input type="checkbox"/> | Additional Information Requested from Licensee |

4. SPECIAL INSTRUCTIONS OR COMMENTS

Public **BU 5/7/02** Non-Public

Initials/Date	Initials/Date
Completed by: R. Ulling 5/7/02	
Reviewed by: [Signature] 5/21/2002	

 **Agilent Technologies**
2850 Centerville Road
Wilmington, DE 19808

RECEIVED
REGION I

2002 MAY -3 PM 1:57

Division of Nuclear Materials Safety
U.S. Nuclear Regulatory Commission
Region I
475 Allendale Road,
King of Prussia, PA 19406

Re: Notice of General License device with high removable activity (NRC License 07-28762-02G)

May 2, 2002


Dear Sir or Madam,

Per the requirements of 10 CFR 31.5, I am notifying your office of a general license device returned to our site from which we have obtained a removable activity wipe in excess of 0.005 μCi . The cell was evaluated by support engineering and its disposition is identified below. I will notify the cell supplier of the high wipe.

<u>Serial #</u>	<u>Model #</u>	<u>Activity (μCi)</u>	<u>Disposition</u>
F6523	19233	0.020	Scrap

Please contact me at 302-633-8262 if there are any questions.

Thank you,



David S. Bennett
Radiation Safety Officer