

May 28, 2002

MEMORANDUM TO: Davis-Besse Nuclear Power Station IMC 0350 Panel

FROM: John A. Grobe, Director, DRS */RA/*

SUBJECT: MINUTES OF INTERNAL MEETING OF THE DAVIS-BESSE
NUCLEAR POWER STATION IMC 0350 PANEL

The implementation of the IMC 0350 process for the Davis-Besse Nuclear Power Station was announced on April 29, 2002. An internal panel meeting was held May 9. Attached for your information are the minutes from the internal meeting of the IMC 0350 panel.

Attachment: As stated

cc w/att: H. Nieh, OEDO
W. Dean, NRR
A. Mendiola, NRR
D. Pickett, NRR
S. Bloom, NRR
G. Grant, RIII
S. Reynolds, RIII
C. Lipa, RIII
L. Collins, RIII
D. Simpkins, RIII
J. Jacobson, RIII
S. Burgess, RIII
S. Thomas, RIII

MEMORANDUM TO: Davis-Besse Nuclear Power Station IMC 0350 Panel

FROM: John A. Grobe, Director, DRS

SUBJECT: MINUTES OF INTERNAL MEETING OF THE DAVIS-BESSE
NUCLEAR POWER STATION IMC 0350 PANEL

The implementation of the IMC 0350 process for the Davis-Besse Nuclear Power Station was announced on April 29, 2002. An internal panel meeting was held May 9. Attached for your information are the minutes from the internal meeting of the IMC 0350 panel.

Attachment: As stated

cc w/att: H. Nieh, OEDO
W. Dean, NRR
A. Mendiola, NRR
D. Pickett, NRR
S. Bloom, NRR
G. Grant, RIII
S. Reynolds, RIII
C. Lipa, RIII
L. Collins, RIII
D. Simpkins, RIII
J. Jacobson, RIII
S. Burgess, RIII
S. Thomas, RIII

DOCUMENT NAME: G:\Davis-Besse 0350\internalmtgminutes0509.wpd

To receive a copy of this document, indicate in the box: "C" = Copy without enclosure "E"= Copy with enclosure "N"= No copy

OFFICE	RIII		RIII		RIII		
NAME	LCollins:ntp		Clipa		JGrobe		
DATE	05/28/02		05/28/02		05/28/02		

OFFICIAL RECORD COPY

MEETING MINUTES: Internal IMC 0350 Restart Panel Meeting
Davis-Besse Nuclear Power Station

DATE: May 9, 2002

TIME: 3:00 pm (Central)

ATTENDEES:

S. Bloom
S. Burgess
T. Chan
D. Coe
S. Coffin
L. Collins
W. Dean
J. Grobe
J. Jacobson
M. Johnson
C. Lipa
A. Mendiola
D. Pickett
D. Simpkins

Agenda Items:

At the beginning of the meeting Jim Dyer addressed the panel members to lay out expectations and to discuss the challenges facing the panel during the IMC 0350 process.

1. Reports from Staff

Repair/Replacement Plans (DE)

DE staff and the panel discussed the panel's role in the technical review of any repair or replacement submitted to the NRC. The panel will have no technical involvement in the review but needs to maintain awareness of the process and in particular, any dissenting views regarding the processing of the licensing decision. The panel needs to be briefed prior to issuing any licensing action.

Risk Analysis (DSSA/SRA)

S. Long and S. Burgess discussed the SDP phase 3 evaluation that is currently underway. The TIA sent in from Region III was accepted. RES is performing technical evaluations to determine the pressure at which the as found cavity would fail and also how large the cavity would need to be to fail at normal operating pressure. RES is also looking at how fast the cavity might have been expanding with time. The results of these evaluations will be used in the SDP phase 3 assessment.

The licensee's response to the RAI was extended to June 7. This was communicated to the NRC on the weekly calls between the licensee and NRR.

Allegations/Investigations (EICS, OI)

This item was not discussed.

Licensing Issues/Actions (DLPM)

The petition review board met today to discuss a 2.206 petition that was received.

Two green ticket items were discussed.

A revision to the Confirmatory Action Letter was discussed.

2. IMC 0350 Panel Business

Inspection Schedule

This item was not discussed.

Process Plan/Restart Checklist Updates

This item was not discussed. The panel agreed to review the process plan line by line at the next panel meeting.

3. Utilization of the Web Page

This item was not discussed.

4. Future Activities/Plans/Meetings

This item was not discussed.

5. Discuss how to handle public or staff comments, questions, allegations, and concerns received by phone, fax, letter, email, or at public meetings.

This item was not discussed.