

SAFEGUARDS INFORMATION

Entergy Nuclear South Entergy Operations, Inc. 17265 River Road Killona, LA 70066 Tel 504 739 6660 Fax 504 739 6678 jvenabl@entergy.com

Joseph E. Venable Vice President, Operations Waterford 3

W3F1-2002-0058 A4.05 PR

June 13, 2002

Via Overnight Delivery

U.S. Nuclear Regulatory Commission ATTN: Document Control Desk One White Flint North 11555 Rockville Pike Rockville, MD 20852-2738

- Subject: Waterford 3 SES Docket No. 50-382 License No. NPF-38 Entergy Operations, Inc. – Response to Issuance of Order for Interim Safeguards and Security Compensatory Measures
- REFERENCES: Letter to Gary. J. Taylor from Samuel J. Collins dated February 25, 2002 Issuance of Order for Interim Safeguards and Security Compensatory Measures (CNRI-2002-00002 / ILN 02-0031)

Letter to Document Control Desk from Entergy Operations, Inc. dated March 15, 2002 Response to Issuance of Order for Interim Safeguards and Security Compensatory Measures (W3F1-2002-0024)

Gentlemen:

On March 15, 2002, Entergy submitted its response to the Interim Safeguards and Security Compensatory Measures Order ("Order") issued by the United States Nuclear Regulatory Commission ("NRC") on February 25, 2002. We indicated in our response that additional time was necessary to complete analyses with respect to

NOTICE: Attachment 1 contains "Safeguards Information." Upon separation of Attachment 1 from this letter, this letter becomes "DECONTROLLED"

SAFEGUARDS INFORMATION

X IE53

W3F1-2002-0058 Page 2 June 13, 2002

1

certain Interim Compensatory Measures (i.e., Interim Compensatory Measures B.2.a.(1), B.2.a.(2) and B.2.b) before we could submit a schedule for achieving compliance with those requirements, in accordance with Section III.C.1 of the Order. In accordance with 10CFR50.4, Entergy hereby submits its supplemental response to the Order. The enclosure to this response contains safeguards information, as defined in 10CFR73.21. Entergy therefore requests that the enclosure be withheld from public disclosure.

Pursuant to Section IV of the Order, on March 15, 2002, Entergy requested an extension of time to file an Answer and request for hearing with respect to those Interim Compensatory Measures listed above. Pursuant to the requirements of 10CFR2.202(a)(2), the Supplemental Answer to the Order is being transmitted to the NRC under separate cover.

If you have any guestions or require additional information, please contact me.

This letter includes new commitments as summarized in Attachment 2.

I declare under penalty of perjury that the foregoing is true and correct. Executed on June 13, 2002.

Very truly yours,

Joseph & Venah

Joseph E. Venable Vice President, Operations Waterford Steam Electric Station, Unit 3

JEV/LAE/baa Attachment 1: Supplemental Response to Issuance of Order for Interim Safeguards and Security Compensatory Measures Attachment 2: List of Regulatory Commitments

> NOTICE: Attachment 1 contains "Safeguards Information." Upon separation of Attachment 1 from this letter, this letter becomes "DECONTROLLED"

> > SAFEGUARDS INFORMATION

W3F1-2002-0058 Page 3 June 13, 2002

۰.

cc: U. S. Nuclear Regulatory Commission ATTN: Samuel J. Collins, Director Office of Nuclear Reactor Regulation Mail Stop O-5E7 One White Flint North 11555 Rockville Pike Rockville, MD20852-2738 (w/o Attachments)

> U.S. Nuclear Regulatory Commission ATTN: Robert E. Martin Mail Stop O-8-G9 One White Flint North 11555 Rockville Pike Rockville, MD 20852-2738 (w/Attachments via overnight delivery)

Secretary, Office of the Secretary U. S. Nuclear Regulatory Commission ATTN: Rulemakings and Adjudications Staff Washington, DC 20555-0001 (w/o Attachments)

Assistant General Council for Materials Litigation and Enforcement U. S. Nuclear Regulatory Commission Washington, DC 20555-0001 (w/o Attachments)

E. W. Merschoff, NRC Region IV (w/Attachments via overnight delivery)
N. Kalyanam, NRC-NRR (w/o Attachments)
J. Smith (w/o Attachments)
N.S. Reynolds (w/o Attachments)
NRC Resident Inspectors Office (w/Attachments)

NOTICE: Attachment 1 contains "Safeguards Information." Upon separation of Attachment 1 from this letter, this letter becomes "DECONTROLLED"

SAFEGUARDS INFORMATION