

Aloha Mr. Bhachu,

The attached letter (with Tesoro's letterhead) was put in the (snail) mail today to your attention. Please let me know if it meets the NRC requirements for terminating the license.

<<NRC Terminate Krypton License 03-27-02.doc>>

Thank You,

Ross M. Rolirad
Supervisor, I&E Engineering
Tesoro Hawaii Refinery
808-479-0535
RRolirad@tesoropetroleum.com

March 27, 2002

Nuclear Regulatory Commission
11545 Rockville Pike
Rockville, MD 20852
Attn: Mail Stop 8F5 (Mr. U. S. Bhachu)

Subject: Request to terminate License # NR0321D105S

Dear Mr. Bhachu,

In accordance with Section 13.4 of NUREG 1556, Vol. 3, we are requesting that the referenced license be terminated. Following are our replies to the four points of information required by Section 13.4 of NUREG 1556, Volume 3:

- Both custom Krypton-85 sources have been decommissioned and transferred to Qual-X, Inc. at 3029 Home Road, Powell, OH 43065 for recycling. The transfer was made on February 23, 2001. Qual-X Inc. license number is: 031214210003. Their contact is Mr. Greg Mahon @ 740-881-5543. Tesoro Hawaii Refinery (formerly BHP Petroleum Americas) has no additional Krypton-85 devices in use or, in our possession.
- Not Applicable. Sources were custom devices for use within the refinery only.
- Not Applicable. Sources were custom devices for use within the refinery only.
- Tesoro Hawaii Corporation hereby verifies that no changes were made to the products since their initial registration, or last amendment.

Respectfully,

Ross M. Rolirad
Supervisor, I&E Engineering
Tesoro Hawaii Corporation
91-325 Komohana Street
Kapolei, HI 96707

Ph.: 808-479-0535; Fax: 707-516-2486

Mail Envelope Properties (3CA2782E.AE1 : 12 : 35553)

Subject: Request to terminate license # NR0321D105S
Creation Date: 3/27/02 8:57PM
From: "Rolirad, Ross M" <RRolirad@tesoropetroleum.com>

Created By: RRolirad@tesoropetroleum.com

Recipients

nrc.gov

twf4_po.TWFN_DO

USB (Ujagar Bhachu)

tesoropetroleum.com

HChristiansen CC (Christiansen, Henry)

nrc.gov

twf5_po.TWFN_DO

SAC CC (Shirley Crutchfield)

Post Office

twf4_po.TWFN_DO

twf5_po.TWFN_DO

Route

nrc.gov

tesoropetroleum.com

nrc.gov

Files

MESSAGE

Part.001

NRC Terminate Krypton License 03-27-02.doc

Mime.822

Size

374

1217

39956

Date & Time

03/27/02 08:57PM

26624

Options

Expiration Date:

None

Priority:

Standard

Reply Requested:

No

Return Notification:

None

Concealed Subject:

No

Security:

Standard



TESORO

Tesoro Hawaii Corporation
733 Bishop Street Suite 2700
P.O. Box 3379
Honolulu, Hawaii 96842-0001
808 547 3111
808 547 3145 Fax

March 27, 2002

Nuclear Regulatory Commission
11545 Rockville Pike
Rockville, MD 20852
Attn: Mail Stop 8F5 (Mr. U. S. Bhachu)

Subject: Request to terminate License # NR0321D105S

Dear Mr. Bhachu,

In accordance with Section 13.4 of NUREG 1556, Vol. 3, we are requesting that the referenced license be terminated. Following are our replies to the four points of information required by Section 13.4 of NUREG 1556, Volume 3:

- Both custom Krypton-85 sources have been decommissioned and transferred to Qual-X, Inc. at 3029 Home Road, Powell, OH 43065 for recycling. The transfer was made on February 23, 2001. Qual-X Inc. license number is: 031214210003. Their contact is Mr. Greg Mahon @ 740-881-5543. Tesoro Hawaii Refinery (formerly BHP Petroleum Americas) has no additional Krypton-85 devices in use or, in our possession.
- Not Applicable. Sources were custom devices for use within the refinery only.
- Not Applicable. Sources were custom devices for use within the refinery only.
- Tesoro Hawaii Corporation hereby verifies that no changes were made to the products since their initial registration, or last amendment.

Respectfully,

Ross M. Rolirad
Supervisor, I&E Engineering
Tesoro Hawaii Corporation
91-325 Komohana Street
Kapolei, HI 96707
Ph.: 808-479-0535; Fax: 707-516-2486