INDEX

ADMINISTRA	TIVE CONTROLS		
SECTION			PAGE
<u>6.1 RESPONSIBILITY</u>			
<u>6.2 ORGANIZATION</u>			
6.2.1 OFFSITE AND ONSITE ORGANIZATION			
	Figure 6.2.1-1	Deleted	6-3
6.2.2 UNIT	STAFF		6-2
	Figure 6.2.2-1	Deleted	6-4
	Table 6.2.2-1	Minimum Shift Crew Composition	6-5
6.2.3 DELE	TED; Refer to note on pa	ge	6-6
6.2.4 SHIF	T TECHNICAL ADVISOR		6-6
<u>6.3 UNIT</u>	STAFF QUALIFICATIONS		6-6
6.4 DELET	<u>ED</u>		6-7
6.5 REVIE	W AND AUDIT		
6.5.1	Plant Operations Revie	w Committee (PORC)	
	Function		6-7
	Composition		6-7
	Alternates		6-7
	Meeting Frequency		6-7
	Quorum		6-7
	Responsibilities		6-8
	Records		6-9

ł

6.4 DELETED

6.5 REVIEW AND AUDIT

6.5.1 PLANT OPERATIONS REVIEW COMMITTEE (PORC)

FUNCTION

6.5.1.1 The PORC shall function to advise the Plant Manager on all matters related to nuclear safety.

COMPOSITION

6.5.1.2 The Plant Operations Review Committee is composed of nine regular members from the Limerick Generating Station staff. Members shall collectively have experience in the following areas:

Plant Operations Engineering Maintenance Instrumentation and Controls Planning Radiation Safety Chemistry Experience Assessment

Members shall meet the requirements of ANSI/ANS 3.1-1978, Section 4.7, for the applicable required experience and be appointed in writing by the Plant Manager. The Chairman and alternate Chairmen of the PORC shall be drawn from the PORC members and appointed in writing by the Plant Manager.

ALTERNATES

6.5.1.3 All alternate members shall be appointed in writing by the PORC Chairman to serve on a temporary basis; however, no more than two alternates shall participate as voting members in PORC activities at any one time.

MEETING FREQUENCY

6.5.1.4 The PORC shall meet at least once per calendar month and as convened by the PORC Chairman or his designated alternate.

QUORUM

6.5.1.5 The quorum of the PORC necessary for the performance of the PORC responsibility and authority provisions of these Technical Specifications shall consist of the Chairman or his designated alternate and four members including alternates.

LIMERICK - UNIT 1

<u>INDEX</u>

ADMINISTRATIVE CONTROLS			
SECTION		<u>PAGE</u>	
<u>6.1 RESPONSIBILITY</u>			
<u>6.2 ORGANIZATION</u>			
6.2.1 OFFSITE AND ONSITE ORGANIZATION			
	DELETED		
Figure 6.2.2-1			
Table 6.2.2-1	Minimum Shift Crew		
	Composition	6-5	
6.2.3 DELETED; Refer to note on page			
6.2.4 SHIFT TECHNICAL ADVISOR			
6.3 UNIT STAFF QUALIFICATIONS			
<u>6.4 DELETED</u>			
6.5 REVIEW AND AUDIT			
6.5.1 Plant Operations Review	(Committee (PORC)		
Function		6-7	
Composition		6-7	
Meeting Frequency	Meeting Frequency		

.

6.4 DELETED

6.5 REVIEW AND AUDIT

6.5.1 PLANT OPERATIONS REVIEW COMMITTEE (PORC)

FUNCTION

6.5.1.1 The PORC shall function to advise the Plant Manager on all matters related to nuclear safety.

COMPOSITION

6.5.1.2 The Plant Operations Review Committee is composed of nine regular members from the Limerick Generating Station staff. Members shall collectively have experience in the following areas:

Plant Operations Engineering Maintenance Instrumentation and Controls Planning Radiation Safety Chemistry Experience Assessment

Members shall meet the requirements of ANSI/ANS 3.1-1978, Section 4.7, for the applicable required experience and be appointed in writing by the Plant Manager. The Chairman and alternate Chairmen of the PORC shall be drawn from the PORC members and appointed in writing by the Plant Manager.

ALTERNATES

6.5.1.3 All alternate members shall be appointed in writing by the PORC Chairman to serve on a temporary basis; however, no more than two alternates shall participate as voting members in PORC activities at any one time.

MEETING FREQUENCY

6.5.1.4 The PORC shall meet at least once per calendar month and as convened by the PORC Chairman or his designated alternate.

QUORUM

6.5.1.5 The quorum of the PORC necessary for the performance of the PORC responsibility and authority provisions of these Technical Specifications shall consist of the Chairman or his designated alternate and four members including alternates.

LIMERICK - UNIT 2