Exelon Nuclear Limerick Generating Station P.O. Box 2300 Sanatoga, PA 19464

.

www.exeloncorp.com

T.S. 6.9.1.6

Nuclear

Exelun

June 12, 2002

U. S. Nuclear Regulatory Commission Attn: Document Control Desk Washington, DC 20555

> Limerick Generating Station, Units 1 and 2 Facility Operating License Nos. NPF-39 and NPF-85 NRC Docket Nos. 50-352 and 50-353

Subject: Monthly Operating Reports for May 2002

Enclosed are the monthly operating reports for Limerick Units 1 and 2 for the month of May 2002 forwarded pursuant to Technical Specification 6.9.1.6 and the guidance of GL 97-02.

If you have any questions or require additional information, please do not hesitate to contact us.

Sincerely,

WPOMALON Jor Rosser C BRAUN Robert C. Braun Plant Manager

Attachments

cc: H. J. Miller, Administrator, Region I, USNRC A. L. Burritt, LGS USNRC Senior Resident Inspector

IE24

Unit: Limerick 1 Docket No: 50-352 Date: 6/12/02 Completed by: Greg Lee (610)718-3707 Telephone:

#### A. OPERATING DATA

¥

**REPORT REPORTING PERIOD-May 2002** 

Design Electrical Rating (MWe-Net)		
Maximum Dependable Capacity (MWe-Net)	1134	

	Month	Year to Date	Cumulative
Hours Reactor Critical (Hours)	659.7	3,176.2	124,731.4
Hours Generator On-Line (Hours)	644.8	3,108.0	122,772.1
Unit Reserve Shutdown Hours (Hours)	0.0	0.0	0.0
Net Electrical Energy (MWh)	712,656	3,357,788	125,839,787

#### **B. UNIT SHUTDOWN**

No.	Date (yymmdd)	Туре	Duration (Hours)	Reason	Method	Corrective Actions/Comments
2	020519	F	99.2	A	3	1F37-Turbine trip due to high turbine thrust bearing wear detector failure.
SUMMARY						

Unit 1 began the month of May 2002 at 100% of rated thermal power (RTP).

On May 18th at 22:00 hours, commenced power reduction to 94% RTP to perform MSIV and turbine valve testing.

On May 19th at 00:54 hours, the turbine tripped, and the reactor automatically scrammed due to high turbine thrust bearing wear detector failure.

On May 22<sup>nd</sup> at 13:14 hours, reactor criticality was achieved.

On May 23rd at 04:05 hours, the main generator was synchronized to the grid.

On May 26th at 10:05 hours, reactor power was reduced from 94% RTP to 65% RTP for rod pattern adjustment. Power ascension was reestablished at 13:10 hours.

On May 27th at 22:58 hours, reactor power was restored to 100% RTP.

Unit 1 ended the month of May 2002 at 100% RTP.

Туре	Reason	Method
F-Forced	A-Equipment Failure (Explain)	1-Manual
S-Scheduled	B-Maintenance or Test	2-Manual
	C-Refueling	3-Automa
	D-Regulatory Restriction	4-Continu
	E-Operator Training/License Examination	5-Other (E
	F-Administrative	
	G-Operational Error (Explain)	
	H-Other (Explain)	

# Manual Trip/Scram

Automatic Trip/Scram Continuation Other (Explain)

#### C. SAFETY/RELIEF VALVE OPERATION

Date	Valves Actuated	No. & Type of Actuation	Plant Condition	Description of Event
		None During May		

 Unit:
 Limerick 2

 Docket No:
 50-353

 Date:
 6/12/02

 Completed by:
 Greg Lee

 Telephone:
 (610)718-3707

# A. OPERATING DATA

.

\*\* ----

# **REPORT REPORTING PERIOD-**May 2002

Design Electrical Rating (MWe-Net)	1191
Maximum Dependable Capacity (MWe-Net)	1134

	Month	Year to Date	Cumulative
Hours Reactor Critical (Hours)	744.0	3,623.0	101,056.0
Hours Generator On-Line (Hours)	744.0	3,623.0	99,385.9
Unit Reserve Shutdown Hours (Hours)	0.0	0.0	0.0
Net Electrical Energy (MWh)	841,484	4,213,317	105,838,041

#### **B. UNIT SHUTDOWN**

No.	Date (yymmdd)	Туре	Duration (Hours)	Reason	Method	Corrective Actions/Comments	
			None During				
			Iviay				
SUM	MARY				<u> </u>		
Unit 2	Unit 2 began the month of May 2002 at 100% of rated thermal power (RTP).						
On May 24th at 22:08 hours, commenced power reduction to 57% RTP to perform MSIV & turbine							
valve testing, and condenser waterbox cleaning.							
On May 27 <sup>th</sup> at 17:50 hours, reactor power was restored to 100% RTP.							
On May 27th at 22:35 hours, commenced power reduction to 80% RTP to repair the limit switch on							
MSV# 2.							
On M	On May 28th at 19:40 hours, reactor power was restored to 100% RTP.						
Unit 2	Unit 2 ended the month of May 2002 at 100% RTP.						

Туре	Reason
F-Forced	A-Equipment Failure (Explain)
S-Scheduled	B-Maintenance or Test
	<b>C</b> -Refueling
	D-Regulatory Restriction
	E-Operator Training/License Examination
	F-Administrative
	G-Operational Error (Explain)
	H-Other (Explain)

Method 1-Manual 2-Manual Trip/Scram 3-Automatic Trip/Scram 4-Continuation 5-Other (Explain)

### C. SAFETY/RELIEF VALVE OPERATION

Date	Valves Actuated	No. & Type of Actuation	Plant Condition	Description of Event
		None During May		