

August 16, 2002

Mr. Mark Reddeman  
Site Vice President  
Kewaunee and Point Beach Nuclear Plants  
Nuclear Management Company, LLC  
6610 Nuclear Road  
Two Rivers, WI 54241

SUBJECT: POINT BEACH NUCLEAR POWER PLANT, UNITS 1 AND 2 -  
BULLETIN 2001-01, "CIRCUMFERENTIAL CRACKING OF REACTOR  
PRESSURE VESSEL HEAD PENETRATION NOZZLES"

Dear Mr. Reddemann:

On August 3, 2001, the U.S. Nuclear Regulatory Commission (NRC) staff issued Bulletin 2001-01, "Circumferential Cracking of Reactor Pressure Vessel Head Penetration Nozzles," to the industry requesting that addressees provide information related to the structural integrity of the reactor pressure vessel head penetration (VHP) nozzles for their respective facilities, including the extent of VHP nozzle leakage and cracking that has been found to date, the inspections and repairs that have been undertaken to satisfy applicable regulatory requirements, and the basis for concluding that their plans for future inspections will ensure compliance with applicable regulatory requirements at their respective pressurized-water reactor (PWR) plants. You were requested to respond to Items 1 and 4 of the Bulletin within 30 days of its issuance.

You provided your Bulletin response by letters dated September 4, 2001, January 4, 2002, January 28, 2002, and May 9, 2002, indicating that your plants are in the category of plants considered as having moderate susceptibility to VHP nozzle cracking, based on a relative susceptibility ranking of more than 5 and less than 30 effective full power years from the Oconee Nuclear Station, Unit 3, condition. The NRC staff finds that you have provided the requested information. Your Bulletin responses stated your intent to perform an effective visual examination of 100 percent of the VHP nozzles at the next refueling outage for each unit. For those nozzles that you cannot perform an effective visual examination, you stated that you will perform an examination from underneath the reactor pressure vessel head to ensure no through-wall pressure boundary leakage of the nozzles. We note that for Unit 2, an effective visual examination of 100 percent of the VHP nozzles was completed in April 2002. The NRC staff has concluded that the inspection schedule and scope described in your Bulletin response provide reasonable assurance that public health and safety will be maintained at your plants. Since the proposed inspection scope and schedule described in your response were integral to the staff's findings, it is the staff's expectation that you will submit a revised response to the Bulletin if you make any substantive changes to the schedule and/or scope of future inspections for your plants. If warranted by such changes, the staff will reevaluate this issue for Point Beach Nuclear Plant, Unit 1.

Addressees are reminded that Item 5 of the Bulletin requested the following information within 30 days after plant restart following the next refueling outage:

- a. a description of the extent of VHP nozzle leakage and cracking detected at your plant, including the number, location, size, and nature of each crack detected;
- b. if cracking is identified, a description of the inspections (type, scope, qualification requirements, and acceptance criteria), repairs, and other corrective actions you have taken to satisfy applicable regulatory requirements. This information is requested only if there are any changes from prior information submitted in accordance with this bulletin.

Sincerely,

*/RA/*

Deirdre W. Spaulding, Project Manager, Section 1  
Project Directorate III  
Division of Licensing Project Management  
Office of Nuclear Reactor Regulation

Docket Nos. 50-266 and 50-301

cc: See next page

Addressees are reminded that Item 5 of the Bulletin requested the following information within 30 days after plant restart following the next refueling outage:

- a. a description of the extent of VHP nozzle leakage and cracking detected at your plant, including the number, location, size, and nature of each crack detected;
- b. if cracking is identified, a description of the inspections (type, scope, qualification requirements, and acceptance criteria), repairs, and other corrective actions you have taken to satisfy applicable regulatory requirements. This information is requested only if there are any changes from prior information submitted in accordance with this bulletin.

Sincerely,

**/RA/**

Deirdre W. Spaulding, Project Manager, Section 1  
 Project Directorate III  
 Division of Licensing Project Management  
 Office of Nuclear Reactor Regulation

Docket Nos. 50-266 and 50-301

cc: See next page

DISTRIBUTION:

PUBLIC	LRaghavan	OGC	WBateman
PDIII-1 Reading	DSpaulding	ACRS	AHiser
EMCB Reading	JZimmerman	RLanksbury, RIII	JCollins
RBouling			

ADAMS Accession No. ML022170391

OFFICE	PDIII-1/PM	PDIII-1/LA	PDIII-1/SC
NAME	DSpaulding	RBouling	LRaghavan*
DATE	08/15/02	08/15/02	08/15/02

OFFICIAL RECORD COPY

Point Beach Nuclear Plant, Units 1 and 2

cc:

Mr. John H. O'Neill, Jr.  
Shaw, Pittman, Potts & Trowbridge  
2300 N Street, NW  
Washington, DC 20037-1128

Mr. Richard R. Grigg  
President and Chief Operating Officer  
Wisconsin Electric Power Company  
231 West Michigan Street  
Milwaukee, WI 53201

Site Licensing Manager  
Point Beach Nuclear Plant  
Nuclear Management Company, LLC  
6610 Nuclear Road  
Two Rivers, WI 54241

Mr. Ken Duveneck  
Town Chairman  
Town of Two Creeks  
13017 State Highway 42  
Mishicot, WI 54228

Chairman  
Public Service Commission  
of Wisconsin  
P.O. Box 7854  
Madison, WI 53707-7854

Regional Administrator, Region III  
U.S. Nuclear Regulatory Commission  
801 Warrenville Road  
Lisle, IL 60532-4351

Resident Inspector's Office  
U.S. Nuclear Regulatory Commission  
6612 Nuclear Road  
Two Rivers, WI 54241

Ms. Sarah Jenkins  
Electric Division  
Public Service Commission of Wisconsin  
P.O. Box 7854  
Madison, WI 53707-7854

Mr. Roy A. Anderson  
Executive Vice President and  
Chief Nuclear Officer  
Nuclear Management Company, LLC  
700 First Street  
Hudson, WI 54016

Nuclear Asset Manager  
Wisconsin Electric Power Company  
231 West Michigan Street  
Milwaukee, WI 53201