

April 24, 1990

Docket Nos. 50-282  
and 50-306

Mr. Thomas M. Parker, Manager  
Nuclear Support Services  
Northern States Power Company  
414 Nicollet Mall  
Minneapolis, Minnesota 55401

Dear Mr. Parker:

SUBJECT: ERRATA FOR AMENDMENT NO. 92 AND AMENDMENT NO. 85 TO FACILITY  
OPERATING LICENSES DPR-42 AND DPR-60 (TAC NOS. 75314 AND 75315)

The changes to the Technical Specifications (TS) implemented by License Amendment Nos. 92 and 85, which were transmitted to you by letter dated March 13, 1990, have been found to contain text errors. Specifically, the Amendments' Index pages did not indicate the deletion of some Figures from the TS.

The enclosed errata to the TS changes implemented by License Amendment Nos. 92 and 85 are hereby transmitted and deletion of the proper TS Figures should be followed.

Sincerely,

Original signed by

Dominic C. DiIanni, Project Manager  
Project Directorate III-1  
Division of Reactor Projects - III,  
IV, V & Special Projects  
Office of Nuclear Reactor Regulation

Enclosures:  
As stated

cc w/enclosures  
See next page

DISTRIBUTION

DOCKET FILE  
NRC & LOCAL PDRs  
PD31 R/F  
JZWOLINSKI  
PSHUTTLEWORTH  
DDIANNI  
ACRS(10)  
GPA/PA

OGC  
EJORDAN  
DHAGAN  
GHILL(4)  
WANDA JONES  
JCALVO  
OC/LFMB

LA/PD31:DRSP, *MWA*  
PSHUTTLEWORTH  
4/23/90

*DCD*  
PM/PD31:DRSP  
DDIANNI  
4/23/90

*DCD*  
(A)D/PD31  
DDIANNI  
4/23/90

*DFol*  
*1/1*

9004300293 900424  
PDR ADOCK 05000282  
F PDC

PI ERRATA 75314/15 *CP-1*



UNITED STATES  
NUCLEAR REGULATORY COMMISSION  
WASHINGTON, D. C. 20555

April 24, 1990

Docket Nos. 50-282  
and 50-306

Mr. Thomas M. Parker, Manager  
Nuclear Support Services  
Northern States Power Company  
414 Nicollet Mall  
Minneapolis, Minnesota 55401

Dear Mr. Parker:

SUBJECT: ERRATA FOR AMENDMENT NO. 92 AND AMENDMENT NO. 85 TO FACILITY  
OPERATING LICENSES DPR-42 AND DPR-60 (TAC NOS. 75314 AND 75315)

The changes to the Technical Specifications (TS) implemented by License Amendment Nos. 92 and 85, which were transmitted to you by letter dated March 13, 1990, have been found to contain text errors. Specifically, the Amendments' Index pages did not indicate the deletion of some Figures from the TS.

The enclosed errata to the TS changes implemented by License Amendment Nos. 92 and 85 are hereby transmitted and deletion of the proper TS Figures should be followed.

Sincerely,

A handwritten signature in cursive script that reads "Dominic C. DiIanni".

Dominic C. DiIanni, Project Manager  
Project Directorate III-1  
Division of Reactor Projects - III,  
IV, V & Special Projects  
Office of Nuclear Reactor Regulation

Enclosures:  
As stated

cc w/enclosures  
See next page

Mr. T. M. Parker  
Northern States Power Company

Prairie Island Nuclear Generating  
Plant

cc:  
Gerald Charnoff, Esq.  
Shaw, Pittman, Potts and Trowbridge  
2300 N Street, N.W.  
Washington, DC 20037

Dr. J. W. Ferman  
Minnesota Pollution Control Agency  
520 LaFayette Road  
St. Paul, MN 55155

Mr. E. L. Watzl, Plant Manager  
Prairie Island Nuclear Generating Plant  
Northern States Power Company  
Route 2  
Welch, Minnesota 55089

Joseph G. Maternowski  
Assistant Attorney General  
Environmental Protection Division  
Suite 200  
520 Lafayette Road  
St. Paul, Minnesota 55155

U.S. Nuclear Regulatory Commission  
Resident Inspector's Office  
1719 Wakonade Drive East  
Welch, Minnesota 55089

Regional Administrator, Region III  
U.S. Nuclear Regulatory Commission  
Office of Executive Director for  
Operations  
799 Roosevelt Road  
Glen Ellyn, Illinois 60137

Mr. William Miller, Auditor  
Goodhue County Courthouse  
Red Wing, Minnesota 55066

ERRATA

ATTACHMENT TO LICENSE AMENDMENT NO. 92

FACILITY OPERATING LICENSE NO. DPR-42

DOCKET NO. 50-282

Revise Appendix A Technical Specifications by removing the pages identified below and inserting the attached pages. The revised pages are identified by amendment number and contain marginal lines indicating the area of change

REMOVE

TS-ix  
TS-xiii  
TS.1-2  
TS.2.3-3  
Table TS 3.5-2  
TS.3.10-1  
TS.3.10-2  
TS.3.10-3  
TS.3.10-4  
TS.3.10-5  
TS.3.10-7  
TS.3.10-8  
TS.6.7-4  
TS.6.7-5  
-  
B.2.1-2  
B.3.10-1  
B.3.10-3  
B.3.10-4  
B.3.10-6  
B.3.10-10  
Figure TS 3.10-3  
Figure TS 3.10-4  
Figure TS 3.10-5  
Figure TS 3.10-6  
Figure TS 3.10-7  
Figure TS 3.12-2

INSERT

TS-ix  
TS-xiii  
TS.1-2  
TS.2.3-3  
Table TS 3.5-2  
TS.3.10-1  
TS.3.10-2  
TS.3.10-3  
TS.3.10-4  
TS.3.10-5  
TS.3.10-7  
TS.3.10-8  
TS.6.7-4  
TS.6.7-5  
TS.6.7-6  
B.2.1.-2  
B.3.10-1  
B.3.10-3  
B.3.10-4  
B.3.10-6  
B.3.10-10  
-  
-  
-  
-  
-  
-

ERRATA

ATTACHMENT TO LICENSE AMENDMENT NO. 92

FACILITY OPERATING LICENSE NO. DPR-42

DOCKET NO. 50-282

Revise Appendix A Technical Specifications by removing the pages identified below and inserting the attached pages. The revised pages are identified by amendment number and contain marginal lines indicating the area of change

REMOVE

TS-ix  
TS-xiii  
TS.1-2  
TS.2.3-3  
Table TS 3.5-2  
TS.3.10-1  
TS.3.10-2  
TS.3.10-3  
TS.3.10-4  
TS.3.10-5  
TS.3.10-7  
TS.3.10-8  
TS.6.7-4  
TS.6.7-5  
-  
B.2.1-2  
B.3.10-1  
B.3.10-3  
B.3.10-4  
B.3.10-6  
B.3.10-10  
Figure TS 3.10-3  
Figure TS 3.10-4  
Figure TS 3.10-5  
Figure TS 3.10-6  
Figure TS 3.10-7  
Figure TS 3.12-2

INSERT

TS-ix  
TS-xiii  
TS.1-2  
TS.2.3-3  
Table TS 3.5-2  
TS.3.10-1  
TS.3.10-2  
TS.3.10-3  
TS.3.10-4  
TS.3.10-5  
TS.3.10-7  
TS.3.10-8  
TS.6.7-4  
TS.6.7-5  
TS.6.7-6  
B.2.1.-2  
B.3.10-1  
B.3.10-3  
B.3.10-4  
B.3.10-6  
B.3.10-10  
-  
-  
-  
-  
-