Docket Nos. 50-282 and 50-306

> Mr. T. M. Parker, Manager Nuclear Support Services Northern States Power Company 414 Nicollet Mall Minneapolis, Minnesota 55401

Dear Mr. Parker:

ERRATA FOR AMENDMENT NOS. 96 AND 89 TO FACILITY OPERATING LICENSE SUBJECT: DPR-42 AND DPR-60 (TAC NOS. 79690 AND 79691)

The changes to the plant Technical Specifications (TS) implemented by License Amendment Nos. 96 and 89, which were transmitted to you by letter dated May 9, 1991, have been found to contain text errors on page TS.£.2-7. A corrected page TS.6.2-7 is attached and should replace the page previously transmitted.

Sincerely,

/s/

Armando Masciantonio, Project Manager Project Directorate III-1 Division of Reactor Projects - III/IV/V Office of Nuclear Reactor Regulation

Enclosure: As stated

cc w/enclosure: See next page

DISTRIBUTION DOCKET FILE NRC & LOCAL PDRs PD31 R/F

BBOGER JZWOLINSKI PSHUTTLEWORTH **AMASCIANTONIO** OC/LFMB

LA/PD31:DRP345 PSHUTTLEWORTH

5/2/191 9106070086 910529 PDR ADOCK 05000282 PM/PD31:DRP345 AMASCIANTONIO 5/28/91 asm

OGC

DHAGAN

CGRIMES

GPA/PA

ACRS(10)

GHILL(4)√

WANDA JONES

D/PD31:DRP345 LMARSH

5/24/91

医病情感引起, 直 化反池 [4]



UNITED STATES NUCLEAR REGULATORY COMMISSION WASHINGTON, D. C. 20555

May 29, 1991

Docket Nos. 50-282 and 50-306

Mr. T. M. Parker, Manager Nuclear Support Services Northern States Power Company 414 Nicollet Mall Minneapolis, Minnesota 55401

Dear Mr. Parker:

SUBJECT: ERRATA FOR AMENDMENT NOS. 96 AND 89 TO FACILITY OPERATING LICENSE DPR-42 AND DPR-60 (TAC NOS. 79690 AND 79691)

The changes to the plant Technical Specifications (TS) implemented by License Amendment Nos. 96 and 89, which were transmitted to you by letter dated May 9, 1991, have been found to contain text errors on page TS.6.2-7. A corrected page TS.6.2-7 is attached and should replace the page previously transmitted.

Sincerely,

a.S. monist.

Armando Masciantonio, Project Manager Project Directorate III-1 Division of Reactor Projects - III/IV/V Office of Nuclear Reactor Regulation

Enclosure: As stated

cc w/enclosure: See next page Mr. T. M. Parker Northern States Power Company

cc:

Gerald Charnoff, Esq. Shaw, Pittman, Potts and Trowbridge 2300 N Street, N.W. Washington, DC 20037

Mr. E. L. Watzl, Site General Manager Prairie Island Nuclear Generating Plant Northern States Power Company Route 2 Welch, Minnesota 55089

Joseph G. Maternowski
Assistant Attorney General
Environmental Protection Division
Suite 200
520 Lafayette Road
St. Paul, Minnesota 55155

U.S. Nuclear Regulatory Commission Resident Inspector's Office 1719 Wakonade Drive East Welch, Minnesota 55089

Regional Administrator, Region III U.S. Nuclear Regulatory Commission Office of Executive Director for Operations 799 Roosevelt Road Glen Ellyn, Illinois 60137

Mr. William Miller, Auditor Goodhue County Courthouse Red Wing, Minnesota 55066

- b. Content and method of submission of presentations to the Operations Committee
- c. Mechanism for scheduling meetings
- d. Provision for meeting agenda
- e. Use of subcommittees
- f. Review and approval, by members, of OC actions
- g. Provision for distribution of minutes

C. Maintenance Procedures

- Maintenance work requests and their associated procedures required by specification 6.5.C and changes thereto, shall be prepared, reviewed and approved. Each procedure or procedure change shall be reviewed by a qualified individual(s) other than the individual(s) who prepared the procedure or procedure change. The appropriate superintendent (as previously designated by the Plant Manager) shall approve these procedures.
- 2. Individuals responsible for reviews performed in accordance with the requirements of specification 6.2.C.l above shall meet or exceed the qualifications described in section 4.2 or 4.4 of ANSI N13.1-1971 and shall be previously designated by the Plant Manager. Such reviews shall include a determination of whether or not additional cross disciplinary review is necessary.
- 3. All reviews shall include a determination of the need for a safety evaluation to establish whether or not an unreviewed safety question is involved.