

James R. Becker Station Director Diablo Canyon Power Plant Mail Code 104/5/504 PO Box 56 Avila Beach, CA 93424

805 545 3462 Fax 805 545 4234

August 15, 2002

PG&E Letter DCL-02-094

U.S. Nuclear Regulatory Commission ATTN: Document Control Desk Washington, DC 20555-0001

Docket No. 50-275, OL-DPR-80 Docket No. 50-323, OL-DPR-82 Diablo Canyon Units 1 and 2 Monthly Operating Report for July 2002

Dear Commissioners and Staff:

Attached is the Monthly Operating Report for Diablo Canyon Power Plant, Units 1 and 2, for July 2002. This report is submitted in accordance with Technical Specification 5.6.4 and NRC Generic Letter 97-02.

Also attached is Enclosure 3, which is being submitted to replace Page 2 of Enclosure 2, "Unit Shutdowns" for Unit 1, in the June 2002 Monthly Operating Report, DCL-02-076, dated July 12, 2002. Revision bars and lineouts indicate the changes.

Sincerely,

James R. Becker

Imp/1713/R0235849

**Enclosures** 

cc/enc:

Paul R. Fox, American Nuclear Insurers

Robert D. Glynn, Jr.

Barbara Lewis, McGraw Hill

Ellis W. Merschoff, NRC Regional Administrator, Region IV

David L. Proulx, NRC Senior Resident Inspector

Gregory M. Rueger

Girija S. Shukla, NRC Project Manager

**INPO Record Center** 

## JULY 2002, OPERATION SUMMARIES DIABLO CANYON POWER PLANT UNITS 1 AND 2

## Summary of Unit 1 Operation

Unit 1 began July in Mode 1 (Power Operation) at approximately 100 percent power. On July 2, 2002, Operators reduced power to as low as approximately 81 percent due to increasing turbine vibration. After adjusting generator seal temperatures, vibrations decreased. On July 4, 2002, operators returned the unit to approximately 100 percent power. On July 13, 2002, operators reduced power to approximately 15 percent and separated the generator from the grid due to increasing vibrations at the turbine generator current transformers. On July 14, 2002, after installing a "balance shot" on the turbine, operators paralleled the unit to the grid, and increased power to approximately 100 percent.

## Summary of Unit 2 Operation

Unit 2 began July in Mode 1 at approximately 100 percent power. There were no significant operational activities.

## Actuations of Safety or Pressurizer Power Operated Relief Valves

There were no challenges to the pressurizer power operated relief valves, pressurizer safety valves, or steam generator safety valves.

## **OPERATING DATA REPORT**

DOCKET NO.:

50-275

UNIT NAME:

Diablo Canyon Unit 1 08/01/2002

DATE:

COMPLETED BY: L. M. Parker

TELEPHONE:

(805) 545-4327

**REPORT MONTH: July 2002** 

Γ	1.	Design Electrical Rating (MWe - Net):	1,103
Γ	2.	Maximum Dependable Capacity (MWe - Net):	1,087

		This Month	YTD	Cumulative
3.	Number of Hours Reactor Critical:	744.0	4,371.5	131,791.5
4.	Number of Hours Generator On-Line:	729.8	4,293.2	130,335.5
5.	Unit Reserve Shutdown Hours:	0.0	0.0	0.0
6.	Net Electrical Energy Generated (MWH):	787,822	4,600,124	134,758,213

### **UNIT SHUTDOWNS**

DOCKET NO.:

50-275

UNIT NAME:

Diablo Canyon Unit 1

DATE:

08/01/2002

COMPLETED BY: L. M. Parker

TELEPHONE:

(805) 545-4327

REPORT MONTH: July 2002

NO.	DATE (YYMMDD)	TYPE F (Forced) S (Scheduled)	DURATION (HOURS)	REASON <sup>1</sup>	METHOD OF SHUTTING DOWN <sup>2</sup>	CAUSE & CORRECTIVE ACTIONS COMMENTS
	020713	F	14.2			Increasing vibrations in the turbine generator forced operators to reduce power. The generator was manually taken off line. The reactor remained in Mode 1 at approximately 15 percent power. Therefore, this event is counted for the "duration" off-line but not as a shutdown of the reactor.

### 1. Reason

- A-Equipment Failure (Explain)
- **B-Maintenance or Test**
- C-Refueling
- D-Regulatory Restriction
- E-Operator Training/License Examination
- F- Administrative
- G-Operational Error (Explain)
- H-Other (Explain)

#### 2. Method

- 1-Manual
- 2-Manual Trip/Scram
- 3-Automatic Trip/Scram
- 4-Continuation from Previous Month
- 5-Other

# **OPERATING DATA REPORT**

DOCKET NO.:

50-323

UNIT NAME:

Diablo Canyon Unit 2 08/01/2002

DATE:

COMPLETED BY: L. M. Parker

TELEPHONE:

(805) 545-4327

REPORT MONTH: July 2002

	1.	Design Electrical Rating (MWe - Net):	1119
Ì	2.	Maximum Dependable Capacity (MWe - Net):	1087

		This Month	YTD	Cumulative
3.	Number of Hours Reactor Critical:	744.0	5,055.1	127,736.9
4.	Number of Hours Generator On-Line:	744.0	5,050.0	126,274.0
5.	Unit Reserve Shutdown Hours:	0.0	0.0	0.0
6.	Net Electrical Energy Generated (MWH):	814,205	5,403,779	132,809,711

## **UNIT SHUTDOWNS**

DOCKET NO.:

50-323

UNIT NAME:

Diablo Canyon Unit 2

DATE:

08/01/2002

COMPLETED BY: L. M. Parker TELEPHONE:

(805) 545-4327

REPORT MONTH: July 2002

NO.	DATE (YYMMDD)	TYPE F (Forced) S (Scheduled)	DURATION (HOURS)	REASON <sup>1</sup>	METHOD OF SHUTTING DOWN <sup>2</sup>	CAUSE & CORRECTIVE ACTIONS COMMENTS
N/A						There were no shutdowns this month.

1. Reason

A-Equipment Failure (Explain)

**B-Maintenance or Test** 

C-Refueling

**D-Regulatory Restriction** 

E-Operator Training/License Examination

F- Administrative

G-Operational Error (Explain)

H-Other (Explain)

2. Method

1-Manual

2-Manual Trip/Scram

3-Automatic Trip/Scram

4-Continuation from Previous Month

5-Other

### **UNIT SHUTDOWNS**

DOCKET NO.:

50-275

**UNIT NAME:** 

Diablo Canyon Unit 1

DATE:

07/01/2002 R. L. Russell

COMPLETED BY: TELEPHONE:

(805) 545-4327

**REPORT MONTH: June 2002** 

NO.	DATE (YYMMDD)	TYPE F (Forced) S (Scheduled)	DURATION (HOURS)	REASON <sup>1</sup>	METHOD OF SHUTTING DOWN <sup>2</sup>	CAUSE & CORRECTIVE ACTIONS COMMENTS
2	020603	F	35.8	A	3	A valve positioner air manifold failed resulting in a loss of air to the operator of a main feedwater regulating valve. The valve closed causing an automatic reactor trip on low-low steam generator water level. Refer to NRC Event Number 38961, Licensee Event Report 1-2002-004
2	020605	F	15.7	A	4	Liquid was discovered in the belly of the main generator. The unit was rapidly ramped from 23-15%, then the main generator was tripped. The reactor remained at Mode 1, above 8 % reactor power. Therefore, this event is counted for the "duration" off-line but not as a shutdown of the reactor.

1. Reason

A-Equipment Failure (Explain)

B-Maintenance or Test

C-Refueling

**D-Regulatory Restriction** 

E-Operator Training/License Examination

F- Administrative

G-Operational Error (Explain)

H-Other (Explain)

2. Method

1-Manual

2-Manual Trip/Scram 3-Automatic Trip/Scram

4-Continuation from Previous Month

5-Other