

UNITED STATES NUCLEAR REGULATORY COMMISSION REGION IV 611 RYAN PLAZA DRIVE, SUITE 400 ARLINGTON, TEXAS 76011-4005

AUG 2 6 2002

David L. Wilson, Vice President of Nuclear Energy Nebraska Public Power District P.O. Box 98 Brownville, Nebraska 68321

SUBJECT: MIDCYCLE PERFORMANCE REVIEW AND INSPECTION PLAN - COOPER NUCLEAR STATION

Dear Mr. Wilson

On August 1, 2002, the NRC staff completed its midcycle plant performance assessment of Cooper Nuclear Station. In accordance with NRC Inspection Manual Chapter 0305, "Operating Reactor Assessment Program," the midcycle review involved the participation of all technical divisions in evaluating the performance of your Cooper Nuclear Station facility for the first half of the current assessment cycle, January 1 through December 31, 2002. The purpose of this letter is to inform you of our assessment of your safety performance during this period and our plans for future inspections at your facility so that you will have an opportunity to prepare for these inspections and to inform us of any planned inspections which may conflict with your plant activities.

Plant performance for the most recent quarter was within the Multiple/Repetitive Degraded Cornerstone column of the NRC's Action Matrix based on greater than four quarters with multiple White findings in the Emergency Preparedness Cornerstone.

A supplemental inspection was performed involving NPPD's failure to take immediate compensatory actions following identification of a compromise of the 2000 biennial requalification written examinations. The inspectors determined that you performed a comprehensive root cause evaluation, determined the extent of condition, and developed appropriate corrective actions for this issue. This issue was determined to be a White finding in the Mitigating System Cornerstone, which occurred during the last quarter of the previous assessment period.

A second supplemental inspection was conducted in April 2002 as a result of two additional White findings in the Emergency Preparedness Cornerstone. The results of this inspection indicated that your root cause evaluation did not fully identify and assess all contributing causes that resulted in the breakdown of the Emergency Preparedness Program. These two findings were assessed during the third quarter of calender year 2001 and remain open.

In response to the Multiple/Repetitive Degraded Cornerstone, a third supplemental inspection is currently being conducted to assess your corrective action plans. The results will be communicated at the conclusion of the inspection.

-2-

Additional supplemental inspections will be conducted concerning your performance improvement plan. These inspections will be performed on a quarterly basis. The schedule for these will be communicated via separate correspondence.

In our Annual Assessment letter dated March 4, 2002, we advised you of substantive crosscutting issues in the areas of Problem Identification and Resolution and Human Performance. These two areas continue to show adverse trends, while efforts to correct these areas have been largely ineffective.

The enclosed inspection plan details the inspections scheduled through September 30, 2003. The inspection plan is provided to minimize the resource impact on your staff and to allow for scheduling conflicts and personnel availability to be resolved in advance of inspector arrival onsite. Routine resident inspections are not listed due to their ongoing and continuous nature. The last 6 months of the inspection plan are tentative and may be revised at the end-of-cycle review.

In addition, the NRC is in the process of finalizing a Temporary Instruction (TI) that will be used to review implementation of the Interim Compensatory Measures required by the Agency's Security Order to all commercial nuclear power plants dated February 25, 2002. Schedules have not yet been finalized, but it is anticipated that these inspections will begin within the next calendar quarter. Once finalized, the details will be communicated by separate correspondence.

In accordance with 10 CFR 2.790 of the NRC's "Rules of Practice," a copy of this letter and its enclosure will be made available electronically for public inspection in the NRC Public Document Room or from the Publicly Available Records (PARS) component of NRC's document system (ADAMS). ADAMS is accessible from the NRC Web site at http://www.nrc.gov/reading-rm/adams.html (the Public Electronic Reading Room).

If circumstances arise which cause us to change the inspection plan, we will contact you to discuss the change as soon as possible. Please contact Mr. Thomas Farnholtz at (817) 860-8243 with any questions you may have regarding this letter or the inspection plan.

Sincerely,

Ellis W. Merschoff Regional Administrator

Docket: 50-298 License: DPR-46

Enclosure: Cooper Nuclear Station Inspection/Activity Plan

cc w/enclosure: Michael T. Coyle Site Vice President Nebraska Public Power District P.O. Box 98 Brownville, Nebraska 68321

John R. McPhail, General Counsel Nebraska Public Power District P.O. Box 499 Columbus, Nebraska 68602-0499

D. F. Kunsemiller, Risk and Regulatory Affairs Manager Nebraska Public Power District P.O. Box 98 Brownville, Nebraska 68321

Michael J. Linder, Director Nebraska Department of Environmental Quality P.O. Box 98922 Lincoln, Nebraska 68509-8922

Chairman Nemaha County Board of Commissioners Nemaha County Courthouse 1824 N Street Auburn, Nebraska 68305

Sue Semerena, Section Administrator Nebraska Health and Human Services System Division of Public Health Assurance Consumer Services Section 301 Centennial Mall, South P.O. Box 95007 Lincoln, Nebraska 68509-5007

Ronald A. Kucera, Deputy Director for Public Policy Department of Natural Resources 205 Jefferson Street Jefferson City, Missouri 65101

Jerry Uhlmann, Director State Emergency Management Agency P.O. Box 116 Jefferson City, Missouri 65101

Vick L. Cooper, Chief Radiation Control Program, RCP Kansas Department of Health and Environment Bureau of Air and Radiation 1000 SW Jackson, Suite 310 Topeka, Kansas 66612-1366

Daniel K. McGhee Bureau of Radiological Health Iowa Department of Public Health 401 SW 7th Street, Suite D Des Moines, Iowa 50309

William R. Mayben, President and Chief Executive Officer Nebraska Public Power District 1414 15th Street Columbus, Nebraska 68601

Marlin Logan Presiding Commissioner Atchison County P.O. Box 280 Rock Port, Missouri 64482

Dennis Martin, Sheriff Atchison County Sheriff's Office 511 West Clay Rock Port, Missouri 64482

Loras Baumhover, Sheriff 1805 N Street Auburn, Nebraska 68305

Dick Hainje, Regional Director Federal Emergency Management Agency Region VII 2323 Grand Blvd., Suite 900 Kansas City, Missouri 64108-2670

Daniel K. McGhee Bureau of Radiological Health Iowa Department of Public Health Lucas State Office Building 321 12th Street Des Moines, Iowa 50319-0075

Gary McNutt, Director, Radiation Control Program Section for Environmental Public Health P.O. Box 570 Jefferson City, Missouri 65102-0570

Robert Leopold, State Liaison Officer Nebraska Health and Human Services Department of Regulation and Licensure Assurance 301 Centennial Mall, South P.O. Box 95007 Lincoln, Nebraska 68509-5007

Electronic distribution by RIV: Regional Administrator (EWM) DRP Director (KEB) DRS Director (EEC) Senior Resident Inspector (SCS) Branch Chief, DRP/F (KMK) Senior Project Engineer, DRP/F (JAC) Staff Chief, DRP/TSS (PHH) **RITS Coordinator (NBH)** Jim Isom, Pilot Plant Program (JAI) RidsNrrDipmLipb B. Henderson, PAO (BWH) W. A. Maier, RSLO (WAM) C. J. Gordon (CJG) DRS Branch Chiefs (GMG, ATG, CSM) W. D. Travers, EDO (WDT) C. A. Carpenter, Chief, NRR/DIPM/IIPB (CAC) R. K. Frahm, PPR Program Manager, NRR/DIPM/IIPB (RKF) R. W. Borchardt, Associate Dir. for Inspection and Programs (RWB1) B. W. Sheron, Associate Dir. for Project Licensing and Technical Analysis (BWS) J. Shea, Chief, Regional Operations Staff, OEDO (JWS1) W. Ruland, NRR Project Director (WHR) R. Gramm, Chief, Section 1, NRR/DLPM (RAG) M. Thadani, NRR Project Manager (LJB)

Hard Copy: **Records Center, INPO**

RWAGine CDRP/	DIDRSKER	D DRP 1	DRA	RA
TRFarnholtz;df	EECollins	KEBrockman	TPGwynn	EWMerschoff
TRF	alt in	NM Ar		
8/9 /02	8/22/02	8/20/02	8/ /02	8/22/02
OFFICIAL RECORD	COPY		T=Telephone	E=E-mail F=Fa

S:\DRP\DRPDIR\Midcycle 2002\CNS.wpd

OFFICIAL RECORD COPY

Page 1 of 2

08/13/2002 15:04:08 Report 22

Cooper Inspection / Activity Plan 08/18/2002 - 09/30/2003

· · ·

Unit				Planned Dates		Inspection		
Number	Inspection Activity	Title	on Site	Start	End	Туре		
	PSB-EP1 - EP EXERCISE BASELINE INSPECTION 3							
1	IP 7111401	Exercise Evaluation		08/26/2 002	08/30/2002	Baseline Inspections		
1	IP 7111404	Emergency Action Level and Emergency Plan Changes		08/26/2002	08/30/2002	Baseline Inspections		
1	IP 71151	Performance Indicator Verification		08/26/2002	08/30/2002	Baseline Inspections		
	EMB - HEAT	SINK PERF	1					
1	IP 7111107B	Heat Sink Performance		09/09/2002	09/13/2002	Baseline Inspections		
	PSB-S1 - ACCE	SS AUTH/CONTROL, SEC PLAN & PIV	1					
1	IP 7113001	Access Authorization Program (Behavior Observation Only)		09/09/2002	09/13/2002	Baseline Inspections		
1	IP 7113002	Access Control (Search of Personnel, Packages, and Vehicles: Identification and Authorization)		09/09/2002	09/13/2002	Baseline Inspections		
1	IP 7113004	Security Plan Changes		09/09/2002	09/13/2002	Baseline Inspections		
1	IP 71151	Performance Indicator Verification		09/09/2002	09/13/2002	Baseline Inspections		
	OB-PIR - CNS F	PIR INSPECTION	2					
1	IP 71152B	Identification and Resolution of Problems		09/15/2003	09/19/2003	Baseline Inspections		
1	IP 71152B	Identification and Resolution of Problems		09/29/2003	10/04/2003	Baseline Inspections		
	ACCESSPI - ACRS	Α	1					
1	IP 7112101	Access Control to Radiologically Significant Areas		03/17/2003	03/21/2003	Baseline Inspections		
1	IP 71151	Performance Indicator Verification		03/17/2003	03/21/2003	Baseline Inspections		
	EMB - ISI		1					
1	IP 7111108	Inservice Inspection Activities		04/07/2003	04/11/2003	Baseline Inspections		
	EMB - SSD&	PCI	5					
1	IP 7111121	Safety System Design and Performance Capability		05/05/2003	05/09/2003	Baseline Inspections		
1	IP 7111121	Safety System Design and Performance Capability		05/19/2003	05/23/2003	Baseline Inspections		
	EMB - 50.59		1					
1	IP 7111102	Evaluation of Changes, Tests, or Experiments		05/19/2003	05/23/2003	Baseline Inspections		
	OB-IN - INITIA	AL EXAM PREP	3					
1	X02234	COOPER - INITIAL EXAM (04/03)		05/26/2003	05/30/2003	Not Applicable		
		SAFETY TEAM	4					
1	IP 7112103	Radiation Monitoring Instrumentation and Protective Equipment		06/09/2003	06/13/2003	Baseline Inspections		
1	IP 7112201	Radioactive Gaseous and Liquid Effluent Treatment and Monitoring Systems		06/09/2003	06/13/2003	Baseline Inspections		
1	IP 7112202	Radioactive Material Processing and Transportation		06/09/2003	06/13/2003	Baseline Inspections		
1	IP 7112203	Radiological Environmental Monitoring Program		06/09/2003	06/13/2003	Baseline Inspections		
	OB-IN - INITIA	AL EXAMS	5					
1	X02234	COOPER - INITIAL EXAM (04/03)		06/16/2003	06/20/2003	Not Applicable		
	ALARA2 - ALAR	A PLANNING AND CONTROLS	1					
1	IP 7112102	ALARA Planning and Controls		07/07/2003	07/11/2003	Baseline Inspections		
	This report does not include	INPO and OUTAGE activities.						

This report does not include INPO and OUTAGE activities. This report shows only on-site and announced inspection procedures. Page 2 of 2 08/13/2002

15:04:08

Report 22

Cooper Inspection / Activity Plan 08/18/2002 - 09/30/2003

· · ·

Unit			No. of Staff	Planne	d Dates	Inspection
Number	Inspection Activity	Title	on Site	Start	End	Туре
	PSB-EP1 - EP PF	ROGRAM BASELINE INSPECTION	1			
1	IP 7111402	Alert and Notification System Testing		07/14/2003	07/18/2003	Baseline Inspections
1	IP 7111403	Emergency Response Organization Augmentation Testing		07/14/2003	07/18/2003	Baseline Inspections
1	IP 7111404	Emergency Action Level and Emergency Plan Changes		07/14/2003	07/18/2003	Baseline Inspections
1	IP 7111405	Correction of Emergency Preparedness Weaknesses and Deficiencies		07/14/2003	07/18/2003	Baseline Inspections
1	IP 71151	Performance Indicator Verification		07/1 4/2003	07/18/2003	Baseline Inspections