Region I NMSS Licensee Event Report

ł

	Region I NMSS Licensee Event Report
Licensee	AGILENT TECHNOLOGIES
Event Description	Notice of General License Device w/High Removable Activity
License # 07-28762-026 Event Date 200	Docket # 03002988 MLER-RI 2002-050 Report Date 8/2/02
1. REPORTING REQUIR 10 CFR 20.2201 10 CFR 20.2203	Theft or Loss 10 CFR 35.33 Misadministration 30 Day Report License Condition
10 CFR 30.50 R Other	eport) CFR 31.5
2. REGION I RESPONSE	
Immediate Site I Special Inspection Telephone Inqui	on inspector/Date
Preliminary Rep Information Ente Report referred	red in RI Log
3. REPORT EVALUATIO	
Description of E	
Cause of Event	Additional Information Requested from Licensee
4. SPECIAL INSTRUCTION	DNS OR COMMENTS
Public U	Non-Public
Initials/Date	Initials/Date
Completed by:	Whis Date 2/20/02
Reviewed by:	Junn Junn Junn Manuel



Agilent Technologies 2850 Centerville Road Wilmington, DE 19808

2002 AUG -2 PM 12: 16

Division of Nuclear Materials Safety U.S. Nuclear Regulatory Commission Region I 475 Allendale Road, King of Prussia, PA 19406

Re: Notice of General License device with high removable activity (NRC License 07-28762-02G)

August 1, 2002

Dear Sir or Madam,

Per the requirements of 10 CFR 31.5, I am notifying your office of the following devices returned by overseas customers from which we have obtained removable activity wipes in excess of 0.005 μ Ci. Cells N0203, N0243, and F2784 were returned from overseas. All cells were evaluated by support engineering and their disposition is identified below. I will notify the cell supplier of the high wipes.

Serial #	Model #	Activity (µCi)	Disposition	Comment
M1431	19233	0.013	Refurbish	Source dirty but reusable.
F7991	19233	0.018	Refurbish	Source is clean and reusable.
U2722	G2397A	0.031	Scrapped	Plated source ring fell out.

Please contact me at 302-633-8262 if there are any questions.

n an Araba an Araba. An Araba an

Thank you,

David S. Bennett Radiation Safety Officer