

#### **Commissioners' Technical Assistants Brief**

Wednesday, October 3, 2001 1:00 p.m. - 2:00 p.m.

Room: 18th Floor Commissioners' Conference Room

Purpose:

1) To discuss and focus on the results of the staff's Bulletin 2001-01, "Circumferential Cracking of Reactor Pressure Vessel Head Penetration Nozzles," response reviews for the high susceptibility plants

2) To discuss the basis for the next Regulatory Action to be taken

Success:

Commissioners' Technical Assistants understand the results of the staff's review and the next

Regulatory Action(s)

Introduction:

Jake Zimmerman

5 mins.

Discussion of Reviews:

Allen Hiser

20 mins.

Discussion of Next Regulatory Action(s):

Mark Reinhart

20 mins.

Information in this record was deleted in accordance with the Freedom of Information Act, exemptions

ENY



#### PROCESS/STATUS/SCHEDULE

#### **Action Items Completed**

Bulletin Issued - August 3, 2001

Bulletin Responses Received - September 4, 2001

Preliminary Review of Responses Complete - September 12, 2001

- NRR & RES 7 Submittals
  - Plants that have found Cracking & Leakage (5 plants) Bin 1
  - ▶ Plants with High Susceptibility, < 5 EFPY of Oconee 3 (7 plants) Bin 2
- NRR/DLPM PM "Tiger" Team 37 Submittals
  - Plants with Moderate Susceptibility, b/w 5 & 30 EFPY of Oconee 3 (32 plants) Bin 3
  - Plants with Low Susceptibility, > 30 EFPY of Oconee 3 (25 plants) Bin 4

Temporary Instruction (TI) Issued to Regions - September 20, 2001

#### Pre-decisional information - Not for Public Disclosure



### PLANTS WITH CRACKING/LEAKAGE HISTORY (BIN 1) AND HIGH SUSCEPTIBILITY PLANTS (BIN 2)

	Last Inspection		Next Inspection				CCDP* (IPE)	Regulatory Action	
Plants	Date	Date Method			Method		00Di (ii L)	Proposed ?	
@coneci.	1/2(0.010):	୍ରିଲ୍ଲା Waya : 100% :	je/2002°	:OK	Oval Visya) - 100%	OK:	[E-2  -8 [5]= 3 (Hesponse)	NO.	
(@jojojnjee) 23.	(04/ <u>/4</u> 00)	(Oyal: Viaual: 100%)	**************************************	(@K:	(Qual. Visual - 100%)	:@K	ાંકિટ ક્રાહ્માં ક્રિક્સમાં	NO	
iOconea.S	2/2000 <sup>1</sup>	Quai. Visua) - 100%	10.74	1	Qual, Maral - 100%	ōK.	)	NO	
ANG-L	Jois/Zigiojj	(อิบัสไ: Visual - 100%		(OK	Oval-Visual=10,0%*	:ÓK	3E0	NO NO	
B (0,546,61017/2)	(0.9)/1 9(9)/5	IDNDE-91%			TUNE SERVICE SERVICE	OK.	47450	ino!	
Staphy at	දිනු 2000		The second second second second	(C) 2000 (2000 )	Oual-Mavai-d00%	08	5,8E-6,	NO:-	
TIMIFIC S	(6(6)6) \\(\)8(0)	151. Visual - 1.00% :	10/2010	୍ୱଠାଙ୍କ	(ିପ୍ରାଲ୍: ଐଲ୍ଲାଲ୍) - ଆଉନ୍ଧି	OK.	74.5[≘6]	ONU	
North Anna 1	02/1996	ID NDE-31%	09/2001	ОК	Qual. Visual (100%) & ECT/UT ****	NO	6.6E-3	YES ****	
Robinson	027/2001.	Misual = Paridal = :		NO.	.Qual Misual⊫100% ****	NO	2E:2	YES****	
Davis-Besse	0,3/20,00	Visual-Baitial		NO	Ogal-Visual100%	ÓΚ	6:9E-3	YES	
North Anna 2	rsjör (2)0,011	7 7 77 77		NO	@uat:Visual!-ii.00%****	ŊÓ	6.6E-3	YES ****	
Suinyi2	Fall-2(000)		03/2002	NO	Qual-Visual - 100%	OK.	5:3E-3	YES**	

Conditional core damage probability.

\*\*\* Prior inspection at last RFO, in accordance with GL 88-05 & GL 97-01.

<sup>\*\*</sup> Licensee has committed to qualified visual examination per conference call (September 21, 2001).

<sup>\*\*\*\*</sup> Licensee may or does not have sufficient information to demonstrate that last inspection was a qualified visual examination.

#### Pre-decisional information - Not for Public Disclosure PLANTS HAVING MODERATE SUSCEPTIBILITY TO PWSCC AS OF 10/03/2001

	Ranking (EFPY)		Reg. Action Proposed		
Plant		Date			
Beaver Valley 2: 10 a	115.4	Sépt 2001 3	e 1. Eff. visualini Sept 2001 st	ok,	110
Beaver Valley ?	1665	Feb 2002)	音にVisualini(で的)2002 外 年の。	∤ ok	1/0
Calven Olije i.	998	IFG0-240092	i ist visial romi. Von tali 2002	vok:	, No.
	102		ালাই পরিসুরা কৈওিয়ান পরী	őke,	(0)7
Operal Riversie	601	୍ତଖ୍ୟ ଅନ୍ତା	द्वाः प्रक्रमाणस्त्री २००१ ।	(0)(6	5 1/0
Digidio Canyon di	20,6	ryjay 20,002	高於Wigitell LMEV 2002	(OK	7,4(0)
Delio Cenyon 2	A PATOTIES		ar Viewella	OK.	1/0
Failey is	1 160	Ost, 2005	ির্বি, Vieual na (Cai, 2001)	0.5	709
Kewayinga	210	୍ରମଣ୍ଡ <u>ଅ</u> ନ୍ତର	aj Maraha Falizoon	l'ok	1869
Rom Bredhill			ar viscelling (	(Q.(C.)	140
Point Beach 25	F16.	/smil 2002	Sit Visual in Spring 2002	Öğe	1,10,10,11,11,11,11,11,11,11,11,11,11,11
Prelije kleneli	267		Za Jeli Wevelun	'OK	1/0/
Partial Mage 2	260	Feb. 2002	IETI IVIEVEILIN Felä 20092	OK	1634 NOS
Salim is,	(3)8		All Visionia E	) (0)K	7107
Saloni24	1777	./An 2002	i i i Vigoratija Aor. 2002	OK:	140
ইন্ন-তানুনান্ত্ৰপ্ৰ	10,70	(7ny/2002)	. SIL Visinal or Oban Volt May 2002	(01%	071.5
Sinonoid:	1018	Juni 2009 <u>2</u>	Sir Vienelloi Quel Vol.	OK.	(4/0)
S., Lucieri, L	1018		Ki Visualui <u>D</u>	(Ō)K	140
THE KEY FORM OF STA	6.6	(0;a, 200g)	Eli Vieuel II: Oslober 2001	OK.	10
Truscoy Polint 41	6.75	Win 2008	雪(Vianallia Spine)2002	017	40
Walanholds 22	7.63	(4a, 2002	s : Efficiely of Visual In Spring 2002	ok i	NO
Fort Calhoun	17,9		Visual in	NO	NO"
Ginna	15.0	Mar. 2002	Not Specified (notify 1/02)	NO	NO*
Farley 2	8.3		NDE TBD ir	NÔ	NO*
Millstone 2	14.3	Feb. 2002	Not Specified (notify 1/02)	NO	NO*
ANO:8		/-(5)3  2(G)22	: VSTriface of Volton 25% In Spirity 2002	10	
Indian Points, a	2063		Not Specified (new coviner):	NO.	
Indian RomPerson	1415		GES:8810F/8197-01	[k@*	
(Palo Vaide II	2217702		Nojie/(Wolfd		YES.
Palo-Verde/2		WENE 2002	a Alvonor(Wollein)	0/0	Y Y S
Palo Verde/6	177G	is (Sept. 2001)	Noneityolik .	NO.	MESS.
ISMELUCIO/2	in an	Nov. 2001	None (Eff. Visual II)	NO.	YES Y

Staff is pursuing additional information from the licensee for review Licensee proposed to remove one panel of insulation, and to look under the shroud to examine as many CRDMs as possible. St. Lucie Unit 2 has 91 CRDMs

#### **NEXT REGULATORY ACTION**

#### • Adequate Protection

- Special Circumstance
- ▶ Risk
- Deterministic Standards

#### Regulatory Action

- Phone call with Licensee
- Meeting with Licensee
- Implement Regulatory Action

Pre-decisional Information - Not for Public Displosure

#### PERFORMANCE GOALS

#### Maintain Safety

- Purpose of the bulletin is to collect information to determine if additional regulatory action is necessary
- Information to date provides a sufficient technical basis to show that conditions adverse to quality are being managed for most, but not all plants in the short-term
- Additional cracking should be anticipated long-term management needed

#### Increase Public Confidence

- Participation at public meetings via telephone
- ▶ Maintaining current information on Bulletin 2001-01 & Alloy 600 Web Sites
- Disciplined and timely reviews of plant-specific responses and regulatory action(s)

#### Make NRC Activities and Decisions More Effective, Efficient, and Realistic


- Reviews prioritized based on susceptibility groupings and plant outage schedules
- Use of Risk Insights

#### Reduce Unnecessary Regulatory Burden

- Information requested in the bulletin was minimized
- Stakeholder meetings on resolution of issue (Short- and Long-term)
- Inspection, Assessment, and Repair methods must be developed to manage this issue

#### STEPS TO SUPPORT REGULATORY ACTION

- Brief NRR Leadership Team 9/20/01 (Complete)
- Brief NRR Executive Team 9/26/01 (Complete)
- NRR Management Phone Calls w/ Licensees' 9/28/01 (Complete)
  - Robinson 2
  - Davis-Besse
  - North Anna 2
  - Surry 2
- Brief Executive Director for Operations 10/2/01 (Complete)
- Brief Commission Technical Assistants 10/3/01
- Brief Committee to Review Generic Requirements 10/11/01



ONS-1 Reactor Vessel
Head showing Boric Acid
at CRDM Nozzle
(November 2000)

ONS-1 Reactor Vessel Head showing Boric Acid at Thermocouple Nozzle (November 2000)



## Visual Inspection at Oconee Unit 3 (February 2001)

CRDM Nozzle #56





April 19, 2001

## CRDM Nozzle #50





April 19, 2001


### Visual Inspection at ANO-1 (March 2001)




Visual Inspection at Robinson 2 (April 2001)




## Visual Inspection at Salem Unit 1 (April 2001)



Visual Inspection at Farley Unit 2 (February 2001)





# Visual Inspection at North Anna Unit 2 (September 2001)






# Visual Inspection at North Anna Unit 2 (cont.) (September 2001)





# Visual Inspection at North Anna Unit **2** (cont.) (September 2001)



Visual Inspection at Crystal River 3 (October 2001)

