

H. B. Barron Vice President **Duke Energy Corporation**

McGuire Nuclear Station 12700 Hagers Ferry Road Huntersville, NC 28078-9340 (704) 875-4800 OFFICE (704) 875-4809 FAX

August 15, 2002

United States Nuclear Regulatory Commission ATTENTION: Document Control Desk Washington, DC 20555-0001

SUBJECT: Duke Energy Corporation McGuire Nuclear Station Units 1 and 2 Docket Nos. 50-369 and 50-370 Technical Specification (TS) Bases Change

Attached is a revision to McGuire Technical Specification Bases Manual Sections 3.4.12 (LTOP System) and 3.5.1 (Accumulators).

The phrase "using the power disconnect switches in the correct position" is being deleted from TS SR Bases 3.5.1.5 (ECCS) to maintain consistency with the language in TS SR Bases 3.4.12 (LTOP). Power is preferably removed from the CLA Discharge Isolation Valves by using the power disconnect switches on the control panel, but this revision will also permit power to be removed by opening breaker to valve which is also allowable.

Attachment 1 contains the revised TS Bases List of Effective Sections. Attachment 2 contains revised TS Bases.

Please contact Jeff Thomas at (704) 875-4535 if you have any questions.

Very truly yours,

NR Ray

H. B. Barron



Attachments

U. S. Nuclear Regulatory Commission August 15, 2002 Page 2

Xc w/attachments:

L. A. Reyes U. S. Nuclear Regulatory Commission Regional Administrator, Region II Atlanta Federal Center 61 Forsyth St., SW, Suite 23T85 Atlanta, GA 30303

R. E. Martin U. S. Nuclear Regulatory Commission Mail Stop 0-8G9 11555 Rockville Pike Rockville, MD 20852-2738

R. M. Frye, Director Division of Radiation Protection 3825 Barrett Drive Raleigh, NC 27609-7221

S. M. Shaeffer Senior Resident Inspector U. S. Nuclear Regulatory Commission McGuire Nuclear Station U. S. Nuclear Regulatory Commission August 15, 2002 Page 3

Bc w/attachments:

·--- ;

Mike Cash (EC050) ELL (EC050) Kay Crane McGuire Master File 1.3.2.12

ATTACHMENT 1

````

# REVISED TECHNICAL SPECIFICATION BASES LIST OF EFFECTIVE SECTIONS

# McGuire Nuclear Station Technical Specifications List of Effective Pages and Bases List of Effective Sections Through Amendment Nos. 201/182

ļ

•

î,

| Page Number | Amendment | <b>Revision Date</b> |
|-------------|-----------|----------------------|
| i           | 184/166   | 9/30/98              |
| ii          | 184/166   | 9/30/98              |
| iii         | 184/166   | 9/30/98              |
| iv          | 184/166   | 9/30/98              |
| 1.1-1       | 184/166   | 9/30/98              |
| 1.1-2       | 184/166   | 9/30/98              |
| 1.1-3       | 184/166   | 9/30/98              |
| 1.1-4       | 194/175   | 9/18/00              |
| 1.1-5       | 194/175   | 9/18/00              |
| 1.1-6       | 194/175   | 9/18/00              |
| 1.1-7       | 194/175   | 9/18/00              |
| 1.2-1       | 184/166   | 9/30/98              |
| 1.2-2       | 184/166   | 9/30/98              |
| 1.2-3       | 184/166   | 9/30/98              |
| 1.3-1       | 184/166   | 9/30/98              |
| 1.3-2       | 184/166   | 9/30/98              |
| 1.3-3       | 184/166   | 9/30/98              |
| 1.3-4       | 184/166   | 9/30/98              |
| 1.3-5       | 184/166   | 9/30/98              |
| 1.3-6       | 184/166   | 9/30/98              |
| 1.3-7       | 184/166   | 9/30/98              |
| 1.3-8       | 184/166   | 9/30/98              |
| 1.3-9       | 184/166   | 9/30/98              |
| 1.3-10      | 184/166   | 9/30/98              |
| 1.3-11      | 184/166   | 9/30/98              |
| 1.3-12      | 184/166   | 9/30/98              |
| 1.3-13      | 184/166   | 9/30/98              |
| 1.4-1       | 184/166   | 9/30/98              |
| 1.4-2       | 184/166   | 9/30/98              |
| 1.4-3       | 184/166   | 9/30/98              |

| Page Number<br>1.4-4 | Amendment<br>184/166 | <b>Revision Date</b><br>9/30/98 |
|----------------------|----------------------|---------------------------------|
| 2.0-1                | 184/166              | 9/30/98                         |
| 2.0-2                | 191/172              | 3/20/00                         |
| 3.0-1                | 184/166              | 9/30/98                         |
| 3.0-2                | 184/166              | 9/30/98                         |
| 3.0-3                | 184/166              | 9/30/98                         |
| 3.0-4                | 184/166              | 9/30/98                         |
| 3.0-5                | 184/166              | 9/30/98                         |
| 3.1.1-1              | 184/166              | 9/30/98                         |
| 3.1.2-1              | 184/166              | 9/30/98                         |
| 3.1.2-2              | 184/166              | 9/30/98                         |
| 3.1.3-1              | 184/166              | 9/30/98                         |
| 3.1.3-2              | 184/166              | 9/30/98                         |
| 3.1.3-3              | 184/166              | 9/30/98                         |
| 3.1.4-1              | 184/166              | 9/30/98                         |
| 3.1.4-2              | 184/166              | 9/30/98                         |
| 3.1.4-3              | 184/166              | 9/30/98                         |
| 3.1.4-4              | 186/167              | 9/8/99                          |
| 3.1.5-1              | 184/166              | 9/30/98                         |
| 3.1.5-2              | 184/166              | 9/30/98                         |
| 3.1.6-1              | 184/166              | 9/30/98                         |
| 3.1.6-2              | 184/166              | 9/30/98                         |
| 3.1.6-3              | 184/166              | 9/30/98                         |
| 3.1.7-1              | 184/166              | 9/30/98                         |
| 3.1.7-2              | 184/166              | 9/30/98                         |
| 3.1.8-1              | 184/166              | 9/30/98                         |
| 3.1.8-2              | 184/166              | 9/30/98                         |
| 3.2.1-1              | 184/166              | 9/30/98                         |
| 3.2.1-2              | 184/166              | 9/30/98                         |
| 3.2.1-3              | 184/166              | 9/30/98                         |
| 3.2.1-4              | 188/169              | 9/22/99                         |
| 3.2.1-5              | 188/169              | 9/22/99                         |
| 3.2.2-1              | 184/166              | 9/30/98                         |

• •

| Page Number<br>3.2.2-2 | Amendment<br>184/166 | Revision Date<br>9/30/98 |
|------------------------|----------------------|--------------------------|
| 3.2.2-3                | 184/166              | 9/30/98                  |
| 3.2.2-4                | 188/169              | 9/22/99                  |
| 3.2.3-1                | 184/166              | 9/30/98                  |
| 3.2.4-1                | 184/166              | 9/30/98                  |
| 3.2.4-2                | 184/166              | 9/30/98                  |
| 3.2.4-3                | 184/166              | 9/30/98                  |
| 3.2.4-4                | 184/166              | 9/30/98                  |
| 3.3.1-1                | 184/166              | 9/30/98                  |
| 3.3.1-2                | 184/166              | 9/30/98                  |
| 3.3.1-3                | 184/166              | 9/30/98                  |
| 3.3.1-4                | 184/166              | 9/30/98                  |
| 3.3.1-5                | 184/166              | 9/30/98                  |
| 3.3.1-6                | 184/166              | 9/30/98                  |
| 3.3.1-7                | 184/166              | 9/30/98                  |
| 3.3.1-8                | 184/166              | 9/30/98                  |
| 3.3.1-9                | 184/166              | 9/30/98                  |
| 3.3.1-10               | 184/166              | 9/30/98                  |
| 3.3.1-11               | 184/166              | 9/30/98                  |
| 3.3.1-12               | 184/166              | 9/30/98                  |
| 3.3.1-13               | 184/166              | 9/30/98                  |
| 3.3.1-14               | 194/175              | 9/18/00                  |
| 3.3.1-15               | 194/175              | 9/18/00                  |
| 3.3.1-16               | 194/175              | 9/18/00                  |
| 3.3.1-17               | 194/175              | 9/18/00                  |
| 3.3.1-18               | 194/175              | 9/18/00                  |
| 3.3.1-19               | 194/175              | 9/18/00                  |
| 3.3.1-20               | 184/166              | 9/30/98                  |
| 3.3.2-1                | 184/166              | 9/30/98                  |
| 3.3.2-2                | 184/166              | 9/30/98                  |
| 3.3.2-3                | 184/166              | 9/30/98                  |
| 3.3.2-4                | 184/166              | 9/30/98                  |
| 3.3.2-5                | 184/166              | 9/30/98                  |

| Amendment<br>198/179 | Revision Date<br>4/12/01                                                                                                                                                                                                                                                                                                                                                                                 |
|----------------------|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| 198/179              | 4/12/01                                                                                                                                                                                                                                                                                                                                                                                                  |
| 184/166              | 9/30/98                                                                                                                                                                                                                                                                                                                                                                                                  |
| 184/166              | 9/30/98                                                                                                                                                                                                                                                                                                                                                                                                  |
| 194/175              | 9/18/00                                                                                                                                                                                                                                                                                                                                                                                                  |
| 194/175              | 9/18/00                                                                                                                                                                                                                                                                                                                                                                                                  |
| 194/175              | 9/18/00                                                                                                                                                                                                                                                                                                                                                                                                  |
| 198/179              | 4/12/01                                                                                                                                                                                                                                                                                                                                                                                                  |
| 194/175              | 9/18/00                                                                                                                                                                                                                                                                                                                                                                                                  |
| 184/166              | 9/30/98                                                                                                                                                                                                                                                                                                                                                                                                  |
| 184/166              | 9/30/98                                                                                                                                                                                                                                                                                                                                                                                                  |
| 184/166              | 9/30/98                                                                                                                                                                                                                                                                                                                                                                                                  |
| 184/166              | 9/30/98                                                                                                                                                                                                                                                                                                                                                                                                  |
| 184/166              | 9/30/98                                                                                                                                                                                                                                                                                                                                                                                                  |
| 184/166              | 9/30/98                                                                                                                                                                                                                                                                                                                                                                                                  |
| 184/166              | 9/30/98                                                                                                                                                                                                                                                                                                                                                                                                  |
| 184/166              | 9/30/98                                                                                                                                                                                                                                                                                                                                                                                                  |
| 184/166              | 9/30/98                                                                                                                                                                                                                                                                                                                                                                                                  |
| 194/175              | 9/18/00                                                                                                                                                                                                                                                                                                                                                                                                  |
| 184/166              | 9/30/98                                                                                                                                                                                                                                                                                                                                                                                                  |
| 184/166              | 9/30/98                                                                                                                                                                                                                                                                                                                                                                                                  |
| 194/175              | 9/18/00                                                                                                                                                                                                                                                                                                                                                                                                  |
| 191/172              | 3/20/00                                                                                                                                                                                                                                                                                                                                                                                                  |
| 191/175              | 3/20/00                                                                                                                                                                                                                                                                                                                                                                                                  |
| 184/166              | 9/30/98                                                                                                                                                                                                                                                                                                                                                                                                  |
| 191/172              | 3/20/00                                                                                                                                                                                                                                                                                                                                                                                                  |
| 184/166              | 9/30/98                                                                                                                                                                                                                                                                                                                                                                                                  |
| 184/166              | 9/30/98                                                                                                                                                                                                                                                                                                                                                                                                  |
| 184/166              | 9/30/98                                                                                                                                                                                                                                                                                                                                                                                                  |
| 184/166              | 9/30/98                                                                                                                                                                                                                                                                                                                                                                                                  |
| 184/166              | 9/30/98                                                                                                                                                                                                                                                                                                                                                                                                  |
| 184/166              | 9/30/98                                                                                                                                                                                                                                                                                                                                                                                                  |
| 184/166              | 9/30/98                                                                                                                                                                                                                                                                                                                                                                                                  |
|                      | 198/179198/179184/166184/166194/175194/175194/175198/179194/175184/166184/166184/166184/166184/166184/166184/166184/166184/166184/166184/166184/166184/166194/175184/166184/166184/166191/172191/172191/172184/166184/166184/166184/166184/166184/166184/166184/166184/166184/166184/166184/166184/166184/166184/166184/166184/166184/166184/166184/166184/166184/166184/166184/166184/166184/166184/166 |

| Page Number<br>3.4.4-1 | Amendment<br>184/166 | Revision Date<br>9/30/98 |
|------------------------|----------------------|--------------------------|
| 3.4.5-1                | 184/166              | 9/30/98                  |
| 3.4.5-2                | 184/166              | 9/30/98                  |
| 3.4.5-3                | 184/166              | 9/30/98                  |
| 3.4.6-1                | 184/166              | 9/30/98                  |
| 3.4.6-2                | 184/166              | 9/30/98                  |
| 3.4.7-1                | 184/166              | 9/30/98                  |
| 3.4.7-2                | 184/166              | 9/30/98                  |
| 3.4.8-1                | 184/166              | 9/30/98                  |
| 3.4.8-2                | 184/166              | 9/30/98                  |
| 3.4.9-1                | 184/166              | 9/30/98                  |
| 3.4.9-2                | 184/166              | 9/30/98                  |
| 3.4.10-1               | 184/166              | 9/30/98                  |
| 3.4.10-2               | 184/166              | 9/30/98                  |
| 3.4-11-1               | 184/166              | 9/30/98                  |
| 3.4.11-2               | 184/166              | 9/30/98                  |
| 3.4-11-3               | 184/166              | 9/30/98                  |
| 3.4.11-4               | 184/166              | 9/30/98                  |
| 3.4.12-1               | 184/166              | 9/30/98                  |
| 3.4.12-2               | 184/166              | 9/30/98                  |
| 3.4.12-3               | 184/166              | 9/30/98                  |
| 3.4.12-4               | 184/166              | 9/30/98                  |
| 3.4.12-5               | 184/166              | 9/30/98                  |
| 3.4.12-6               | 184/166              | 9/30/98                  |
| 3.4.13-1               | 184/166              | 9/30/98                  |
| 3.4.13-2               | 184/166              | 9/30/98                  |
| 3.4.14-1               | 184/166              | 9/30/98                  |
| 3.4.14-2               | 184/166              | 9/30/98                  |
| 3.4.14-3               | 184/166              | 9/30/98                  |
| 3.4.14-4               | 184/166              | 9/30/98                  |
| 3.4.15-1               | 184/166              | 9/30/98                  |
| 3.4.15-2               | 184/166              | 9/30/98                  |
| 3.4.15-3               | 184/166              | 9/30/98                  |

| Page Number<br>3.6.6-1 | Amendment<br>184/166 | Revision Date<br>9/30/98 |
|------------------------|----------------------|--------------------------|
| 3.6.6-2                | 184/166              | 9/30/98                  |
| 3.6.7-1                | 184/166              | 9/30/98                  |
| 3.6.7-2                | 184/166              | 9/30/98                  |
| 3.6.8-1                | 184/166              | 9/30/98                  |
| 3.6.8-2                | 184/166              | 9/30/98                  |
| 3.6.9-1                | 184/166              | 9/30/98                  |
| 3.6.9-2                | 184/166              | 9/30/98                  |
| 3.6.10-1               | 184/166              | 9/30/98                  |
| 3.6.10-2               | 184/166              | 9/30/98                  |
| 3.6.11-1               | 184/166              | 9/30/98                  |
| 3.6.11-2               | 184/166              | 9/30/98                  |
| 3.6.12-1               | 184/166              | 9/30/98                  |
| 3.6.12-2               | 201/182              | 3/13/02                  |
| 3.6.12-3               | 201/182              | 3/13/02                  |
| 3.6.13-1               | 184/166              | 9/30/98                  |
| 3.6.13-2               | 184/166              | 9/30/98                  |
| 3.6.13-3               | 184/166              | 9/30/98                  |
| 3.6.14-1               | 184/166              | 9/30/98                  |
| 3.6.14-2               | 184/166              | 9/30/98                  |
| 3.6.14-3               | 184/166              | 9/30/98                  |
| 3.6.15-1               | 184/166              | 9/30/98                  |
| 3.6.15-2               | 184/166              | 9/30/98                  |
| 3.6.16-1               | 184/166              | 9/30/98                  |
| 3.6.16-2               | 184/166              | 9/30/98                  |
| 3.7.1-1                | 184/166              | 9/30/98                  |
| 3.7.1-2                | 184/166              | 9/30/98                  |
| 3.7.1-3                | 184/166              | 9/30/98                  |
| 3.7.2-1                | 184/166              | 9/30/98                  |
| 3.7.2-2                | 184/166              | 9/30/98                  |
| 3.7.3-1                | 184/166              | 9/30/98                  |
| 3.7.3-2                | 184/166              | 9/30/98                  |
| 3.7.4-1                | 184/166              | 9/30/98                  |

. .

.

| Page Number<br>3.7.4-2 | Amendment<br>184/166 | Revision Date<br>9/30/98 |
|------------------------|----------------------|--------------------------|
| 3.7.5-1                | 184/166              | 9/30/98                  |
| 3.7.5-2                | 184/166              | 9/30/98                  |
| 3.7.5-3                | 184/166              | 9/30/98                  |
| 3.7.5-4                | 184/166              | 9/30/98                  |
| 3.7.6-1                | 184/166              | 9/30/98                  |
| 3.7.6-2                | 184/166              | 9/30/98                  |
| 3.7.7-1                | 184/166              | 9/30/98                  |
| 3.7.7-2                | 184/166              | 9/30/98                  |
| 3.7.8-1                | 184/166              | 9/30/98                  |
| 3.7.8-2                | 184/166              | 9/30/98                  |
| 3.7.9-1                | 187/168              | 9/22/99                  |
| 3.7.9-2                | 187/168              | 9/22/99                  |
| 3.7.9-3                | 184/166              | 9/30/98                  |
| 3.7.10-1               | 184/166              | 9/30/98                  |
| 3.7.10-2               | 184/166              | 9/30/98                  |
| 3.7.11-1               | 184/166              | 9/30/98                  |
| 3.7.11-2               | 184/166              | 9/30/98                  |
| 3.7.12-1               | 184/166              | 9/30/98                  |
| 3.7.12-2               | 184/166              | 9/30/98                  |
| 3.7.13-1               | 184/166              | 9/30/98                  |
| 3.7.14-1               | 184/166              | 9/30/98                  |
| 3.7.15-1               | 197/178              | 11/27/00                 |
| 3.7.15-2               | 197/178              | 11/27/00                 |
| 3.7.15-3               | 197/178              | 11/27/00                 |
| 3.7.15-4               | 197/178              | 11/27/00                 |
| 3.7.15-5               | 197/178              | 11/27/00                 |
| 3.7.15-6               | 197/178              | 11/27/00                 |
| 3.7.15-7               | 197/178              | 11/27/00                 |
| 3.7.15-8               | 197/178              | 11/27/00                 |
| 3.7.15-9               | 197/178              | 11/27/00                 |
| 3.7.15-10              | 197/178              | 11/27/00                 |
| 3.7.15-11              | 197/178              | 11/27/00                 |

-

| Page Number<br>3.7.15-12 | Amendment<br>197/178 | Revision Date<br>11/27/00 |
|--------------------------|----------------------|---------------------------|
| 3.7.15-13                | 197/178              | 11/27/00                  |
| 3.7.15-14                | 197/178              | 11/27/00                  |
| 3.7.15-15                | 197/178              | 11/27/00                  |
| 3.7.15-16                | 197/178              | 11/27/00                  |
| 3.7.15-17                | 197/178              | 11/27/00                  |
| 3.7.15-18                | 197/178              | 11/27/00                  |
| 3.7.15-19                | 197/178              | 11/27/00                  |
| 3.7.15-20                | 197/178              | 11/27/00                  |
| 3.7.15-21                | 197/178              | 11/27/00                  |
| 3.7.16-1                 | 184/166              | 9/30/98                   |
| 3.8.1-1                  | 184/166              | 9/30/98                   |
| 3.8.1-2                  | 184/166              | 9/30/98                   |
| 3.8.1-3                  | 184/166              | 9/30/98                   |
| 3.8.1-4                  | 184/166              | 9/30/98                   |
| 3.8.1-5                  | 184/166              | 9/30/98                   |
| 3.8.1-6                  | 184/166              | 9/30/98                   |
| 3.8.1-7                  | 184/166              | 9/30/98                   |
| 3.8.1-8                  | 192/173              | 3/15/00                   |
| 3.8.1-9                  | 184/166              | 9/30/98                   |
| 3.8.1-10                 | 184/166              | 9/30/98                   |
| 3.8.1-11                 | 192/173              | 3/15/00                   |
| 3.8.1-12                 | 184/166              | 9/30/98                   |
| 3.8.1-13                 | 184/166              | 9/30/98                   |
| 3.8.1-14                 | 184/166              | 9/30/98                   |
| 3.8.1-15                 | 184/166              | 9/30/98                   |
| 3.8.2-1                  | 184/166              | 9/30/98                   |
| 3.8.2-2                  | 184/166              | 9/30/98                   |
| 3.8.2-3                  | 184/166              | 9/30/98                   |
| 3.8.3-1                  | 184/166              | 9/30/98                   |
| 3.8.3-2                  | 184/166              | 9/30/98                   |
| 3.8.3-3                  | 184/166              | 9/30/98                   |
| 3.8.4-1                  | 184/166              | 9/30/98                   |

-

| Page Number<br>3.8.4-2 | Amendment<br>184/166 | Revision Date<br>9/30/98 |
|------------------------|----------------------|--------------------------|
| 3.8.4-3                | 184/166              | 9/30/98                  |
| 3.8.5-1                | 184/166              | 9/30/98                  |
| 3.8.5-2                | 184/166              | 9/30/98                  |
| 3.8.6-1                | 184/166              | 9/30/98                  |
| 3.8.6-2                | 184/166              | 9/30/98                  |
| 3.8.6-3                | 184/166              | 9/30/98                  |
| 3.8.6-4                | 184/166              | 9/30/98                  |
| 3.8.7-1                | 184/166              | 9/30/98                  |
| 3.8.8-1                | 184/166              | 9/30/98                  |
| 3.8.8-2                | 184/166              | 9/30/98                  |
| 3.8.9-1                | 184/166              | 9/30/98                  |
| 3.8.9-2                | 184/166              | 9/30/98                  |
| 3.8.10-1               | 184/166              | 9/30/98                  |
| 3.8.10-2               | 184/166              | 9/30/98                  |
| 3.9.1-1                | 184/166              | 9/30/98                  |
| 3.9.2-1                | 184/166              | 9/30/98                  |
| 3.9.3-1                | 184/166              | 9/30/98                  |
| 3.9.3-2                | 184/166              | 9/30/98                  |
| 3.9.4-1                | 184/166              | 9/30/98                  |
| 3.9.4-2                | 184/166              | 9/30/98                  |
| 3.9.5-1                | 184/166              | 9/30/98                  |
| 3.9.5-2                | 184/166              | 9/30/98                  |
| 3.9.6-1                | 184/166              | 9/30/98                  |
| 3.9.6-2                | 184/166              | 9/30/98                  |
| 3.9.7-1                | 184/166              | 9/30/98                  |
| 4.0.1                  | 197/178              | 11/27/00                 |
| 4.0.2                  | 197/178              | 11/27/00                 |
| 5. <b>1-1</b>          | 184/166              | 9/30/98                  |
| 5.2-1                  | 184/166              | 9/30/98                  |
| 5.2-2                  | 184/166              | 9/30/98                  |
| 5.2-3                  | 184/166              | 9/30/98                  |
| 5.3-1                  | 184/166              | 9/30/98                  |

| Page Number<br>5.4-1 | Amendment<br>184/166 | Revision Date<br>9/30/98 |
|----------------------|----------------------|--------------------------|
| 5.5-1                | 184/166              | 9/30/98                  |
| 5.5-2                | 199/180              | 1/15/02                  |
| 5.5-3                | 184/166              | 9/30/98                  |
| 5.5-4                | 184/166              | 9/30/98                  |
| 5.5-5                | 190/171              | 12/21/99                 |
| 5.5-6                | 184/166              | 9/30/98                  |
| 5.5-7                | 184/166              | 9/30/98                  |
| 5.5-8                | 184/166              | 9/30/98                  |
| 5.5-9                | 184/166              | 9/30/98                  |
| 5.5-10               | 184/166              | 9/30/98                  |
| 5.5-11               | 184/166              | 9/30/98                  |
| 5.5-12               | 184/166              | 9/30/98                  |
| 5.5-13               | 184/166              | 9/30/98                  |
| 5.5-14               | 196/177              | 11/2/00                  |
| 5.5-15               | 184/166              | 9/30/98                  |
| 5.5-16               | 184/166              | 9/30/98                  |
| 5.5-17               | 184/166              | 9/30/98                  |
| 5.5-18               | 184/166              | 9/30/98                  |
| 5.6-1                | 184/166              | 9/30/98                  |
| 5.6-2                | 184/166              | 9/30/98                  |
| 5.6-3                | 188/169              | 9/22/99                  |
| 5.6-4                | 195/176              | 9/22/00                  |
| 5.6-5                | 184/166              | 9/30/98                  |
| 5.7-1                | 184/166              | 9/30/98                  |
| 5.7-2                | 184/166              | 9/30/98                  |
|                      |                      |                          |

# (Revised per section)

| i       | Revision 0 | 9/30/98 |
|---------|------------|---------|
| ii      | Revision 0 | 9/30/98 |
| iii     | Revision 0 | 9/30/98 |
| B 2.1.1 | Revision 0 | 9/30/98 |

• •

| Page Number<br>B 3.4.14 | Amendment<br>Revision 0 | Revision Date<br>9/30/98 |
|-------------------------|-------------------------|--------------------------|
| B 3.4.15                | Revision 0              | 9/30/98                  |
| B 3.4.16                | Revision 0              | 9/30/98                  |
| B 3.4.17                | Revision 0              | 9/30/98                  |
| B 3.5.1                 | <b>Revision 30</b>      | 8/13/02                  |
| B 3.5.2                 | Revision 10             | 9/22/00                  |
| B 3.5.3                 | Revision 0              | 9/30/98                  |
| B 3.5.4                 | Revision 0              | 9/30/98                  |
| B 3.5.5                 | Revision 0              | 9/30/98                  |
| B 3.6.1                 | Revision 0              | 9/30/98                  |
| B 3.6.2                 | Revision 17             | 10/08/01                 |
| B 3.6.3                 | Revision 18             | 10/23/01                 |
| B 3.6.4                 | Revision 0              | 9/30/98                  |
| B 3.6.5                 | Revision 0              | 9/30/98                  |
| B 3.6.6                 | Revision 0              | 9/30/98                  |
| B 3.6.7                 | Revision 0              | 9/30/98                  |
| B 3.6.8                 | Revision 0              | 9/30/98                  |
| B 3.6.9                 | Revision 0              | 9/30/98                  |
| B 3.6.10                | Revision 0              | 9/30/98                  |
| B 3.6.11                | Revision 0              | 9/30/98                  |
| B 3.6.12                | Revision 25             | 3/13/02                  |
| B 3.6.13                | Revision 0              | 9/30/98                  |
| B 3.6.14                | Revision 0              | 9/30/98                  |
| B 3.6.15                | Revision 0              | 9/30/98                  |
| B 3.6.16                | Revision 0              | 9/30/98                  |
| B 3.7.1                 | Revision 0              | 9/30/98                  |
| B 3.7.2                 | Revision 0              | 9/30/98                  |
| B 3.7.3                 | Revision 0              | 9/30/98                  |
| B 3.7.4                 | Revision 0              | 9/30/98                  |
| B 3.7.5                 | Revision 0              | 9/30/98                  |
| B 3.7.6                 | Revision 0              | 9/30/98                  |
| B 3.7.7                 | Revision 0              | 9/30/98                  |
| B 3.7.8                 | Revision 0              | 9/30/98                  |
|                         |                         |                          |

# ATTACHMENT 2

~ ·

•

# REVISED TECHNICAL SPECIFICATION BASES 3.4.12, 3.5.1

#### B 3.4 REACTOR COOLANT SYSTEM (RCS)

#### B 3.4.12 Low Temperature Overpressure Protection (LTOP) System

# BASES BACKGROUND The LTOP System controls RCS pressure at low temperatures so the integrity of the reactor coolant pressure boundary (RCPB) is not compromised by violating the pressure and temperature (P/T) limits of 10 CFR 50, Appendix G (Ref. 1). The reactor vessel is the limiting RCPB component for demonstrating such protection. This specification provides the maximum allowable actuation logic setpoints for the power operated relief valves (PORVs) and LCO 3.4.3, "RCS Pressure and Temperature (P/T) Limits," provides the maximum RCS pressure for the existing RCS cold leg temperature during cooldown, shutdown, and heatup to meet the Reference 1 requirements during the LTOP MODES. The reactor vessel material is less tough at low temperatures than at normal operating temperature. As the vessel neutron exposure accumulates, the material toughness decreases and becomes less resistant to pressure stress at low temperatures (Ref. 2). RCS pressure, therefore, is maintained low at low temperatures and is increased only as temperature is increased. The potential for vessel overpressurization is most acute when the RCS is water solid, occurring only while shutdown; a pressure fluctuation can occur more quickly than an operator can react to relieve the condition. Exceeding the RCS P/T limits by a significant amount could cause brittle cracking of the reactor vessel. LCO 3.4.3 requires administrative control of RCS pressure and temperature during heatup and cooldown to prevent exceeding the specified limits. This LCO provides RCS overpressure protection by having a minimum coolant input capability and having adequate pressure relief capacity. Limiting coolant input capability requires all but one centrifugal charging pump or one safety injection pump incapable of injection into the RCS and isolating the accumulators. The pressure relief capacity requires either two redundant PORVs or a depressurized RCS and an RCS vent of sufficient size. One PORV or the open RCS vent is the overpressure protection device that acts to terminate an increasing pressure event. With minimum coolant input capability, the ability to provide core coolant addition is restricted. The LCO does not require the makeup control

#### BACKGROUND (continued)

system deactivated or the safety injection (SI) actuation circuits blocked. Due to the lower pressures in the LTOP MODES and the expected core decay heat levels, the makeup system can provide adequate flow via the makeup control valve. If conditions require the use of more than one centrifugal charging pump for makeup in the event of loss of inventory, then pumps can be made available through manual actions.

#### **PORV Requirements**

As designed for the LTOP System, each PORV is signaled to open if the RCS pressure reaches 385 psig when the PORVS are in the "lo-press" mode of operation. If the PORVs are being used to meet the requirements of this specification, then RCS cold leg temperature is limited in accordance with the LTOP analysis. For cases where no reactor coolant pumps are in operation, this temperature limit is met by monitoring of BOTH the Wide Range Cold Leg temperatures and Residual Heat Removal Heat Exchanger discharge temperature. These temperatures are the most representative of the fluid in the reactor vessel downcomer region. The LTOP actuation logic monitors both RCS temperature and RCS pressure. The signals used to generate the pressure setpoints originate from the safety related narrow range pressure transmitters. The signals used to generate the temperature permissives originate from the wide range RTDs on cold leg C and hot leg D. Each signal is input to the appropriate NSSS protection system cabinet where it is converted to an internal signal and then input to a comparator to generate an actuation signal. If the indicated pressure meets or exceeds the bistable setpoint, a PORV is signaled to open.

This Specification presents the PORV setpoints for LTOP. Having the setpoints of both valves within the limits ensures that the Reference 1 limits will not be exceeded in any analyzed event.

When a PORV is opened in an increasing pressure transient, the release of coolant will cause the pressure increase to slow and reverse. As the PORV releases coolant, the RCS pressure decreases until a reset pressure is reached and the valve is signaled to close. The pressure continues to decrease below the reset pressure as the valve closes.

#### **RCS Vent Requirements**

Once the RCS is depressurized, a vent exposed to the containment atmosphere will maintain the RCS at containment ambient pressure in an RCS overpressure transient, if the relieving requirements of the transient do not exceed the capabilities of the vent. Thus, the vent path must be

#### BACKGROUND (continued)

capable of relieving the flow resulting from the limiting LTOP mass or heat input transient, and maintaining pressure below the P/T limits. The required vent capacity may be provided by one or more vent paths.

The vent path(s) must be above the level of reactor coolant, so as not to drain the RCS when open.

APPLICABLE Safety analyses (Ref. 4) demonstrate that the reactor vessel is SAFETY ANALYSES adequately protected against exceeding the Reference 1 P/T limits. In MODES 1, 2, and 3, and in MODE 4 with RCS cold leg temperature exceeding 300°F, the pressurizer safety valves will prevent RCS pressure from exceeding the Reference 1 limits. At about 300°F and below, overpressure prevention falls to two OPERABLE PORVs or to a depressurized RCS and a sufficient sized RCS vent. Each of these means has a limited overpressure relief capability.

> The actual temperature at which the pressure in the P/T limit curve falls below the pressurizer safety valve setpoint increases as the reactor vessel material toughness decreases due to neutron embrittlement. Each time the P/T curves are revised, the LTOP System must be re-evaluated to ensure its functional requirements can still be met using the PORV method or the depressurized and vented RCS condition.

> Any change to the RCS must be evaluated against the Reference 4 analyses to determine the impact of the change on the LTOP acceptance limits.

Transients that are capable of overpressurizing the RCS are categorized as either mass or heat input transients, examples of which follow:

Mass Input Type Transients

- a. Inadvertent safety injection; or
- b. Charging/letdown flow mismatch.

Heat Input Type Transients

- a. Inadvertent actuation of pressurizer heaters;
- b. Loss of RHR cooling; or

# APPLICABLE SAFETY ANALYSES (continued)

c. Reactor coolant pump (RCP) startup with temperature asymmetry within the RCS or between the RCS and steam generators.

The following are required during the LTOP MODES to ensure that mass and heat input transients do not occur, which either of the LTOP overpressure protection means cannot handle:

- a. Rendering all but one centrifugal charging pump or one safety injection pump incapable of injection;
- b. Deactivating the accumulator discharge isolation valves in their closed positions; and
- c. Disallowing start of an RCP if secondary temperature is more than 50°F above primary temperature in any one loop. LCO 3.4.6, "RCS Loops—MODE 4," and LCO 3.4.7, "RCS Loops—MODE 5, Loops Filled," provide this protection.

The Reference 4 analyses demonstrate that either one PORV or the depressurized RCS and RCS vent can maintain RCS pressure below limits when only one centrifugal charging pump or one safety injection pump are actuated. Thus, the LCO allows only one centrifugal charging pump or one safety injection pump OPERABLE during the LTOP MODES. Since neither one PORV nor the RCS vent can handle the pressure transient from accumulator injection when RCS temperature is low the LCO also requires the accumulators isolation when accumulator pressure is greater than or equal to the maximum RCS pressure for the existing RCS cold leg temperature allowed in LCO 3.4.3.

The isolated accumulators must have their discharge valves closed and power removed.

Fracture mechanics analyses established the temperature of LTOP Applicability at 300°F.

The consequences of a small break loss of coolant accident (LOCA) in LTOP MODE 4 conform to 10 CFR 50.46 and 10 CFR 50, Appendix K (Refs. 5 and 6), requirements by having a maximum of one centrifugal charging pump OPERABLE and SI actuation enabled.

#### APPLICABLE SAFETY ANALYSES (continued)

#### PORV Performance

The fracture mechanics analyses show that the vessel is protected when the PORVs are set to open at or below the specified limit. The setpoints are derived by analyses that model the performance of the LTOP System, assuming the limiting LTOP transient of one centrifugal charging pump or one safety injection pump injecting into the RCS. These analyses consider pressure overshoot and undershoot beyond the PORV opening and closing, resulting from signal processing and valve stroke times. The PORV setpoints at or below the derived limit ensures the Reference 1 P/T limits will be met.

The PORV setpoints will be updated when the revised P/T limits conflict with the LTOP analysis limits. The P/T limits are periodically modified as the reactor vessel material toughness decreases due to neutron embrittlement caused by neutron irradiation. Revised limits are

determined using neutron fluence projections and the results of examinations of the reactor vessel material irradiation surveillance specimens. The Bases for LCO 3.4.3, "RCS Pressure and Temperature (P/T) Limits," discuss these examinations.

The PORVs are considered active components. Thus, the failure of one PORV is assumed to represent the worst case, single active failure.

#### **RCS Vent Performance**

With the RCS depressurized, analyses show a vent size of 2.75 square inches is capable of mitigating the allowed LTOP overpressure transient. The capacity of a vent this size is greater than the flow of the limiting transient for the LTOP configuration, one centrifugal charging pump or one safety injection pump OPERABLE, maintaining RCS pressure less than the maximum pressure on the P/T limit curve.

The RCS vent size will be re-evaluated for compliance each time the P/T limit curves are revised based on the results of the vessel material surveillance.

The RCS vent is passive and is not subject to active failure.

The LTOP System satisfies Criterion 2 of 10 CFR 50.36 (Ref. 7).

| BASES         | · · · · · · · · · · · · · · · · · · ·                                                                                                                                                                                                                                                                                                                                                          |
|---------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| LCO           | This LCO requires that the LTOP System is OPERABLE. The LTOP<br>System is OPERABLE when the minimum coolant input and pressure<br>relief capabilities are OPERABLE. Violation of this LCO could lead to the<br>loss of low temperature overpressure mitigation and violation of the<br>Reference 1 limits as a result of an operational transient.                                             |
|               | To limit the coolant input capability, the LCO permits a maximum of one centrifugal charging pump or one safety injection pump capable of injecting into the RCS and requires all accumulator discharge isolation valves closed and immobilized when accumulator pressure is greater than or equal to the maximum RCS pressure for the existing RCS cold leg temperature allowed in LCO 3.4.3. |
|               | The elements of the LCO that provide low temperature overpressure mitigation through pressure relief are:                                                                                                                                                                                                                                                                                      |
|               | a. Two OPERABLE PORVs (NC-32B and NC-34A); or                                                                                                                                                                                                                                                                                                                                                  |
|               | A PORV is OPERABLE for LTOP when its block valve is open, its lift setpoint is set to the specified limit and testing proves its automatic ability to open at this setpoint, and motive power is available to the valve and its control circuit.                                                                                                                                               |
|               | b. A depressurized RCS and an RCS vent.                                                                                                                                                                                                                                                                                                                                                        |
|               | An RCS vent is OPERABLE when open with an area of $\geq$ 2.75 square inches.                                                                                                                                                                                                                                                                                                                   |
|               | Each of these methods of overpressure prevention is capable of mitigating the limiting LTOP transient.                                                                                                                                                                                                                                                                                         |
| APPLICABILITY | This LCO is applicable in MODE 4 when any RCS cold leg temperature is $\leq$ 300°F, in MODE 5, and in MODE 6 when the reactor vessel head is on. The pressurizer safety valves provide overpressure protection that meets the Reference 1 P/T limits above 300°F. When the reactor vessel head is off, overpressurization cannot occur.                                                        |
|               | LCO 3.4.3 provides the operational P/T limits for all MODES.<br>LCO 3.4.10, "Pressurizer Safety Valves," requires the OPERABILITY of<br>the pressurizer safety valves that provide overpressure protection during<br>MODES 1, 2, and 3, and MODE 4 above 300°F.                                                                                                                                |
|               | Low temperature overpressure prevention is most critical during<br>shutdown when the RCS is water solid, and a mass or heat input<br>transient can cause a very rapid increase in RCS pressure when little or<br>no time allows operator action to mitigate the event.                                                                                                                         |

÷

.

# APPLICABILITY (continued)

The Applicability is modified by a Note stating that accumulator isolation is only required when the accumulator pressure is more than or at the maximum RCS pressure for the existing temperature, as allowed by the P/T limit curves. This Note permits the accumulator discharge isolation valve Surveillance to be performed only under these pressure and temperature conditions.

ACTIONS LCO 3.0.4 is not applicable for entry into LTOP operation.

A.1, A.2.1, A.2.2.1, A.2.2.2., A.3, and A.4

With two centrifugal charging pumps, safety injection pumps, or a combination of each, capable of injecting into the RCS, RCS overpressurization is possible.

To immediately initiate action to restore restricted coolant input capability to the RCS reflects the urgency of removing the RCS from this condition. Two pumps may be capable of injecting into the RCS provided the RHR suction relief valve is OPERABLE with the RCS cold leg temperature > 167°F or > 107°F and cooldown rate limited to 20°F, or if two PORVs are secured open with the associated block valves open and power removed, or with an RCS vent of 4.5 square inches. For cases where no reactor coolant pumps are in operation, RCS cold leg temperature limits are to be met by monitoring of BOTH the WR Cold Leg temperatures and Residual Heat Removal Heat Exchanger discharge temperature. With both PORVS and block valves secured open, or with an RCS vent of 4.5 square inches, there are no credible single failures to limit the flow relief capacity. For the RHR relief valve to be OPERABLE, the RHR suction isolation valves must be open and the relief valve setpoint at 450 psig consistent with the safety analysis. The RHR suction relief valves are spring loaded, bellows type water relief valves with pressure tolerances and accumulation limits established by Section III of the American Society of Mechanical Engineers (ASME) Code (Ref. 3) for Class 2 relief valves.

Required Action A.1 is modified by a Note that permits two centrifugal charging pumps capable of RCS injection for  $\leq$  15 minutes to allow for pump swaps.

# B.1, C.1, and C.2

An unisolated accumulator requires isolation within 1 hour. This is only required when the accumulator pressure is at or more than the maximum

McGuire Units 1 and 2

#### ACTIONS (continued)

RCS pressure for the existing temperature allowed by the P/T limit curves.

If isolation is needed and cannot be accomplished in 1 hour, Required Action C.1 and Required Action C.2 provide two options, either of which must be performed in the next 12 hours. By increasing the RCS temperature to > 300°F, an accumulator pressure of 639 psig cannot exceed the LTOP limits if the accumulators are fully injected. Depressurizing the accumulators below the LTOP limit also gives this protection.

The Completion Times are based on operating experience that these activities can be accomplished in these time periods and on engineering evaluations indicating that an event requiring LTOP is not likely in the allowed times.

#### <u>D.1</u>

In MODE 4 when any RCS cold leg temperature is  $\leq 300^{\circ}$ F, with one PORV inoperable, the PORV must be restored to OPERABLE status within a Completion Time of 7 days. Two PORVS are required to provide low temperature overpressure mitigation while withstanding a single failure of an active component.

The Completion Time considers the facts that only one of the PORVs is required to mitigate an overpressure transient and that the likelihood of an active failure of the remaining valve path during this time period is very low.

# E.1 and E.2

The consequences of operational events that will overpressurize the RCS are more severe at lower temperature (Ref. 8). Thus, with one of the two PORVs inoperable in MODE 5 or in MODE 6 with the head on, all operations which could lead to a water solid pressurizer must be suspended immediately and the Completion Time to restore two valves to OPERABLE status is 24 hours.

The Completion Time represents a reasonable time to investigate and repair several types of relief valve failures without exposure to a lengthy period with only one OPERABLE PORV to protect against overpressure events.

#### ACTIONS (continued)

#### F.1 and F.2

If the Required Actions and associated Completion Times of Condition E are not met, then alternative actions are necessary to establish the required redundancy in relief capacity. This is accomplished by verifying that the RHR relief valve is OPERABLE and the RHR suction isolation valves open and the RCS cold leg temperature > 167°F. For cases where no reactor coolant pumps are in operation, RCS cold leg temperature limits are to be met by monitoring of BOTH the WR Cold Leg temperatures and Residual Heat Removal Heat Exchanger discharge temperature. The

Completion Time of 1 hour reflects the importance of restoring the required redundancy at lower RCS temperatures.

#### <u>G.1</u>

The RCS must be depressurized and a vent must be established within 8 hours when:

- a. Both required PORVs are inoperable; or
- b. A Required Action and associated Completion Time of Condition C, D, E, or F is not met; or
- c. The LTOP System is inoperable for any reason other than Condition A, B, C, D, E, or F.

The vent must be sized  $\geq$  2.75 square inches to ensure that the flow capacity is greater than that required for the worst case mass input transient reasonable during the applicable MODES. This action is needed to protect the RCPB from a low temperature overpressure event and a possible brittle failure of the reactor vessel.

The Completion Time considers the time required to place the plant in this Condition and the relatively low probability of an overpressure event during this time period due to increased operator awareness of administrative control requirements.

| SURVEILLANCE<br>REQUIREMENTS | SR 3.4.12.1 and SR 3.4.12.2                                                                                                                        |
|------------------------------|----------------------------------------------------------------------------------------------------------------------------------------------------|
|                              | To minimize the potential for a low temperature overpressure event by limiting the mass input capability, all but one centrifugal charging pump or |
|                              |                                                                                                                                                    |

McGuire Units 1 and 2

## SURVEILLANCE REQUIREMENTS (continued)

one safety injection pump are verified incapable of injecting into the RCS and the accumulator discharge isolation valves are verified closed and power removed (See Ref. 10).

The centrifugal charging pump and safety injection pump are rendered incapable of injecting into the RCS through removing the power from the pumps by racking the breakers out under administrative control. An alternate method of LTOP control may be employed using at least two independent means to prevent a pump start such that a single failure or single action will not result in an injection into the RCS. This may be accomplished through two valves in the discharge flow path being closed.

The Frequency of 12 hours is sufficient, considering other indications and alarms available to the operator in the control room, to verify the required status of the equipment.

#### SR 3.4.12.3

The RHR suction relief valve shall be demonstrated OPERABLE by verifying the RHR suction isolation valves are open and by testing it in accordance with the Inservice Testing Program. This Surveillance is only required to be performed if the RHR suction relief valve is being used to meet the Required Actions of this LCO.

The RHR suction valves are verified to be opened every 12 hours. The Frequency is considered adequate in view of other administrative controls such as valve status indications available to the operator in the control room that verify the RHR suction valves remain open.

The ASME Code, Section XI (Ref. 9), test per Inservice Testing Program verifies OPERABILITY by proving proper relief valve mechanical motion and by measuring and, if required, adjusting the lift setpoint.

#### SR 3.4.12.4

The RCS vent of  $\geq$  2.75 square inches is proven OPERABLE by verifying its open condition either:

- a. Once every 12 hours for a valve that cannot be locked.
- b. Once every 31 days for a valve that is locked, sealed, or secured in position. A removed pressurizer safety valve fits this category.

#### SURVEILLANCE REQUIREMENTS (continued)

The passive vent arrangement must only be open to be OPERABLE. This Surveillance is required to be performed if the vent is being used to satisfy the pressure relief requirements of the LCO 3.4.12b.

#### SR 3.4.12.5

The PORV block valve must be verified open every 72 hours to provide the flow path for each required PORV to perform its function when actuated. The valve must be remotely verified open in the main control room. This Surveillance is performed if the PORV satisfies the LCO.

The block valve is a remotely controlled, motor operated valve. The power to the valve operator is not required removed, and the manual operator is not required locked in the inactive position. Thus, the block valve can be closed in the event the PORV develops excessive leakage or does not close (sticks open) after relieving an overpressure situation.

The 72 hour Frequency is considered adequate in view of other administrative controls available to the operator in the control room, such as valve position indication, that verify that the PORV block valve remains open.

#### SR 3.4.12.6

Performance of a COT is required within 12 hours after decreasing RCS temperature to  $\leq$  300°F and every 31 days on each required PORV to verify and, as necessary, adjust its lift setpoint. The COT will verify the setpoint is within the allowed maximum limits. PORV actuation could depressurize the RCS and is not required.

The 12 hour Frequency considers the unlikelihood of a low temperature overpressure event during this time.

A Note has been added indicating that this SR is required to be met 12 hours after decreasing RCS cold leg temperature to  $\leq$  300°F. The test must be performed within 12 hours after entering the LTOP MODES.

#### SR 3.4.12.7

Performance of a CHANNEL CALIBRATION on each required PORV actuation channel is required every 18 months to adjust the whole channel so that it responds and the valve opens within the required range and accuracy to known input.

- REFERENCES 1. 10 CFR 50, Appendix G.
  - 2. Generic Letter 88-11.
  - 3. ASME, Boiler and Pressure Vessel Code, Section III.
  - 4. UFSAR, Section 5.2.
  - 5. 10 CFR 50, Section 50.46.
  - 6. 10 CFR 50, Appendix K.
  - 7. 10 CFR 50.36, Technical Specifications, (c)(2)(ii).
  - 8. Generic Letter 90-06.
  - 9. ASME, Boiler and Pressure Vessel Code, Section XI.
  - 10. Duke letter to NRC, "Cold Leg Accumulator Isolation Valves", dated September 8, 1987.

# B 3.5 EMERGENCY CORE COOLING SYSTEMS (ECCS)

#### B 3.5.1 Accumulators

# BASES The functions of the ECCS accumulators are to supply water to the BACKGROUND reactor vessel during the blowdown phase of a loss of coolant accident (LOCA), to provide inventory to help accomplish the refill phase that follows thereafter, and to provide Reactor Coolant System (RCS) makeup for a small break LOCA. The blowdown phase of a large break LOCA is the initial period of the transient during which the RCS departs from equilibrium conditions, and heat from fission product decay, hot internals, and the vessel continues to be transferred to the reactor coolant. The blowdown phase of the transient ends when the RCS pressure falls to a value approaching that of the containment atmosphere. In the refill phase of a LOCA, which immediately follows the blowdown phase, reactor coolant inventory has vacated the core through steam flashing and ejection out through the break. The core is essentially in adiabatic heatup. The balance of accumulator inventory is then available to help fill voids in the lower plenum and reactor vessel downcomer so as to establish a recovery level at the bottom of the core and ongoing reflood of the core with the addition of safety injection (SI) water. The accumulators are pressure vessels partially filled with borated water and pressurized with nitrogen gas. The accumulators are passive components, since no operator or control actions are required in order for them to perform their function. Internal accumulator tank pressure is sufficient to discharge the accumulator contents to the RCS, if RCS pressure decreases below the accumulator pressure. Each accumulator is piped into an RCS cold leg via an accumulator line

Each accumulator is piped into an RCS cold leg via an accumulator line and is isolated from the RCS by a motor operated isolation valve and two check valves in series. The motor operated isolation valves are interlocked by P-11 with the pressurizer pressure measurement channels to ensure that the valves will automatically open as RCS pressure increases to above the permissive circuit P-11 setpoint.

This interlock also prevents inadvertent closure of the valves during normal operation prior to an accident. The valves will automatically open, however, as a result of an SI signal. The isolation valves between the accumulators and the Reactor Coolant System are required to be open

#### BACKGROUND (continued)

and power removed during unit operation. In that the subject valves are normally open and do not serve as an active device during a LOCA, the requirements of the Institute of Electrical and Electronic Engineers (IEEE) Standard 279-1971 (Ref. 1) is not applicable in this situation. Therefore, the subject valve control circuit is not designed to this standard.

The accumulator size, water volume, and nitrogen cover pressure are selected so that three of the four accumulators are sufficient to partially cover the core before significant clad melting or zirconium water reaction can occur following a LOCA. The need to ensure that three accumulators are adequate for this function is consistent with the LOCA assumption that the entire contents of one accumulator will be lost via the RCS pipe break during the blowdown phase of the LOCA.

APPLICABLE The accumulators are assumed OPERABLE in both the large and SAFETY ANALYSES small break LOCA analyses at full power (Ref. 2). These are the Design Basis Accidents (DBAs) that establish the acceptance limits for the accumulators. Reference to the analyses for these DBAs is used to assess changes in the accumulators as they relate to the acceptance limits.

> In performing the LOCA calculations, conservative assumptions are made concerning the availability of ECCS flow. In the early stages of a LOCA, with or without a loss of offsite power, the accumulators provide the sole source of makeup water to the RCS. The assumption of loss of offsite power is required by regulations and conservatively imposes a delay wherein the ECCS pumps cannot deliver flow until the emergency diesel generators start, come to rated speed, and go through their timed loading sequence. In cold leg break scenarios, the entire contents of one accumulator are assumed to be lost through the break.

> The limiting large break LOCA is a double ended guillotine break at the discharge of the reactor coolant pump. During this event, the accumulators discharge to the RCS as soon as RCS pressure decreases to below accumulator pressure.

As a conservative estimate, no credit is taken for ECCS pump flow until an effective delay has elapsed. This delay accounts for the diesels starting, the valves opening, and the pumps being loaded and delivering full flow. The delay time is conservatively set with an additional 2 seconds to account for SI signal generation. During this time, the accumulators are analyzed as providing the sole source of emergency core cooling. No operator action is assumed during the blowdown stage of a large break LOCA.

# APPLICABLE SAFETY ANALYSES (continued)

The worst case small break LOCA analyses also assume a time delay before pumped flow reaches the core. For the larger range of small breaks, the rate of blowdown is such that the increase in fuel clad temperature is terminated solely by the accumulators, with pumped flow then providing continued cooling. As break size decreases, the accumulators, safety injection pumps, and centrifugal charging pumps all play a part in terminating the rise in clad temperature. As break size continues to decrease, the role of the accumulators continues to decrease until they are not required and the centrifugal charging pumps become solely responsible for terminating the temperature increase.

This LCO helps to ensure that the following acceptance criteria established for the ECCS by 10 CFR 50.46 (Ref. 3) will be met following a small break LOCA and there is a high probability that the criteria are met following a large break LOCA:

- a. Maximum fuel element cladding temperature is  $\leq$  2200°F;
- Maximum cladding oxidation is ≤ 0.17 times the total cladding thickness before oxidation;
- c. Maximum hydrogen generation from a zirconium water reaction is ≤ 0.01 times the hypothetical amount that would be generated if all of the metal in the cladding cylinders surrounding the fuel, excluding the cladding surrounding the plenum volume, were to react; and
- d. Core is maintained in a coolable geometry.

Since the accumulators discharge during the blowdown phase of a LOCA, they do not contribute directly to the long term cooling requirements of 10 CFR 50.46. However, the boron content of the accumulator water helps to maintain the reactor core subcritical after reflood, thereby eliminating fission heat as an energy source for which cooling must be provided.

For both the large and small break LOCA analyses, a nominal contained accumulator water volume is used. The contained water volume is the same as the deliverable volume for the accumulators, since the accumulators are emptied, once discharged. The large and small break LOCA analyses are performed with accumulator volumes that are consistent with the LOCA evaluation models. To allow for operating margin, values of  $\pm$  31.5 ft<sup>3</sup> are specified.

# APPLICABLE SAFETY ANALYSES (continued)

The minimum boron concentration setpoint is used in the post LOCA sump boron concentration calculation. The calculation is performed to assure reactor subcriticality in a post LOCA environment. Of particular

interest is the large break LOCA, since no credit is taken for control rod assembly insertion. A reduction in the accumulator minimum boron concentration would produce a subsequent reduction in the available containment sump concentration for post LOCA shutdown and an increase in the maximum sump pH. The maximum boron concentration is used in determining the cold leg to hot leg recirculation injection switchover time and minimum sump pH.

The large and small break LOCA analyses are performed with accumulator pressures that are consistent with the LOCA evaluation models. To allow for operating margin and accumulator design limits, a range from 585 psig to 639 psig is specified. The maximum nitrogen cover pressure limit prevents accumulator relief valve actuation, and ultimately preserves accumulator integrity.

The effects on containment mass and energy releases from the accumulators are accounted for in the appropriate analyses (Ref. 4). The accumulators satisfy Criterion 3 of 10 CFR 50.36 (Ref. 5).

LCO The LCO establishes the minimum conditions required to ensure that the accumulators are available to accomplish their core cooling safety function following a LOCA. Four accumulators are required to ensure that 100% of the contents of three of the accumulators will reach the core during a LOCA. This is consistent with the assumption that the contents of one accumulator spill through the break. If less than three accumulators are injected during the blowdown phase of a LOCA, the ECCS acceptance criteria of 10 CFR 50.46 (Ref. 3) could be violated.

For an accumulator to be considered OPERABLE, the isolation valve must be fully open, power removed above 1000 psig, and the limits established in the SRs for contained volume, boron concentration, and nitrogen cover pressure must be met. Additionally, the nitrogen and liquid volumes between accumulators must be physically separate. APPLICABILITY In MODES 1 and 2, and in MODE 3 with RCS pressure > 1000 psig, the accumulator OPERABILITY requirements are based on full power operation. Although cooling requirements decrease as power decreases, the accumulators are still required to provide core cooling as long as elevated RCS pressures and temperatures exist.

This LCO is only applicable at pressures > 1000 psig. At pressures  $\leq$  1000 psig, the rate of RCS blowdown is such that the ECCS pumps can provide adequate injection to ensure that peak clad temperature remains below the 10 CFR 50.46 (Ref. 3) limit of 2200°F for small break LOCAs and there is a high level of probability that the peak cladding temperature does not exceed 2200°F for large break LOCAs.

In MODE 3, with RCS pressure  $\leq$  1000 psig, and in MODES 4, 5, and 6, the accumulator motor operated isolation valves are closed to isolate the accumulators from the RCS. This allows RCS cooldown and depressurization without discharging the accumulators into the RCS or requiring depressurization of the accumulators.

#### ACTIONS

If the boron concentration of one accumulator is not within limits, it must be returned to within the limits within 72 hours. In this Condition, ability to maintain subcriticality or minimum boron precipitation time may be reduced. The boron in the accumulators contributes to the assumption that the combined ECCS water in the partially recovered core during the early reflooding phase of a large break LOCA is sufficient to keep that portion of the core subcritical. One accumulator below the minimum boron concentration limit, however, will have no effect on available ECCS water and an insignificant effect on core subcriticality during reflood. Boiling of ECCS water in the core during reflood concentrates boron in the saturated liquid that remains in the core. In addition, current analysis techniques demonstrate that the accumulators do not discharge following a large main steam line break for the plant. Even if they do discharge, their impact is minor and not a design limiting event. Thus, 72 hours is allowed to return the boron concentration to within limits.

## <u>B.1</u>

A.1

If one accumulator is inoperable for a reason other than boron concentration, the accumulator must be returned to OPERABLE status within 1 hour. In this Condition, the required contents of three accumulators cannot be assumed to reach the core during a LOCA. Due to the severity of the consequences should a LOCA occur in these

#### ACTIONS (continued)

conditions, the 1 hour Completion Time to open the valve, remove power to the valve, or restore the proper water volume or nitrogen cover pressure ensures that prompt action will be taken to return the inoperable accumulator to OPERABLE status. The Completion Time minimizes the potential for exposure of the plant to a LOCA under these conditions.

#### C.1 and C.2

If the accumulator cannot be returned to OPERABLE status within the associated Completion Time, the plant must be brought to a MODE in which the LCO does not apply. To achieve this status, the plant must be brought to MODE 3 within 6 hours and RCS pressure reduced to  $\leq$  1000 psig within 12 hours. The allowed Completion Times are reasonable, based on operating experience, to reach the required plant conditions from full power conditions in an orderly manner and without challenging plant systems.

## <u>D.1</u>

If more than one accumulator is inoperable, the plant is in a condition outside the accident analyses; therefore, LCO 3.0.3 must be entered immediately.

#### SURVEILLANCE REQUIREMENTS

# <u>SR 3.5.1.1</u>

Each accumulator valve should be verified to be fully open every 12 hours. This verification ensures that the accumulators are available for injection and ensures timely discovery if a valve should be less than fully open. If an isolation valve is not fully open, the rate of injection to the RCS would be reduced. Although a motor operated valve position should not change with power removed, a closed valve could result in not meeting accident analyses assumptions. This Frequency is considered reasonable in view of other administrative controls that ensure a mispositioned isolation valve is unlikely.

#### SR 3.5.1.2 and SR 3.5.1.3

Every 12 hours, borated water volume and nitrogen cover pressure are verified for each accumulator. This is typically performed using the installed control room indication. This Frequency is sufficient to ensure adequate injection during a LOCA. Because of the static design of the accumulator, a 12 hour Frequency usually allows the operator to identify

## SURVEILLANCE REQUIREMENTS (continued)

changes before limits are reached. Operating experience has shown this Frequency to be appropriate for early detection and correction of off normal trends.

#### <u>SR 3.5.1.4</u>

The boron concentration should be verified to be within required limits for each accumulator every 31 days since the static design of the accumulators limits the ways in which the concentration can be changed. The 31 day Frequency is adequate to identify changes that could occur from mechanisms such as stratification or inleakage. Sampling the affected accumulator within 6 hours after a 1% tank volume increase will identify whether inleakage has caused a reduction in boron concentration to below the required limit. It is not necessary to verify boron concentration if the added water inventory is from the refueling water storage tank (RWST), because the water contained in the RWST is within the accumulator boron concentration requirements. This is consistent with the recommendation of NUREG-1366 (Ref. 6).

#### <u>SR 3.5.1.5</u>

Verification every 31 days that power is removed from each accumulator isolation valve operator (see Ref. 7) when the RCS pressure is > 1000 psig ensures that an active failure could not result in the undetected closure of an accumulator motor operated isolation valve. If this were to occur, only two accumulators would be available for injection given a single failure coincident with a LOCA. Since power is removed under administrative control, the 31 day Frequency will provide adequate assurance that power is removed.

This SR allows power to be supplied to the motor operated isolation valves when RCS pressure is  $\leq$  1000 psig, thus allowing operational flexibility by avoiding unnecessary delays to manipulate the breakers during plant startups or shutdowns. Even with power supplied to the valves, inadvertent closure is prevented by the RCS pressure interlock associated with the valves.

Should closure of a valve occur in spite of the interlock, the SI signal provided to the valves would open a closed valve in the event of a LOCA.

?

ź

- REFERENCES 1. IEEE Standard 279-1971.
  - 2. UFSAR, Chapter 6.
  - 3. 10 CFR 50.46.
  - 4. DPC-NE-3004.
  - 5. 10 CFR 50.36, Technical Specification, (c)(2)(ii).
  - 6. NUREG-1366, February 1990.
  - 7. Duke letter to NRC, "Cold Leg Accumulator Isolation Valves", dated September 8, 1987