

September 18, 2002

Mr. Lew W. Myers
Chief Operating Officer
FirstEnergy Nuclear Operating Company
Davis-Besse Nuclear Power Station
5501 North State Route 2
Oak Harbor, OH 43449-9760

SUBJECT: DAVIS-BESSE NUCLEAR POWER STATION, UNIT 1 - REPLY TO RESPONSE
TO ORDER FOR INTERIM SAFEGUARDS AND SECURITY COMPENSATORY
MEASURES (TAC NO. MB4120)

Dear Mr. Myers:

On February 25, 2002, the U.S. Nuclear Regulatory Commission (NRC) issued Orders modifying the operating licenses for the Davis-Besse Nuclear Power Station, Unit 1 to require compliance with the specified interim safeguards and security compensatory measures (ICM's).

The NRC staff's letter of May 13, 2002, addressed your earlier response to the Orders and granted, in response to your request, an extension of time until June 6, 2002, for your submission of the required response for ICM B.2.a. Your letter of June 6, 2002, provided your response to ICM B.2.a and also provided further responses to ICMs B.2.b and B.2.c.

The NRC staff has reviewed your responses to the ICMs listed above submitted by your letter of June 6, 2002 and finds that you have satisfied the current reporting requirements of the Order.

The NRC will determine the effectiveness of your implementation of the ICMs through on-site inspections. Pursuant to Section III.C.2 of the Order, you reported to the Commission by letter dated September 9, 2002, that you have achieved full compliance with the requirements described in Attachment 2 to the Order.

Please contact Jon Hopkins at (301) 415-3027 if you have any other questions on these issues.

Sincerely,

/RA/

John A. Zwolinski, Director
Division of Licensing Project Management
Office of Nuclear Reactor Regulation

Docket No. 50-346

cc: See next page

Davis-Besse Nuclear Power Station, Unit 1

cc:

Mary E. O'Reilly
FirstEnergy Corporation
76 South Main St.
Akron, OH 44308

Manager-Regulatory Affairs
First Energy Nuclear Operating Company
Davis-Besse Nuclear Power Station
Oak Harbor, OH 43449-9760

Director
Ohio Department of Commerce
Division of Industrial Compliance
Bureau of Operations & Maintenance
6606 Tussing Road
P.O. Box 4009
Reynoldsburg, OH 43068-9009

Regional Administrator
U.S. Nuclear Regulatory Commission
801 Warrenville Road
Lisle, IL 60523-4351

Michael A. Schoppman
Framatome ANP
1911 N. Ft. Myer Drive
Rosslyn, VA 22209

Resident Inspector
U.S. Nuclear Regulatory Commission
5503 North State Route 2
Oak Harbor, OH 43449-9760

Plant Manager, Randel J. Fast
FirstEnergy Nuclear Operating Company
Davis-Besse Nuclear Power Station
5501 North State - Route 2
Oak Harbor, OH 43449-9760

Dennis Clum
Radiological Assistance Section Supervisor
Bureau of Radiation Protection
Ohio Department of Health
P.O. Box 118
Columbus, OH 43266-0118

Carol O'Claire, Chief, Radiological Branch
Ohio Emergency Management Agency
2855 West Dublin Granville Road
Columbus, OH 43235-2206

Zack A. Clayton
DERR
Ohio Environmental Protection Agency
P.O. Box 1049
Columbus, OH 43266-0149

State of Ohio
Public Utilities Commission
180 East Broad Street
Columbus, OH 43266-0573

Attorney General
30 East Broad Street
Columbus, OH 43216

President, Board of County
Commissioners of Ottawa County
Port Clinton, OH 43252

President, Board of County
Commissioners of Lucas County
One Government Center, Suite 800
Toledo, Ohio 43604-6506

Terry Lodge, Convenor and Chair
Toledo Coalition for Safe Energy
316 N. Michigan Street, Suite 520
Toledo, OH 43624-1627

David Lochbaum, Nuclear Safety Engineer
Union of Concerned Scientists
1707 H Street NW, Suite 600
Washington, DC 20006

September 18, 2002

Mr. Lew W. Myers
Chief Operating Officer
FirstEnergy Nuclear Operating Company
Davis-Besse Nuclear Power Station
5501 North State Route 2
Oak Harbor, OH 43449-9760

SUBJECT: DAVIS-BESSE NUCLEAR POWER STATION, UNIT 1 - REPLY TO RESPONSE TO ORDER FOR INTERIM SAFEGUARDS AND SECURITY COMPENSATORY MEASURES (TAC NO. MB4120)

Dear Mr. Myers:

On February 25, 2002, the U.S. Nuclear Regulatory Commission (NRC) issued Orders modifying the operating licenses for the Davis-Besse Nuclear Power Station, Unit 1 to require compliance with the specified interim safeguards and security compensatory measures (ICM's).

The NRC staff's letter of May 13, 2002, addressed your earlier response to the Orders and granted, in response to your request, an extension of time until June 6, 2002, for your submission of the required response for ICM B.2.a. Your letter of June 6, 2002, provided your response to ICM B.2.a and also provided further responses to ICMs B.2.b and B.2.c.

The NRC staff has reviewed your responses to the ICMs listed above submitted by your letter of June 6, 2002 and finds that you have satisfied the current reporting requirements of the Order.

The NRC will determine the effectiveness of your implementation of the ICMs through on-site inspections. Pursuant to Section III.C.2 of the Order, you reported to the Commission by letter dated September 9, 2002, that you have achieved full compliance with the requirements described in Attachment 2 to the Order.

Please contact Jon Hopkins at (301) 415-3027 if you have any other questions on these issues.

Sincerely,
/RA/
John A. Zwolinski, Director
Division of Licensing Project Management
Office of Nuclear Reactor Regulation

Docket No. 50-346

cc: See next page

DISTRIBUTION:

PUBLIC	OGC	SCollins/JJohnson	RSullivan
ACRS/ACNW	BSheron	SECY	GTracy
WBorchardt	GHill (4)	LMarsh	VOrdaz
PDII-2 R/F	BBoger	RMartin	RCrlenjak
VDricks	RAibert	JShea	JBelanger
R. Palla	JCreed		

ADAMS Accession No.: ML022540843

OFFICE	PM:LPD3-2	PM:LPD3-2	PM:LPD2-1	LA:LPD3-2	SC:LPD3-2
NAME	MChawla	JHopkins	RMartin	THarris	AMendiola
DATE	09/16/02	09/16/02	09/17/02	09/17/02	09/18/02
OFFICE	SC:NSIR		PD:LPD3	D:DLPM	
NAME	AMadison		SBajwa	JZwolinski	
DATE	09/17/02		09/18/02	09/18/02	

OFFICIAL RECORD COPY