J. Barnie Beasley, Jr., P.E. Vice President Southern Nuclear Operating Company, Inc. 40 Inverness Center Parkway Post Office Box 1295 Birmingham, Alabama 35201

Tel 205 992 7110 Fax 205 992 0403

September 11, 2002

Docket Nos.: 50-348 50-364 SOUTHERN COMPANY Energy to Serve Your World^{ss}

NEL-02-0185

U. S. Nuclear Regulatory Commission ATTN: Document Control Desk Washington, D. C. 20555-0001

Joseph M. Farley Nuclear Plant Monthly Operating Report

Ladies and Gentlemen:

Enclosed are the August 2002 Monthly Operating Reports for Joseph M. Farley Nuclear Plant Units 1 and 2, as required by Section 5.6.4 of the Technical Specifications.

If you have any questions, please advise.

Respectfully submitted,

RWC:mor

Enclosures:

- 1. August Monthly Operating Report for Plant Farley Unit 1
- 2. August Monthly Operating Report for Plant Farley Unit 2



Page 2 U. S. Nuclear Regulatory Commission

cc: <u>Southern Nuclear Operating Company</u> Mr. D. E. Grissette, General Manager

> <u>U. S. Nuclear Regulatory Commission, Washington, D. C.</u> Mr. F. Rinaldi, Licensing Project Manager – Farley

<u>U. S. Nuclear Regulatory Commission, Region II</u> Mr. L. A. Reyes, Regional Administrator Mr. T. P. Johnson, Senior Resident Inspector – Farley

OPERATING DATA REPORT

DOCKET NO.:	50-348
UNIT NAME:	J. M. Farley - Unit 1
DATE:	September 4, 2002
COMPLETED BY:	W. L. Marlar
TELEPHONE:	(334) 814-4554

•

OPERATING STATUS

.

.

.

.

1.	Reporting Period:	AUGUST 2002
2.	Design Electrical Rating (Net MWe):	854
3.	Maximum Dependable Capacity (Net MWe):	833

		This Month	<u>Year to Date</u>	Cumulative
4.	Number Of Hours Reactor Was Critical:	744.0	5,800.1	178,046.0
5.	Hours Generator On-line:	744.0	5,784.0	175,752.2
6.	Unit Reserve Shutdown Hours:	0.0	0.0	0.0
÷ ·	Net Electrical Energy Generated (MWH):	614,266.0	4,834,560.0	139,187,506.0

CHALLENGES TO PRESSURIZER PORV OR PRESSURIZER SAFETY VALVES

Date	Tag No.	Event Description
		There were no challenges to Pressurizer PORV or Pressurizer Safety Valves.
	-	

.

UNIT SHUTDOWNS

DOCKET NO.: 50-348 UNIT NAME: J. M. Farley - Unit 1 DATE: September 4, 2002 W. L. Marlar COMPLETED BY: **TELEPHONE:** (334) 814-4554

REPORTING PERIOD:

AUGUST 2002

No.	Date	Type F: Forced S: Scheduled	Duration (Hours)	Reason (1)	Method of Shutting Down (2)	Cause/Corrective Actions Comments
						There were no unit shutdowns during the month.
(1) REAS	ON				(2) METHOD	

(1) REASON

A - Equipment Failure (Explain)

- B Maintenance or Test
- C Refueling
- D Regulatory Restriction
- E Operator Training/License Examination
- F Administrative
- G Operational Error (Explain)
- H Other (Explain)

CAUSE/CORRECTIVE ACTION/COMMENTS

NARRATIVE REPORT

At 0001 on 020810, a ramp down to approximately 91% power was commenced to perform governor valve testing. The testing was completed and the unit was returned to 100% power at 0512 on 020810.

- 1 Manual 2 - Manual Trip/Scram
- 3 Automatic Trip/Scram
- 4 Continuation 5 - Other (Explain)

.

OPERATING DATA REPORT

DOCKET NO .:	50-364		
UNIT NAME:	J. M. Farley - Unit 2		
DATE:	September 4, 2002		
COMPLETED BY:	W. L. Marlar		
TELEPHONE:	(334) 814-4554		

OPERATING STATUS

1.Reporting Period:AUGUST 20022.Design Electrical Rating (Net MWe):8553.Maximum Dependable Capacity (Net MWe):842

		<u>This Month</u>	Year_to Date	<u>Cumulative</u>
4. Number Of Hours Reacto	or Was Critical:	744.0	5,831.0	161,316.6
5. Hours Generator On-line	-	744.0	5,831.0	159,376.8
6. Unit Reserve Shutdown I	-	0.0	0.0	0.0
 Net Electrical Energy Ge 	-	615,343.0	4,927,895.0	127,509,974.0

CHALLENGES TO PRESSURIZER PORV OR PRESSURIZER SAFETY VALVES

Date	Tag No.	Event Description
		There were no challenges to Pressurizer PORV or Pressurizer Safety Valves.

DOCKET NO.: 50-364 UNIT NAME: J. M. Farley - Unit 2 DATE: September 4, 2002 COMPLETED BY: W. L. Marlar TELEPHONE: (334) 814-4554

REPORTING PERIOD: <u>AUGUST 2002</u>

. `

No.	Date	Type F: Forced S: Scheduled	Duration (Hours)	Reason (1)	Method of Shutting Down (2)	Cause/Corrective Actions Comments
						There were no unit shutdowns during the month.
A - Equipment Failure (Explain) B - Maintenance or Test C - Refueling D - Regulatory Restriction				 (2) METHOD 1 - Manual 2 - Manual Trip/Scram 3 - Automatic Trip/Scram 4 - Continuation 5 - Other (Explain) 		

H - Other (Explain)

CAUSE/CORRECTIVE ACTION/COMMENTS

NARRATIVE REPORT

ŧ

At 0735 on 020811, a ramp down to approximately 67% power was commenced to repair a condenser tube leak. The repair was completed and the unit was returned to 100% power at 1206 on 020812.