



Palo Verde Nuclear
Generating Station

William E. Ide
Vice President
Nuclear Production

Technical Specification 5.6.8

Mail Station 7602
P O Box 52034
Phoenix, AZ 85072-2034
TEL (623) 393-6116
FAX (623) 393-6077
192-01109-WEI/DGM/DFH
September 11, 2002

U. S. Nuclear Regulatory Commission
ATTN: Document Control Desk
Mail Station P1-37
Washington, DC 20555-0001

Reference: Unit 2 Special Report 2-SR-2002-001-00, dated April 12, 2002
APS Letter Number 192-01104-WEI/DGM/DFH
Accession Number ML 021350227

Dear Sirs:

**Subject: Palo Verde Nuclear Generating Station (PVNGS) Unit 2
Docket No. STN 50-529,
License No. NPF-51,
Special Report 2-SR-2002-001-01**

Pursuant to PVNGS Technical Specification 5.6.8, enclosed is Supplement 1 to Special Report 2-SR-2002-001. This supplement provides the complete results of the steam generator tube inservice inspection that was performed during the Unit 2 tenth refueling outage.

By copy of this letter and the enclosure, this Special Report is being provided to the NRC Region IV Administrator and the PVNGS Resident Inspector.

No commitments are being made to the NRC by this letter. Please contact Daniel G. Marks at (623) 393-6492 if you have any questions or require additional information.

Sincerely,

WEI/DGM/DFH/kg

Enclosure

cc: E. W. Merschoff (all with enclosure)
J. N. Donohew
N. L. Salgado

IE22