

September 23, 2002

U. S. Nuclear Regulatory Commission Attention: Document Control Desk

Washington, D. C. 20555

Subject: Docket No. 50-361

Owner's Report of Inservice Inspection, Form NIS-1 San Onofre Nuclear Generating Station, Unit 2

Reference: American Society of Mechanical Engineers (ASME)

Boiler and Pressure Vessel Code (ASME B&PVC)

Section XI: 1989 Edition, No Addenda; Second Inservice Inspection Interval

Gentlemen:

In accordance with 10CFR50.55a(g) and ASME B&PVC, Section XI, Article IWA-6000, this letter submits the Inservice Inspection (ISI) Summary Report, including the Owner's Reports of Repairs and Replacements, for San Onofre Nuclear Generating Station, Unit 2.

This report covers the period from November 17, 2000 through July 2, 2002, the date Unit 2 returned to service following its Cycle 12 refueling outage. If you have any questions or require additional information, please advise.

Sincerely

Enclosure: Inservice Inspection Report

cc: (see attached list)

P1047

cc: E. W. Merschoff, Regional Administrator, NRC Region IV

A.T. Howell, III, Director, Division of Reactor Safety, NRC Region IV

B. M. Pham, NRC Project Manager, San Onofre Units 2 and 3

C. C. Osterholtz, NRC Senior Resident Inspector, San Onofre Units 2 & 3

State of California
Department of Industrial Relations
Division of Industrial Safety
Pressure Vessels Unit
Attention: Richard Eleinko, Senior Safety Engineer
2100 East Katella, Suite 145
Anaheim, CA 92806-6040

State of California
Department of Industrial Relations
Division of Industrial Safety
Pressure Vessels Unit
Attention: J. LeMire, Principal Pressure Vessel Engineer
2100 E. Katella Ave, Suite 140
Anaheim, CA 92806-6040