



Entergy Nuclear Northeast
Indian Point Energy Center
295 Broadway, Suite 1
P.O. Box 249
Buchanan, NY 10511-0249
Tel 914 271 7060
Fax 914 271 7181
jherron@entergy.com

John T. Herron
Senior Vice President

September 26, 2002

Re: Indian Point Unit Nos. 1, 2 and 3
Docket Nos. 50-003, 50-247 and 50-286
NL-02-124
IPN-02-075

U.S. Nuclear Regulatory Commission
Attn: Document Control Desk
Mail Station O-P1-17
Washington, DC 20555-0001

SUBJECT: Combined Emergency Plan For The Indian Point Energy Center

Dear Sirs:

Pursuant to 10 CFR 50.54(q) and in accordance with 10 CFR 50.4(b)(5), Entergy Nuclear Operations, Inc. recently submitted controlled copies of changes to the Emergency Plan procedures for Indian Point Unit Nos. 1, 2 and 3.

The changes integrated and upgraded the Unit Nos. 1 and 2 plan with the Unit No. 3 plan in a combined site Emergency Plan for the Indian Point Energy Center (IPEC). The changes did not decrease the effectiveness of either plan. The Emergency Plan, as a whole, continues to meet the standards of 10 CFR 50.47(b) and the requirements of Appendix E of 10 CFR 50. The changes do not represent a reduction in commitment for any IPEC Unit.

There are no commitments contained in this letter. Should you or your staff have any questions, please contact Mr. Frank Inzirillo, Manager, Emergency Planning at (914) 271-7418.

Sincerely,

A handwritten signature in black ink, appearing to read "John T. Herron", with a large, stylized initial "J" and a horizontal line extending to the right.

cc: Next page

A045

cc: Mr. Hubert J. Miller
Regional Administrator - Region I
U.S. Nuclear Regulatory Commission
475 Allendale Road
King of Prussia, PA 19406-1498

Mr. Patrick D. Milano, Senior Project Manager, Section 1
Project Directorate I
Division of Licensing Project Management
U.S. Nuclear Regulatory Commission
Mail Stop O-8-C-2
Washington, DC 20555-0001

Senior Resident Inspector
U.S. Nuclear Regulatory Commission
Indian Point Unit 2
P.O. Box 38
Buchanan, NY 10511

Senior Resident Inspector
U.S. Nuclear Regulatory Commission
Indian Point Unit 3
P.O. Box 337
Buchanan, NY 10511