

October 10, 2002

Mr. Michael M. Corletti  
Passive Plant Projects & Development  
AP600 & AP1000 Projects  
Westinghouse Electric Company  
Post Office Box 355  
Pittsburgh, Pennsylvania 15230-0355

SUBJECT: REVISED REQUEST FOR ADDITIONAL INFORMATION (RAI) NO. 470.006 -  
AP1000 DESIGN CERTIFICATION REVIEW (TAC NO. MB5491)

Dear Mr. Corletti:

The Nuclear Regulatory Commission (NRC) staff issued RAI No. 470.006 on September 27, 2002 (ADAMS Accession No. ML022670315). The staff would like to clarify this RAI to ensure (1) the information requested is clearly understood, and (2) the staff receives sufficient information to continue its review of the AP1000 design certification application. Please find the revised RAI 470.006 enclosed (the changes are marked with revision bars in the right margin).

This question was sent to you via electronic mail on October 2, 2002.

If you have any questions or comments concerning this matter, you may contact me at (301) 415-3053 or [ljb@nrc.gov](mailto:ljb@nrc.gov).

Sincerely,

***Original signed and mailed 10/10/02***

Lawrence J. Burkhart, AP1000 Project Manager  
New Reactor Licensing Project Office/**RA**/  
Office of Nuclear Reactor Regulation

Docket No. 52-006

Enclosure: As stated

cc: See next page

Mr. Michael M. Corletti  
Passive Plant Projects & Development  
AP600 & AP1000 Projects  
Westinghouse Electric Company  
Post Office Box 355  
Pittsburgh, Pennsylvania 15230-0355

SUBJECT: REVISED REQUEST FOR ADDITIONAL INFORMATION (RAI) NO. 470.006 -  
AP1000 DESIGN CERTIFICATION REVIEW (TAC NO. MB5491)

Dear Mr. Corletti:

The Nuclear Regulatory Commission (NRC) staff issued RAI No. 470.006 on September 27, 2002 (ADAMS Accession No. ML022670315). The staff would like to clarify this RAI to ensure (1) the information requested is clearly understood, and (2) the staff receives sufficient information to continue its review of the AP1000 design certification application. Please find the revised RAI 470.006 enclosed (the changes are marked with revision bars in the right margin).

This question was sent to you via electronic mail on October 2, 2002.

If you have any questions or comments concerning this matter, you may contact me at (301) 415-3053 or [ljb@nrc.gov](mailto:ljb@nrc.gov).

Sincerely,

Lawrence J. Burkhart, AP1000 Project Manager  
New Reactor Licensing Project Office  
Office of Nuclear Reactor Regulation

Docket No. 52-006

Enclosure: As stated

cc: See next page

Distribution:

Hard Copy

PUBLIC  
NRLPO R/F  
LBurkhart  
JLyons

JSebrosky  
MGamberoni

E-Mail

SCollins/JJohnson  
RBorchardt  
ACRS  
OGC

FReinhart  
ADrozd  
MJohnson  
MHart

ACCESSION NO. ML022820451

OFFICE	NRLPO/PM	SPSB/BC	NRLPO/DD
NAME	LBurkhart:cn	MJohnson	MGamberoni
DATE	10/08/02	10/09/02	10/10/02

**OFFICIAL RECORD COPY**

Requests for Additional Information (RAIs)  
AP1000 Standard Design Certification  
Revised RAI 470.006

470.006

Please provide the following information in regard to the radiological consequences analysis of the design-basis loss-of-coolant accident (LOCA) as discussed in Chapter 15.6.5.3 and Table 15.6.5-2 of the AP1000 design control document (DCD):

- A. How was the main control room activity level ( $2.0E-6$  Ci/m<sup>3</sup> [Curies-per-cubic meter] of dose equivalent I-131) and time (0.2622 hours) at which the emergency habitability system is actuated determined? What assumptions were made in the determination of these values?
- B. What is the basis for the control room unfiltered in-leakage assumption of 5.0 cfm (cubic feet-per-minute)?
- C. What assumptions and inputs were used to calculate the LOCA doses in the control room due to radiation from adjacent structures and sky-shine?
- D. General Design Criterion 19, in 10 CFR Part 50, Appendix A, requires that adequate radiation protection shall be provided to permit access and occupancy of the control room under accident conditions without personnel receiving radiation exposure in excess of 5 rem total effective dose equivalent (TEDE), for the duration of the accident. In Section 6.4.4 of the DCD you state that the doses to main control room personnel associated with the LOCA are bounding for all other design basis accidents. The only documented control room dose analysis is for the LOCA, found in Section 15.6.5. Please provide analyses of the doses to main control room personnel associated with the remaining design basis accident radiological analyses, or alternatively provide a discussion why the LOCA control room dose analysis is bounding for each remaining Chapter 15 radiological analysis.

AP 1000

cc:

Mr. W. Edward Cummins  
Advanced Plant Safety & Licensing  
Westinghouse Electric Company  
P.O. Box 355  
Pittsburgh, PA 15230-0355

Mr. Michael Corletti  
Advanced Plant Safety & Licensing  
Westinghouse Electric Company  
P.O. Box 355  
Pittsburgh, PA 15230-0355

Mr. H. A. Sepp  
Westinghouse Electric Company  
P.O. Box 355  
Pittsburgh, PA 15230

Lynn Connor  
Doc-Search Associates  
2211 sw 1<sup>ST</sup> Ave - #1502  
Portland, OR 97201

Barton Z. Cowan, Esq.  
Eckert Seamans Cherin & Mellott, LLC  
600 Grant Street 44<sup>th</sup> Floor  
Pittsburgh, PA 15219

Mr. Ed Rodwell, Manager  
Advanced Nuclear Plants' Systems  
Electric Power Research Institute  
3412 Hillview Avenue  
Palo Alto, CA 94304-1395

Charles Brinkman, Director  
Washington Operations  
Westinghouse Electric Company  
12300 Twinbrook Parkway, Suite 330  
Rockville, MD 20852

Mr. R. Simard  
Nuclear Energy Institute  
1776 I Street NW  
Suite 400  
Washington, DC 20006

Mr. Thomas P. Miller  
U.S. Department of Energy  
Headquarters - Germantown  
19901 Germantown Road  
Germantown, MD 20874-1290

Mr. David Lochbaum  
Nuclear Safety Engineer  
Union of Concerned Scientists  
1707 H Street NW, Suite 600  
Washington, DC 20006-3919

Mr. Paul Gunter  
Nuclear Information & Resource Service  
1424 16th Street, NW., Suite 404  
Washington, DC 20036

Ms. Wenonah Hauter  
Public Citizen's Critical Mass Energy  
Project  
215 Pennsylvania Avenue, SE  
Washington, DC 20003

Mr. Tom Clements  
6703 Guide Avenue  
Takoma Park, MD 20912

Mr. James Riccio  
Greenpeace  
702 H Street, NW, Suite 300  
Washington, DC 20001

Hugh Jackson, Policy Analyst  
Public Citizen's Critical Mass Energy  
and Environment Program  
1724 Duarte Drive  
Henderson, NV 89014

Mr. James F. Mallay, Director  
Regulatory Affairs  
FRAMATOME, ANP  
3315 Old Forest Road  
Lynchburg, VA 24501

Mr. Ed Wallace, General Manager  
Project Management  
Lake Buena Vista Bldg., 3<sup>rd</sup> Floor  
1267 Gordon Hood Avenue  
Centurion 0046  
Republic of South Africa  
PO Box 9396 Centurion 0046

Mr. Vince Langman  
Licensing Manager  
AECL Technologies, Inc.  
901 15<sup>th</sup> Street, NW., Suite 440  
Washington, DC 20005-2301

Mr. Glenn R. George  
PA Consulting Group  
Chrysler Building, 34<sup>th</sup> Floor  
405 Lexington Avenue  
New York, NY 10174

Mr. Gary Wright, Manager  
Office of Nuclear Facility Safety  
Illinois Department of Nuclear Safety  
1035 Outer Park Drive  
Springfield, IL 62704