

2002 EXAM ANALYSIS

SRO #	QUESTION	RO#	ANSWER GIVEN				ACTION TAKEN
			A	B	C	D	
1	Ex02006	1					
2	Ex98030	2					
3	Ex02001	3			S		
4	Ex98103	4		R R S S			
5	Ex02002						
6	Ex00012	5			S		
7	Ex02003	6		R R R S S			Valid question. The answer will be clarified.
8	Ex00073	7			R		
9	Ex02007	8				S	
10	Ex02004	9					
11	Ex00091	10					
12	Ex02008	11	R R R R R S S S S S S S				EWD 23E008 was reviewed during the exam analysis. CRA-FN-2A1 does not trip from an undervoltage, but it will not restart due to control switch contact arrangement. The control switch must be placed in ON before the fans will start. A is correct. C is not correct. Feed back will be given to training concerning correction of referenced training material.
13	Ex99099	12					
14	Ex02009	13	R				
15	Ex00132	14					
16	Ex02010	15		R R S	S		
17	Ex02005	16		R R			

18	Ex02011	17	R R R S S S S		R		This question appears to be a knowledge issue . Feedback will be given to training.
19	Ex00042	18					
20	Ex02012	19			R		
21	Ex00102	20					
22	Ex02013	21			S	S	
23	Ex01126	22					
24	Ex02014						
25	Ex02015						
26	Ex02016	23					
27	Ex01062		S				
28	Ex02017	24	R				
29	Ex00121	25					
30	Ex02018	26					
31	Ex02090						
32	Ex02019	27	S				
33	Ex02020						
34	Ex02021	28	R S		S		
35	Ex02022	29					
36	Ex02023	30		R R S S	S		
37	Ex02024	31					
38	Ex01087	32	R				
39	Ex02025					S S	
40	Ex01039	33					
41	Ex02026	34					
42	Ex98040	35		S			
43	Ex02027	36					
44	Ex00004	37					
45	Ex02028	38			R		
46	Ex02029	39				R	
47	Ex02032	40					
48	Ex02030	41	R	S S			

49	Ex02031	42					R R S S S S	This question appears to be a knowledge issue . Feedback will be given to training.
50	Ex02082							
51	Ex02033	43					S S S S	This question appears to be a knowledge issue . Feedback will be given to training.
52	Ex00041	44				R S		
53	Ex02034	45			S S S			
54	Ex00099	46						
55	Ex98001	47			R S			
56	Ex02035	48	R S S					
57	Ex02036	49	R	R				
58	Ex02037							
59	Ex00100							
60	Ex02089				S S			
61	Ex00011						S	
62	Ex00062	50			S S	S		
63	Ex00115	51						
64	Ex02038	52				R R S S	R R S S S	The question is a valid system knowledge question. It will be re written prior to inclusion in the exam bank.
65	Ex02039	53						
66	Ex02040							
67	Ex02041	54						
68	Ex02042	55	R R S					
69	Ex02043	56						

70	Ex02044	57	S		R R R R S		This question appears to be a knowledge issue . Feedback will be given to training. The question will be clarified prior to inclusion in the exam bank..
71	Ex02045		S	S S S S S S S S			This question appears to be a knowledge issue . Feedback will be given to training.
72	Ex02046		S S S				This is a valid question. The stem will be clarified prior to inclusion in the exam bank.
73	Ex00044	58			R	R	
74	Ex00019	59					
75	Ex02047			S			
76	Ex02048	60		R			
77	Ex02069					S	
78	Ex00038				S		
79	Ex02049	61					
80	Ex02050	62			R R S		
81	Ex02051	63					
82	Ex02052				S S		
83	Ex02053	64					
84	Ex98116	65					
85	Ex02054	66	R				
86	Ex02055				S		
87	Ex02056		S				
88	Ex00039	67		R R R	R		This question appears to be a knowledge issue . Feedback will be given to training and the stem will be clarified prior to inclusion in the exam bank.
89	Ex02059	68				R	
90	Ex02058						
91	Ex02060	69	S		R		
92	Ex02061	70					

93	Ex02062		S				
94	Ex02070				S		
95	Ex02063	71		R R R R S S S S S S			This question is a valid exam question. All incorrect responses were for B, Suppression Pool level. This appears to be a knowledge issue and will be given as feedback to training.
96	Ex02064				S	S S S S	This question will be rewritten for clarity prior to inclusion in the exam bank.
97	Ex02065		S S S S S S S				This question will be clarified by adding "DBA" to A and B.
98	Ex02066	72				S	
99	Ex02067	73					
100	Ex02068						
	Ex02069	74			R		
	Ex02084	75					
	Ex01103	76					
	Ex02071	77		R		R	
	Ex00003	78					
	Ex02072	79				R	
	Ex02073	80					
	Ex02074	81					
	Ex02075	82	R				
	Ex02077	83					
	Ex01065	84					
	Ex02078	85	R		R	R	Valid question. It appears the examinees need to read the question carefully.
	Ex01042	86	R		R		
	Ex02079	87					
	Ex02080	88		R R			
	Ex02081	89					
	Ex98023	90	R	R			

	Ex01113	91					
	Ex01128	92					
	Ex99097	93					
	Ex98096	94					
	Ex00135	95					
	Ex98022	96	R				
	Ex02085	97					
	Ex02086	98		R		R R R	Valid question. This appears to be a knowledge issue and will be given to training as feedback.
	Ex02087	99					
	Ex02088	100					