

From: "Infanger, Paul E." <Paul.Infanger@pgnmail.com>
To: "John Goshen" <JMG4@nrc.gov>
Date: 9/6/01 12:56PM
Subject: RE: Turtles

Florida Power

NRR

Answers to turtle questions.

1. AI-571 Sea Turtle Rescue and Handling Guidelines, Rev 2, issued 3/15/01.
The revision is different because it is now a plant procedure.

2. Nets are still used to recover stranded turtles. Guidance is provided in AI-571 that allows lifting a turtle by the shell only as a last resort. No netting of free (non-stranded) turtles is performed.

3. AI-571 allows for increased bar rack cleaning and operation of the trash rake at the request of the Environmental co-ordinator. No specific frequency is required and the operation of the trash rake is not logged so actual frequency is uncertain. Operation of the trash rake is routinely performed by plant operators to keep the bar racks free of debris. The bar racks themselves are removed and cleaned three to four times per year.

Paul Infanger
CR-3 Licensing/Regulatory Programs
352/563-4796
voicenet 240-3166

-----Original Message-----

From: John Goshen [mailto:JMG4@nrc.gov]
Sent: Tuesday, September 04, 2001 3:13 PM
To: Paul.Infanger@pgnmail.com
Subject: Turtles

Paul, these are the questions. John

John Goshen, P.E.
Crystal River 3 Project Manager
PD II-2
(301) 415-1437

CC: "Powell, Sidney C." <SIDNEY.POWELL@pgnmail.com>

B/6

Received: from igate.nrc.gov
by nrcgwia.nrc.gov; Thu, 06 Sep 2001 12:55:40 -0400
Received: from nrc.gov
by smtp-gateway ESMTPE id MAA28454
for <JMG4@nrc.gov>; Thu, 6 Sep 2001 12:53:22 -0400 (EDT)
Received: from s00502.cplc.com (s00502.ral.cplc.com [10.22.28.10]) by mail-relay.cplc.com with SMTP
(Microsoft Exchange Internet Mail Service Version 5.5.2653.13)
id R4Z4BVY8; Thu, 6 Sep 2001 12:50:30 -0400
Received: by s00502 with Internet Mail Service (5.5.2653.19)
id <SKYL6NQL>; Thu, 6 Sep 2001 12:55:07 -0400
Message-ID: <BD1594D81C7DD5118B970002A51352C607640E@s00506>
From: "Infanger, Paul E." <Paul.Infanger@pgnmail.com>
To: "John Goshen" <JMG4@nrc.gov>
Cc: "Powell, Sidney C." <SIDNEY.POWELL@pgnmail.com>
Subject: RE: Turtles
Date: Thu, 6 Sep 2001 12:55:06 -0400
MIME-Version: 1.0
X-Mailer: Internet Mail Service (5.5.2653.19)
Content-Type: multipart/mixed;
boundary="====_NextPart_000_01C136F4.ADFEED90"

This message is in MIME format. Since your mail reader does not understand this format, some or all of this message may not be legible.

====_NextPart_000_01C136F4 ADFEED90
Content-Type: text/plain;
charset="iso-8859-1"

Answers to turtle questions.

1. AI-571 Sea Turtle Rescue and Handling Guidelines, Rev 2, issued 3/15/01. The revision is different because it is now a plant procedure.

2. Nets are still used to recover stranded turtles. Guidance is provided in AI-571 that allows lifting a turtle by the shell only as a last resort. No netting of free (non-stranded) turtles is performed.

3. AI-571 allows for increased bar rack cleaning and operation of the trash rake at the request of the Environmental co-ordinator. No specific frequency is required and the operation of the trash rake is not logged so actual frequency is uncertain. Operation of the trash rake is routinely performed by plant operators to keep the bar racks free of debris. The bar racks themselves are removed and cleaned three to four times per year.

Paul Infanger
CR-3 Licensing/Regulatory Programs
352/563-4796
voicenet 240-3166

-----Original Message-----
From: John Goshen [mailto:JMG4@nrc.gov]
Sent: Tuesday, September 04, 2001 3:13 PM
To: Paul.Infanger@pgnmail.com

Subject: Turtles

Paul, these are the questions. John

**John Goshen, P.E.
Crystal River 3 Project Manager
PD II-2
(301) 415-1437**

-----_NextPart_000_01C136F4_ADFEED90

**Content-Type: application/msword;
name="A10571.doc"**

Content-Transfer-Encoding: base64

**Content-Disposition: attachment;
filename="A10571.doc"**

Click to view Base64 Encoded File