6147

Crystal River Nuclear Facility

## Summary Report - NCRs Initiated Since 2/27/02

Sorted by	Origination	Date, Ar	Number	r, Priority
-----------	-------------	----------	--------	-------------

Selection Criteria: AR Type = NCR and AR Status not = Canceled with Attribute of 1A POT'L OPER/REPORT

AR# Originator		or	AR Subject	Orig. Date	AR Status	Priority	Potential Oper/Re	port NCR Owner
00056666	·HOYT	KOON	MUV-452 PAILED ITS PMT AFTER PM- 178A.	20020301	APPROVED	2	N	CR3 MAINTENANCE UNIT EVALUATOR GROUP
DURING T	THE STROKE ?	TO CLOSE THE	BA ON MUV-452 VIA WR 364990, THE PMT F VALVE, AT 40% CLO SED, THE TORQUE SWIT T, WE INIT IATED PASSPORT WR 41213 FOR	ICH OPENED. WI	E ENGAGED T	R SUCCE HE OPEF	SSFULLY OPENS T ATOR MAN UALLY	HE VALVE, BUT AND FINISHED
00056669	RICKY	RAWLS	GREEN SEA TURTLE RESCUED FROM CR3 Intake Area	20020301	APPROVED	1	Y	CR3 E&RC RADIATION CONTROL UNIT EVAL GRP
		IURTLE RESCU NOTIFICATIO	JED FROM CRYSTAL RIVER SITE, THE MARACUI DN.	LTURE CENTER II	DENTIFIED T	HE TURI	LE AS A GREEN S	E A TURTLE
00056676	SHAWN	SIMON	D1 AND D1D DAMPER SURVEILLANCE COMMITMENT QUESTION	20020301	INPROG		N	CR3 UNITEVAL GRP

DURING A PROCEDURE CHANGE FOR SP-338 IT WAS DISCOVERED THAT A DAMPER CHECK THAT SUPPORTED A COMMITMENT TO GENERIC LETT ER 96-01 MAY HAVE BEEN INADVERTENTLY DELETED. PT-366 & 367 HAD CONTAINED THE STPES TO INDEPENDENTLY TEST THE CC DAMPE RS D-1 AND D1D. THESE CHECKS WERE TIED TO ITS 3.3.16. ITS 3.3.16 WAS REMOVED FROM THE TECH SPECS. THE QUESTION IS WH ETHER OR NOT THE TRUE TIE SHOULD BE CREVS ITS 3.7.18 AND TH E CHECKS ADDED BACK TO SP-353 OR ANOTHER PROCEDURE.

00056680	FAIRMAN	BOCKHORST	ISR SCREENING NEEDS IMPROVEMENT	20020301	APPROVED	2	N	CR3 ASSESSMENT UNIT EVALUATOR
								GROUP

DOCUMENTATION OF THE INDEPENDENT SAFETY REVIEW ENGINEER'S ( ISRE) SCREENING OF REPORTS THAT EXPAND, CLARIFY, OR CORRECT PREVIOUSLY SUBMITTED LICENSE AMENDMENT REQUESTS (LAR) AND THE BASIS FOR DETERMINING IF THE REPORTS REQUIRE A NEW INDE PENDENT REVIEW NEEDS IMPROVEMENT.

00056684	PETER	WHITE	CONTAMINATION AREA	found	IN	A CI	LBAN	2	0020301	COMPLETE	2	N		E&RC R	AD PRO GRP
			OF THE HP SERVICE <1000 DPM/100CM2.	ROOM,	AN 2	A IR	SAMPLE	HEAD	WAS FOUND	CONTAMINA	TED.	SURVEY NUMBER	02-03	-08.`	THE