J. Barnie Beasley, Jr., P.E.

Vice President

Southern Nuclear Operating Company, Inc.

40 Inverness Center Parkway Post Office Box 1295 Birmingham, Alabama 35201

Tel 205 992 7110 Fax 205 992 0341



February 11, 2003

Docket Nos.:

50-348

50-364

NL-03-0344

U. S. Nuclear Regulatory Commission ATTN: Document Control Desk

Washington, D. C. 20555-0001

Joseph M. Farley Nuclear Plant Monthly Operating Reports

Ladies and Gentlemen:

Enclosed are the January 2003 Monthly Operating Reports as required by Section 5.6.4 of the Technical Specifications.

If you have any questions, please advise.

Sincerely,

JBB/LPH/sdl

Enclosures:

E1 - FNP Unit 1 Monthly Operating Report

E2 - FNP Unit 2 Monthly Operating Report

cc:

Southern Nuclear Operating Company

Mr. J. D. Woodard, Executive Vice President

Mr. D. E. Grissette, General Manager - Plant Farley

Document Services RTYPE: CFA04.054 & G9.03 - Xref: A.2.1

U. S. Nuclear Regulatory Commission

Mr. L. A. Reyes, Regional Administrator

Mr. F. Rinaldi, NRR Project Manager - Farley

Mr. T. P. Johnson, Senior Resident Inspector - Farley

ILDY

OPERATING DATA REPORT

 DOCKET NO.:
 50-348

 UNIT NAME:
 J. M. Farley - Unit 1

 DATE:
 February 5, 2003

 COMPLETED BY:
 W. L. Marlar

 TELEPHONE:
 (334) 814-4554

OPERATING STATUS

1.	Reporting Period:	JANUARY 2003	
2.	Design Electrical Rating (Net MWe):	854	
3.	Maximum Dependable Capacity (Net MWe):	830	

		This Month	Year to Date	Cumulative
4.	Number Of Hours Reactor Was Critical:	744.0	744.0	181,668.9
5.	Hours Generator On-line:	744.0	744.0	179,354.3
6.	Unit Reserve Shutdown Hours:	0.0	0.0	0.0
7.	Net Electrical Energy Generated (MWH):	633,525.0	633,525.0	142,208,263.0

CHALLENGES TO PRESSURIZER PORV OR PRESSURIZER SAFETY VALVES

Date	Tag No.	Event Description
		There were no challenges to Pressurizer PORV or Pressurizer Safety Valves.

UNIT SHUTDOWNS

DOCKET NO.: 50-348

UNIT NAME: J. M. Farley - Unit 1

DATE: February 5, 2003

COMPLETED BY:

W. L. Marlar

TELEPHONE:

(334) 814-4554

REPORTING PERIOD: JANUARY 2003

No.	Date (YYMMDD)	Type F: Forced S: Scheduled	Duration (Hours)	Reason (1)	Method of Shutting Down (2)	Cause/Corrective Actions Comments
						There were no unit shutdowns during the month.
(1) REA	COM				(2) METHOD	

- (1) REASON
- A Equipment Failure (Explain)
- B Maintenance or Test
- C Refueling
- D Regulatory Restriction
- E Operator Training/License Examination
- F Administrative
- G Operational Error (Explain)
- H Other (Explain)

- (2) METHOD.
- 1 Manual
- 2 Manual Trip/Scram
- 3 Automatic Trip/Scram
- 4 Continuation
- 5 Other (Explain)

CAUSE/CORRECTIVE ACTION/COMMENTS

There were no significant power reductions this period.					

OPERATING DATA REPORT

 DOCKET NO.:
 50-364

 UNIT NAME:
 J. M. Farley - Unit 2

 DATE:
 February 5, 2003

 COMPLETED BY:
 W. L. Marlar

 TELEPHONE:
 (334) 814-4554

OPERATING STATUS

1.	Reporting Period:	JANUARY 2003
2.	Design Electrical Rating (Net MWe):	855
3.	Maximum Dependable Capacity (Net MWe):	839

		This Month	Year to Date	Cumulative
4.	Number Of Hours Reactor Was Critical:	744.0	744.0	163,932.3
5.	Hours Generator On-line:	744.0	744.0	161,972.6
6.	Unit Reserve Shutdown Hours:	0.0	0.0	0.0
7.	Net Electrical Energy Generated (MWH):	645,069.0	645,069.0	129,690,591.0

CHALLENGES TO PRESSURIZER PORV OR PRESSURIZER SAFETY VALVES

Date	Tag No.	Event Description
		There were no challenges to Pressurizer PORV or Pressurizer Safety Valves.

UNIT SHUTDOWNS

DOCKET NO.:

50-364

UNIT NAME: J. M. Farley - Unit 2

DATE: February 5, 2003

COMPLETED BY:

W. L. Marlar

TELEPHONE:

(334) 814-4554

REPORTING PERIOD: JANUARY 2003

No.	Date (YYMMDD)	Type F: Forced S: Scheduled	Duration (Hours)	Reason (1)	Method of Shutting Down (2)	Cause/Corrective Actions Comments	
						There were no unit shutdowns during the month.	

(1) REASON

- A Equipment Failure (Explain)
- B Maintenance or Test
- C Refueling
- D Regulatory Restriction
- E Operator Training/License Examination
- F Administrative
- G Operational Error (Explain)
- H Other (Explain)

- (2) METHOD l - Manual
- 2 Manual Trip/Scram
- 3 Automatic Trip/Scram
- 4 Continuation
- 5 Other (Explain)

CAUSE/CORRECTIVE ACTION/COMMENTS

NARRATIVE REPORT

At 1307 on January 18, 2003 a ramp down to approximately 91% power was commenced to perform governor valve testing. The testing was completed and the unit was returned to 100% power at 1639 on January 18, 2003.