


RETURN TO **PI-137 71-9102**
396-SS



NEUTRON PRODUCTS inc

22301 Mt. Ephraim Road, P.O. Box 68
Dickerson, Maryland 20842 USA
301/349-5001 TWX: 710-828-0542

August 2, 1988



Mr. Charles E. MacDonald, Chief
Transportation Branch
Division of Safeguards and Transportation, NMSS
US Nuclear Regulatory Commission
Washington, DC 20555

Docket No. 71-9102

Dear Mr. MacDonald:

This is in response to your letter dated July 13, 1988, which requested that we "provide an engineering drawing of the 20WC-6 overpack showing the dimensions of all principal components, and information pertaining to materials of construction."

The requested information is given by our drawing no. D-240160 (2 sheets), ten copies of which are enclosed. Neutron Products hereby authorizes you to put copies of the drawing in the Public Document Room.

We trust that the information submitted will enable you to extend Certificate of Compliance No. 9102.

Sincerely yours,

NEUTRON PRODUCTS, INC.

Frank Schwoerer
Frank Schwoerer, Vice President

FS:rvs:8
Enclosures

FEE NOT REQUIRED
Supplemental dup.

DF03
11

24589

8808190102 880802
PDR ADOCK 07109102
C PDC

DOCKET NO. 71-9102
CONTROL NO. 24589
DATE OF DOC. August 2, 1988
DATE RCVD. August 4, 1988
FCUF _____ PDR
FCAF _____ LPDR _____
I & E REF.
SAFEGUARDS _____
FCTC OTHER _____
DATE 8/4/88 INITIAL slc

**THIS PAGE IS AN
OVERSIZED DRAWING
OR FIGURE,**

**THAT CAN BE VIEWED AT
THE RECORD TITLED:**

DWG. NO. 240160

SHEET 1 OF 2

**"OVERPAKCS OP-3 & OP-4"
WITHIN THIS PACKAGE...OR,
BY SEARCHING USING THE
DRAWING NUMBER:**

240160

NOTE: Because of this page's large file size, it may be more convenient to copy the file to a local drive and use the Imaging (Wang) viewer, which can be accessed from the Programs/Accessories menu.

**THIS PAGE IS AN
OVERSIZED DRAWING
OR FIGURE,**

**THAT CAN BE VIEWED AT
THE RECORD TITLED:**

DWG. NO. 240160

SHEET 2 OF 2

**"OVERPAKCS OP-3 & OP-4"
WITHIN THIS PACKAGE...OR,
BY SEARCHING USING THE
DRAWING NUMBER:**

240160

NOTE: Because of this page's large file size, it may be more convenient to copy the file to a local drive and use the Imaging (Wang) viewer, which can be accessed from the Programs/Accessories menu.