

April 15, 1982



TO ALL BOILING WATER REACTOR PLANT LICENSEES AND APPLICANTS

Gentlemen:

SUBJECT: TRANSMITTAL OF NUREG-0909 RELATIVE TO THE GINNA TUBE RUPTURE
(Generic Letter No. 82-07)

On January 25, 1982, the R. E. Ginna Nuclear Power Plant experienced a rupture of a steam generator tube. Shortly after the event, Chairman Palladino directed that a task force be established to gather and report on the factual information surrounding the event.

The task force has now completed its investigation and has documented the factual information and their findings associated with the event (See Enclosed NUREG-0909).

This report is being provided for your information only.

Sincerely,

Original signed by
Darrell G. Eisenhut

Darrell G. Eisenhut, Director
Division of Licensing
Office of Nuclear Reactor Regulation

Enclosure:
NUREG-0909

DISTRIBUTION

- Docket
- ORB (BWR) PM's
- ORB LA's
- ORB BC's
- LB (BWR) PM's
- LB LA's
- LB BC's
- Generic Files ORB 1-5
- DEisenhut
- GLainas

8204160152

8204160152 820415
PDR ADOCK 05000010
P PDR

*IDAR-5
INFO-LTR*

OFFICE	DL: ORB #5	DL ORB #5	DL AD/SA	DL: ORB		
SURNAME	JLyons:cc	Dutchfield	GLainas	DEisenhut		
DATE		4/15/82		4/15/82		