

April 15, 1982



TO ALL PRESSURIZED WATER REACTOR PLANT LICENSEES AND APPLICANTS

Gentlemen:

SUBJECT: TRANSMITTAL OF NUREG-0909 RELATIVE TO THE GINNA TUBE RUPTURE
(Generic Letter No. 82-08)

On January 25, 1982, the R. E. Ginna Nuclear Power Plant experienced a rupture of a steam generator tube. Shortly after the event, Chairman Palladino directed that a task force be established to gather and report on the factual information surrounding the event.

The task force has now completed its investigation and has documented the factual information and their findings associated with the event (See Enclosed NUREG-0909). You should review the information for applicability to your facility.

In addition, you should ensure that the information in NUREG-0909 is made available to your plant staff as part of your training program under TMI Action Plan Item I.C.5, Feedback of Operating Experience to Plant Staff.

Sincerely,

Original signed by
Darrell G. Eisenhut

Darrell G. Eisenhut, Director
Division of Licensing
Office of Nuclear Reactor Regulation

Enclosure:
NUREG-0909

8204160155

DISTRIBUTION

Docket
ORB Reading
ORB (PWR) PM's
ORB LA's
ORB BC's
LB (PWR) PM's
LB LA's
LV BC's

Generic Files ORB 1 - 5
DEisenhut
GLainas

*IDAR-5
INFO-HR.*

OFFICE	DL: ORB #5	DL: ORB #5	DL: AD/SA	DL: DIR		
SURNAME	JLyons:cc	DC Michfield	GLainas	DE Eisenhut		
				4-15-82		

OFFICIAL RECORD COPY