

**From:** Gary Demoss *GD*  
**To:** Patrick Baranowsky  
**Date:** 9/18/02 8:32AM  
**Subject:** Fwd: Re: Nozzle Cracking Data for Risk Assessments

The containment air cooler doesn't sound like a big deal. However, I'm interested/worried about the sump plugging issue. Steve Long included the issue in his SDP - but only for LLOCA. I'll look into GSI-191 work on the issue, but I'd appreciate any history lesson you guys can give on this.

Gary

**CC:** Michael Cheok

H-110