

é

• 2

Department of Energy

Yucca Mountain Site Characterization Project Office P. O. Box 98608 Las Vegas, NV 89193-8608

WBS 1.2.9.3 QA

SEP 27 1991

Richard L. Bullock Technical Project Officer for Yucca Mountain Site Characterization Project Raytheon Services Nevada 101 Convention Center Drive Phase II, Suite P-250 Las Vegas, NV 89109

EVALUATION OF RESPONSES TO CORRECTIVE ACTION REQUESTS (CARS) YM-91-070 AND YM-91-072 RESULTING FROM YUCCA MOUNTAIN QUALITY ASSURANCE DIVISION (YMQAD) AUDIT YMP-91-04 OF RAYTHEON SERVICES NEVADA

The YMQAD staff has evaluated the responses to CARS YM-91-070 and YM-91-072. The responses have been determined to be satisfactory. Verification of completion of the corrective actions will be performed after the effective dates provided. Any extension to these dates must be requested in writing with appropriate justification prior to the date. Please send a copy of extension requests to Nita J. Brogan, Science Applications International Corporation, Las Vegas, Nevada.

If you have any questions, please contact Catherine E. Hampton at 794-7973 or Richard E. Powe at 794-7749.

Donald G. Horton, Director

Yucca Mountain Quality Assurance Division

ADD: Ken Hooks LAR. Encl. WM-11 ADD: Ken Hooks LAR. Encl. NHO3

YMOAD: CEH-5830

Enclosure: CARs YM-91-070 and YM-91-072

cc w/encl: K. R. Hooks, NRC, Washington, DC S. W. Zimmerman, NWPO, Carson City, NV M. J. Regenda, RSN, Las Vegas, NV

cc w/o encl:

J. W. Gilray, NRC, Las Vegas, NV N. J. Brogan, SAIC, Las Vegas, NV, 517/T-08

9111010257 910927 YMP-5 WASTE PDR WM-11 PDR 290

			\smile	ORIGINAL THIS IS A RED STAMP	
	14CAR NO.: YM-91-070 DATE: 08/08/91 SHEET: 1 OF 1 QA WBS No.: 1.2.9.3				
	CORRECTIV	E ACTION REQUE	ST		
1 Controlling Document RSN QAPD-002, Rev. 0		·	2 Related Report No. Audit YMP-91-04		
3 Responsible Organization RSN		4 Discussed With J.L. Rue			
10 Response Due 20 days from issue	11 Responsibility for C R.L. Bullock			Stop Work Order Y or N No	
5 Requirement: RSN QAPD-002, Rev. 0, Se responsible for acknowle available at the workpla destroyed, or returned."	ct. 6, Para. 6.1.3, dging document recei ce: and that obsolet	states in part, "Con ipt; ensuring that la te or superseded docu	trolled d test auth ments are	ocument recipients are orized documents are so identified,	
6 Adverse Condition: Obsolete Project Procedure PP-05-04, Rev. 0 was found in controlled Yucca Mountain Operations Project Procedure Manuals and the procedure was not identified as "obsolete." DISCUSSION Six out of nine controlled manuals checked contained obsolete procedure PP-05-04. In each case the document holder had acknowledged receipt of instructions to remove procedure PP-05-04. The document holders were informed and the controlled manuals were corrected. The following controlled manuals were checked: 2, 12, 16, 23, 25, 57, 72, 78, and 87. NOTE: Document Transmittal dated 7/22/91 provided instructions to delete PP-05-04 and provided a Table of Contents dated 7/26/91 that indicated PP-05-04 was deleted. The current Table of Contents dated 7/29/91 does not show PP-05-04 as an issued procedure. As of 7/22/91 there were 97 individual controlled sets of PPs.					
7 Recommended Action(s): Take action to assure obsolete Project Procedure PP-05-04 is identified as obsolete, destroyed, or returned to Document Control					
8 Initiator Data R.E. Powe 08/08/91	e: 9 Severity Level 1 2 2 3 2	- 13 Approved B	.11	Date:	
15 Verification of Corrective Actio			und Port		
16 Corrective Action Completed a	na Accepted:	17 Closure Appro	vea By:		
QAR	Date	OQA			

.

۰.

•		OFFICE OF CIVILIAN RADIOACTIVE WASTE MANAGEMENT U.S. DEPARTMENT OF ENERGY WASHINGTON, D.C.	CAR NC YM-91-070 DATE <u>9/11/91</u> SHEET <u>1</u> of <u>1</u>
		CORRECTIVE ACTION REQUEST (continuation sheet)	
A.	Extent of Deficie	ency	
	investigation rev	was corrected during the audit. Furt vealed that this was an isolated case n are given below:	her indepth . Details of
	transmitted to al Project Procedure Procedure PP-50-(of July 22, 1991, acknowledgements	, a follow-up transmittal (copy attac Il personnel assigned controlled copie es Manual. The transmittal stated the D4, Revision O, had been deleted from , and should be destroyed. The trans were returned by August 28, 1991. The equired and RSN considers this CAR to	es of the at Project the manual as mittal here is no
Β.	<u>Root Cause</u>		
	N/A		
C.	<u>Remedial_Action</u>		
	N/A		
D.	Corrective Action	n to Prevent Recurrence	
	N/A		
	Response Appro	wed: Sandeph I Schreiten Dat	te: <u>9/"/9</u>]
	Response Accep	oted: TE Powe * QAR * deficiency could not be it.	9/17/9] Date
		verified elogod during and the	re-initiation foreing

٩

•: 1 4.

•

.

·	\smile		\smile	ORIGINAL THIS IS A RED STAMP
•	RADIOACTIVE V U.S. DEPART	E OF CIVILIAN WASTE MANAGEN IMENT OF ENERG INGTON, D.C.		14CAR NO.: <u>YM-91-072</u> DATE: <u>08/08/91</u> SHEET: <u>1</u> OF <u>1</u> QA WBS No.: <u>1.2.9.3</u>
	CORRECTIVE	ACTION REQUE	ST	<u></u>
1 Controlling Document RSN PP-17-03, Rev. 0	1 Controlling Document		2 Related Report No. Audit YMP-91-04	
3 Responsible Organization RSN		4 Discussed With J.E. Ferguson	.	
10 Response Due 20 days from issue	11 Responsibility for C R.L. Bullock			Stop Work Order Y or N No
RSN PP-17-03, Rev. 0, Pa packages must be authent dating the record or rec OCRWM QARD, Appendix E, Authentication is the ac accurate, complete, and	icated by authorized ord package." "Glossary," states i t of attesting that	personnel by stampir n part, "Authentic the information conta	ng, signi ation (C	ing, or initialing and
6 Adverse Condition: RSN has processed QA Rec to the work accomplished DISCUSSION For example: The record y had nothing to do with the second y had nothing to do with the	•	_		
7 Recommended Action(s): Correct the deficiency is deficiencies. Take action	lentified. Investig on to prevent recurr	ate to determine if t ence.	bere are	e other similar
8 Initiator Date R.E. Powe 08/08/		- 13 Approved By	: 	Date:
15 Verification of Corrective Actio		17 Closure Approv	red Bv:	
QAR	Date			

۰ ب

*: : , OFFICE OF CIVILIAN RADIOACTIVE WASTE MANAGEMENT U.S. DEPARTMENT OF ENERGY WASHINGTON, D.C.

CORRECTIVE ACTION REQUEST (continuation sheet)

CAR NO	YM-91-072			
SATE _	9/11/91			
SHEET_	1_0F_1_			

A. Extent of Deficiency

A review of training files submitted indicates that the actual training records for Carolyn Aiello is in another record package. The record package in question was a working file containing training attendance sheets which are duplicates of those contained in other individual training record files. This package is unique and is determined to be the only problem of its kind. Further investigation revealed that this was an isolated case.

B. <u>Root Cause</u>

The individual developing the file was not the individual who submitted it to Records Management. The developer was no longer an employee. The developer's replacement inadvertently submitted this file along with other training files for individual employees.

C. <u>Remedial Action</u>

Since the package in question has been determined to contain duplicate material, and has not been processed by the Central Records Facility into the Project Records Information System, it will be recalled and deleted as a record item.

Recall of the package in question was completed on 8-30-91. There is no further action required.

D. Corrective Action to Prevent Recurrence

The Administrative Training Assistance will review all future training records packages prior to submitting them to Records Management, to be assured they contain specific training records required and that duplicate record packages are not created nor submitted.

Responsible Individual:

Manager, Project Administration

w Date: 7n Response Approved SN-YMP-1188

-CAR NO. ____YM-91-072 **OFFICE OF CIVILIAN** DATE: **RADIOACTIVE WASTE MANAGEMENT** SHEET: OF **U.S. DEPARTMENT OF ENERGY** WASHINGTON, D.C. **CORRECTIVE ACTION REQUEST** (continuation sheet) A E Pone 9/17/91 Date C/18/9 Response Accepted: Response Accepted: (34) - 20, 1990