

Department of Energy

Yucca Mountain Site Characterization
Project Office
P. O. Box 98608
Las Vegas, NV 89193-8608

WBS 1.2.9.3 QA

NOV 0 1 1991

Robert F. Pritchett
Technical Project Officer
for Yucca Mountain
Site Characterization Project
Reynolds Electrical &
Engineering Co., Inc.
P.O. Box 98521
Las Vegas, NV 89193-8521

VERIFICATION OF CORRECTIVE ACTIONS AND CLOSURE OF CORRECTIVE ACTION REQUESTS (CARS) YM-91-037 AND YM-91-038 RESULTING FROM YUCCA MOUNTAIN QUALITY ASSURANCE DIVISION (YMQAD) AUDIT 91-02 OF REYNOLDS ELECTRICAL & ENGINEERING CO., INC.

The YMQAD staff has verified the corrective actions to CARs YM-91-037 and YM-91-038 and determined the results to be satisfactory. As a result, the CARs are considered closed.

If you have any questions, please contact either Robert B. Constable at 794-7945 or Robert H. Klemens at 794-7734.

R. Spince

YMQAD:RBC-592

Richard E. Spence, Director Yucca Mountain Quality Assurance Division

Enclosure: CARs YM-91-037 and YM-91-038

cc w/encl:

K. R. Hooks, NRC, Washington,

S. W. Zimmerman, NWPO, Carson City, NV

W. J. Glasser, REECo, Las Vegas, NV

cc w/o encl:

J. W. Gilray, NRC, Las Vegas, NV

N. J. Brogan, SAIC, Las Vegas, NV, 517/T-08

And: K. R. Hooks 4, Enf WM-11 102.7

YMP-5

7111120442 911101 PDR WASTE PDR · recuede und retur del.

ORIGINAL THIS IS A RED STAMP

OFFICE OF CIVILIAN RADIOACTIVE WASTE MANAGEMENT U.S. DEPARTMENT OF ENERGY WASHINGTON, D.C.

14CAR NO.:	YM-91-037		
DATE:	03/07/91		
	1 OF _	2	
	QA		
WBS No :	1.2.9.3		

WASHINGTON, D.C. WBS No.: 1.2.9.3				
CORRECTIVE ACTION REQUEST				
	CORRECTIVE	E ACTION REQUE		
1 Controlling Document QP 17.0				ed Report No. No. 91-02
3 Responsible Organization		4 Discussed With		
REECo		C. Thompson, R. Pr	itchett,	M. Fox
10 Response Due	11 Responsibility for C	Corrective Action	12	Stop Work Order Y or N
30 Days After Issue	P. F. Pritchett		1	No
5 Requirement:				
<pre>OP 17.0, Rev. 4, Paras. responsible for the cont transmitting the origina Para. 6.1.1 states in pa</pre>	rol, authentication l, or best available rt, "As a minimum, (and distribution of i copy to the LRC for A records shall inclu	ts own r processi de docum	ecords, including ng." ments which specify.
verify, or affect quality closely related document	y, i.e., results or s such as qualificat	reviews, audits monit ions of personnel, pr	oring of ocedures	work performance and
<pre>IM-LRC-IP-01, Rev. 0, Pa of Contents and be liste Submittal Form, the comp Contents, shall be trans</pre>	leted record package	e, along with the Subm	ittal Fo	rm and the Table of
6 Adverse Condition:				
Contrary to the above re QA Record Packages descr Records System, or have are as follows:	ibed in REECo QA Imm	olementing Procedures,	cannot	be found within the OA
 No documented eviden- were received by the 	ce was found that the LRC as QA Record Pa	ne QA, IP, QS, Calibra sckages.	tion and	Welding procedures
Standards Lab LRC. Referen	oratory and Weld Lab ce Updated Responses	poratory records have to AFR-5, dated 02/2	not been 0/91.	
2. The Management Asses	sment for 1990 and t	the Readiness Review 1	or Midwa	y Valley activities
7 Recommended Action(s): Identify the remedial ac Investigate the program of similar deficient con-	process, activities	or documentation to d	etermine	the extent and depth
⁸ Initiator (Dat	e: 9 Severity Level	- 13 Approved By		Date:
M. R. Piaz - 02/28/91		00A J.B.	laufort	8/12/91
15 Verification of Corrective Action	າກ;			
Corrective action Ve		ment attached-	PHE	10/25/11
102.7				
16 Corrective Action Completed	and Accepted:	17 Closure Approv	ed Ru	
DAR Revert H. Lemen	•	17 Closure Approv		Une 10/31/91

CAR NO.:	YM-91	L-037	
DATE:	03/0	7/91	
SHEET: _	2	OF	2

CORRECTIVE ACTION REQUEST (continuation sheet)

- 5 Requirements (continued)
 record package."
- 6 Adverse Condition (continued)
 have not been transmitted as a QA record package.
 - 3. Audit REECo-004-90, report was issued on May 29, 1990 and the last finding was closed on July 7, 1990. However, it was transmitted to the LRC on November 7, 1990.
 - Audit REECo-005-90, report was issued on June 6, 1990 and the last finding was closed on June 26, 1990. However, it was transmitted to the LRC on November 7, 1990.
- 7 Recommended Action(s) (continued)

measures required to correct them. Identify the cause of the condition and the planned corrective action to prevent recurrence.

CAR NO	YM->.	
DATE:	04-12-5.	
SHEET:	1 of 2	_

CORRECTIVE ACTION REQUEST (continuation sheet)

CORRECTIVE ACTION RESPONSE: CAR YM-91-037

1. CORRECTIVE ACTION FOR DEFICIENT CONDITION # _ALL_

A. Extent of Deficiency:

- A sample review of record packages was performed and determined that many record packages may be missing from the Local Record Center (LRC).
- For those record packages currently in the LRC, many were not submitted in accordance with the 10-day turnover requirement.

B. Root Cause:

Record Sources have not complied with the records requirements described in the governing procedures as evidenced by their failure to implement the classroom training and guidelines provided.

- C. Remedial Actions: (All Actions To Be Completed By 10/15/91)
 - 1. A review will be conducted to determine how many record packages should have been generated by Quality and Implementing Procedures. Once a list is determined, a comparison will be made to those record packages contained in the records system. If packages are missing, the Records Source will be requested to obtain and transmit it to the LRC. If a complete records package can not be assembled, documentation will be issued and included in the package acknowledging the missing documentation. An evaluation of the affect on quality of the missing documentation will be performed and included as part of the records package. The above actions will be coordinated by the LRC.
 - 2. The completed 1990 Management Assessment was submitted to the LRC on 04/08/91.
 - 3. The Readiness Review for Midway Valley activities will be submitted to the LRC by 05/15/91.
 - 4. For those records that were submitted after the 10-day turnover requirement, no remedial actions can be taken.

CAR NO.	<u> </u>		
DATE: _	04		
SHEET:_	2	_OF	4

CORRECTIVE ACTION REQUEST (continuation sheet)

CORRECTIVE ACTION RESPONSE: CAR YM-91-037 (Continued)

- 1. CORRECTIVE ACTION FOR DEFICIENT CONDITION # _ALL_
 - D. <u>Corrective Action to Prevent Recurrence</u>: (Actions To Be Completed By 05/31/91)
 - 1. QPs 5.1 and 5.3 will be revised to distribute Quality and Implementing Procedures to the LRC as part of the mandatory review. This will ensure that the LRC is aware of what records or record packages will be generated by that procedure. The revisions will be completed by 05/31/91.
 - 2. Notification will be made to all YMP support departments identifying the records management deficiencies observed during the DOE audit of the REECo Yucca Mountain Project. Managers will be cautioned to notify their Record Sources and Administrators of the importance of record generation and submittal of completed records/record packages within the 10-day turnover timeframe. This notification will be completed by 05/31/91.
 - 3. Additional support and direction is being provided by the LRC Staff to Records Sources and Administrators through on-site visits, on-the-job training, menu-driven submittal programs and appropriate user's manuals. This is an on-going activity.

Response Approved:	Bruce Stardelle For R.F.P.	4/12/91
• • • • • • • • • • • • • • • • • • • •	Responsible Manager	Date
ACCEPT RESPONSE:		
ACCEPT RESPONSE:	QAR	Date
	AQO	Date
This response	was amended on AP 23,91	H 4/24/91

CAR NO. YM-91-037
DATE: 04-23-91
SHEET: 1 OF 3

CORRECTIVE ACTION REQUEST (continuation sheet)

AMENDED RESPONSE

CORRECTIVE ACTION RESPONSE: CAR YM-91-037

1. CORRECTIVE ACTION FOR DEFICIENT CONDITION # _ALL_

A. Extent of Deficiency:

- A sample review of record packages was performed and determined that many record packages may be missing from the Local Record Center (LRC).
- For those record packages currently in the LRC, many were not submitted in accordance with the 10-day turnover requirement.

B. Root Cause:

Record Sources have not complied with the records requirements described in the governing procedures as evidenced by their failure to implement the classroom training and guidelines provided.

- C. Remedial Actions: (All Actions To Be Completed By 10/15/91)
 - A review will be conducted to determine how many record packages should have been generated by Quality and Implementing Procedures. This review will be conducted by May 30, 1991 and will identify those packages (current revision level) which represent current activities.
 - 2. Once a list of packages has been determined, a comparison will be made to those record packages contained in the records system. This review will be conducted by 6/15/91.
 - 3. If packages for current activities are found missing, the Records source will be requested by 7/1/91 to obtain and transmit the required records to the LRC. If a complete records package can not be assembled, documentation will be issued and included in the package acknowledging the missing documentation. An evaluation of the affect on quality of the missing documentation will be performed and included as part of the records package. All activities associated with current activity packages will be completed by 8/1/91.

Atr del 4/23/91-580-01-377

CAR NO.		M-9.	
DATE: _	0	4-23	- b .
SHEET:	2	OF_	3

CORRECTIVE ACTION REQUEST (continuation sheet)

AMENDED RESPONSE

CORRECTIVE ACTION RESPONSE: CAR YM-91-037 (Continued)

- 1. CORRECTIVE ACTION FOR DEFICIENT CONDITION # ALL
 - C. Remedial Actions: (Continued)
 - For all other missing packages (not current activity), the Records Source will be requested by 8/1/91 to obtain and transmit the required records to the LRC if the missing information represents package data for an activity which will not be repeated or for procedures which will be used in the future. If a complete records package can not be assembled, documentation will be issued and included in the package acknowledging the missing documentation. An evaluation of the affect on quality of the missing documentation will be performed and included as part of the records package. All activities associated with current activity packages will be completed by 10/15/91
 - 5. The completed 1990 Management Assessment was submitted to the LRC on 04/08/91.
 - 6. The Readiness Review for Midway Valley activities will be submitted to the LRC by 05/15/91.
 - 7. For those records that were submitted after the 10-day turnover requirement, no remedial actions can be taken.
 - D. <u>Corrective Action to Prevent Recurrence:</u> (Actions To Be Completed By 05/31/91)
 - 1. QPs 5.1 and 5.3 will be revised to distribute Quality and Implementing Procedures to the LRC as part of the mandatory review. This will ensure that the LRC is aware of what records or record packages will be generated by that procedure. The revisions will be completed by 05/31/91.

RHK

CAR NO.	YM	-91-	03,
DATE:	04	-23-	91
SHEET:	3	_OF_	3

CORRECTIVE ACTION REQUEST (continuation sheet)

AMENDED RESPONSE

CORRECTIVE ACTION RESPONSE: CAR YM-91-037 (Continued)

- 1. CORRECTIVE ACTION FOR DEFICIENT CONDITION # ALL
 - D. Corrective Action to Prevent Recurrence: (Continued)
 - 2. Notification will be made to all YMP support departments identifying the records management deficiencies observed during the DOE audit of the REECo Yucca Mountain Project. Managers will be cautioned to notify their Record Sources and Administrators of the importance of record generation and submittal of completed records/record packages within the 10-day turnover timeframe. This notification will be completed by 05/31/91.
 - 3. Additional support and direction is being provided by the LRC Staff to Records Sources and Administrators through on-site visits, on-the-job training, menu-driven submittal programs and appropriate user's manuals. This is an on-going activity.

Response Approved:	127 Pritihest	4-23-91
•	Responsible Manager	Date
RESPONSE ACCEPTED:	Vaio Jai	4-24-91
•	QAR	Date
RESPONSE ACCEPTED:	Cathonina Langton La	4-26-91
•	OQA ()	Date



Reynolds Electrical & Engineering Co., Inc.

Post Office Box 98521 ● Las Vegas, NV 89193-8521

580-01-383

Ark 10 1991

WBS 1.2.9 QA

Donald G. Horton, Director Quality Assurance Division Yucca Mountain Site Characterization Project Office U.S. Department of Energy Post Office Box 98608 Las Vegas, NV 89193-8608

CORRECTION OF AMENDED RESPONSE TO CORRECTIVE ACTION REQUEST (CAR) YM-91-037 RESULTING FROM YUCCA MOUNTAIN QUALITY ASSURANCE DIVISION (YMQAD) AUDIT 91-02 OF REYNOLDS ELECTRICAL & ENGINEERING CO., INC. (REECO)

The purpose of this letter is to document a telephone conversation on April 25, 1991 between R. H. Klemens, SAIC Audit Team Leader, and W. J. Glasser, REECo/YMP QA Manager, concerning REECo's amended response to CAR YM-91-037. Mr. Klemens requested a clarification on wording for the last sentence of planned remedial action step C4. The clarification was discussed as follows:

Current:

Remedial Actions section C4, last sentence - "All activities associated with <u>current</u> activity packages will be completed by 10/15/91"

Change to:

Remedial Actions section C4, last sentence - "All activities associated with <u>these</u> activity packages will be completed by 10/15/91"

The affected word has been underlined. This clarification is needed to be consistent with the subject of section C4, "Other missing packages (not current activity)..."

Should you have any questions or require further information, please contact W. J. Glasser of my staff at 794-7562.

R. F. Pritchett, Manager

Yucca Mountain Project Division YMP Technical Project Officer

RFP:WJG:dm

cy: See page 2

REECO
AN LEGES COMPANY

D. G. Horton 580-01-383 Page 2

cy: Central Files THRU
Executive Office, M/S 555
W. J. White, DOE/NV, M/S 505
C. E. Hampton, DOE/YMP, M/S 523
N. J. Brogan, SAIC, M/S 517/T-08,
R. H. Klemens, SAIC, M/S 517



Reynolds Electrical & Engineering Co., Inc.

Post Office Box 98521 ● Las Vegas, NV 89193-8521

IN REPLY REFER TO:

580-01-422

WBS 1.2.9 OA

MAY 14 1991

Donald G. Horton, Director Quality Assurance Division Yucca Mountain Site Characterization Project Office U.S. Department of Energy Post Office Box 98608 Las Vegas, NV 89193-8608

QA RECEIVED

MAY 15 1991

REVISION OF AMENDED RESPONSE TO CORRECTIVE ACTION REQUEST (CAR) YM-91-037 RESULTING FROM YUCCA MOUNTAIN QUALITY ASSURANCE DIVISION (YMQAD) AUDIT 91-02 OF REYNOLDS ELECTRICAL & ENGINEERING CO., INC. (REECO)

The subject amended response stated, for remedial action step 6, that REECo planned to submit the Readiness Review for Midway Valley activities by May 15, 1991. However, REECo has determined that the approved Job Package (JP) 91-1 has not been transmitted to REECo from the Field Operations Center. In addition, the Material Reporting & Handling Plan is presently at the Yucca Mountain Site Characterization Project Office for approval. Since the missing information is required to closeout the completed quality assurance records package, REECo is not required, by the current records management system, to submit the package to the Local Records Center (LRC) at this time.

REECo does not have control over release of all required package documentation. When the required information is completely assembled, the completed package will be closed out and the package submitted.

No further action regarding remedial action step 6 can be initiated by REECo at this time. Therefore, please revise the remedial action to read:

6. The Readiness Review for Midway Valley activities will be submitted to the LRC within 10 days after REECo receives all of the required package information and the package is closed out. The completed quality assurance records package is not required at this time.

REECO

Donald G. Horton 580-01-422 Page 2

Should you have any questions or require further information, please contact $W.\ J.\ Glasser$ of my staff at 794-7562.

R. F. Pritchett, Manager Yucca Mountain Project Division YMP Technical Project Officer

RFP:WJG:rm

cy: Central Files THRU

Executive Office, M/S 555
W. J. White, DOE/NV, M/S 505
C. E. Hampton, DOE/YMP, M/S 523
N. J. Brogan, SAIC, M/S 517/T-08
R. H. Klemens, SAIC, M/S 517

VERIFICATION OF CAR YM-91-037

Block 15 - Verification of Corrective Action

Remedial Action

- Item 1 Verified. Reviewed List of Procedure Record Packages, dated May 30, 1991
- Item 2 Verified. Reviewed Procedure and Activity Record Status, dated June 13, 1991
- Item 3 Verified. All activities associated with current activity packages completed by 10/15/91. Reviewed Activity Record Packages, dated Oct. 15, 1991
- Item 4 Verified. All activities associated with not-current activity packages completed by 10/15/91. Reviewed packages and Standards which were sent to the LRC.
- Item 5 Verified. Reviewed microfilm RE 010776, (submittal of 1990 Management Assessment to the LRC on 4/8/91).
- Item 6 Verified. Readiness Review for Midway Valley activities submitted to the LRC on 7/17/91. Checked microfilm RMS 11739.

Corrective Action

- Item 1 Verified. Reviewed revisions to procedures QP 5.1 and QP 5.3.
- Item 2 Verified. Reference Pritchett Memo dated 5/24/91 on Records Management Corrective Actions.
- Item 3 Verified. Reference record submittal computer programs, on-the-job training, and REECo Records Management Manual.

Pobert H. Klemen 10/25/91

ORIGINAL THIS IS A RED STAMP

OFFICE OF CIVILIAN RADIOACTIVE WASTE MANAGEMENT U.S. DEPARTMENT OF ENERGY WASHINGTON, D.C.

14CAR NO.:	YM7-91-038
DATE:	3/7/91
	1 OF 2
	QA
	1.2.9.3

WASHINGTON, D.C. WBS No.: 1.2.9.3				
	CORRECTIVE	ACTION REQUES	ST	
1 Controlling Document QP 17.0				ed Report No. 91-02
3 Responsible Organization		4 Discussed With		
REECo	···	C. Thompson/R. Pri		
10 Response Due 30 days after issue	11 Responsibility for C R.F. Pritchett	corrective Action		Stop Work Order Y or N
5 Requirement:	R.F. FIICHECE			
QP 17.0, Revision 4, Par completed and processed Management procedure."				
<pre>IM-LRC-IP-01, Revision 0 the LRC, records shall b or enclosures are include</pre>	reviewed to ensure	? and 6.1.1.12.1 state e the record is comple	te and a	to transmittal to
OAPP, Revision 8, Section include (1) individual defurnish evidence of the to demonstrate implement	ocuments that have h activities affecti	meen executed, completing quality; (2) docum	ed, and ents pre	approved and that pared and maintained
6 Adverse Condition:				
Documents maintained as by the implementation of	records are incomple the applicable prod	ete and do not contain redures. Examples are	all of	the records generated
 Management Assessment are missing (Reference 	for year 1990: Come QP 2.3, Revision 1	mpleted checklists and L, Paragraph 7.1)	Correct	ive Action Requests
 QP, IP, QS, Calibration, and Welding procedures: Document Review Record, Document Review Continuation Sheets, and Quality Procedure Change Notices are missing (Reference QP 5.1, Revision 2, Paragraph 7.1) 				
				···
7 Recommended Action(s): Identify the remedial ac Investigate the program of similar deficient con	process, activities	or documentation to d	encies n letermine	noted in Block 6. the extent and depth
8 Initiator Date		- 13 Approved By	:	Date:
Mario R. diaz 2/28/91	1 2 2 3 1	OOA Cathe	A/	Auf 3-11-91
15 Verification of Corrective Action	on:			
Corrective action Verification Statement attached - KHK 10/25/91				
16 Corrective Action Completed	and Accepted:	17 Closure Approv	red By:	
OAR Rebert H. Klemens Date 10/25/91 OOA Pr.C. Spyree 10/31/91				

3/12/91

OFFICE OF CIVILIAN
RADIOACTIVE WASTE MANAGEMENT
U.S. DEPARTMENT OF ENERGY
WASHINGTON, D.C.

CAR NO.: YMF-91-038

DATE: 3/7/91

SHEET: 2 OF 2

CORRECTIVE ACTION REQUEST (continuation sheet)

5 Requirements (continued)

document that will either receive no more entries or whose revision would normally consist of the reissue of the document; and is signed and dated by the originator and, as applicable, by personnel authorized to approve the document."

- QP 2.3, Revision 1, paragraph 7.1 states, "The completed Management Assessment Report, Checklist, Memorandum, and Corrective Action Requests shall be considered QA Records, and shall be maintained in accordance with QP 17.0."
- QP 5.1, Revision 2, paragraph 7.1 states, "Procedures and their revisions, Document Review Record, Document Review Record Continuation Sheets, and the Quality Procedure Change Notices, when applicable, generated by the implementation of this procedure are QA Records and shall be packaged together and processed in accordance with QP 17.0.
- 7 Recommended Action(s) (continued)

Identify these deficiencies and provide the measures required to correct them. Identify the cause of the condition and the planned corrective action to prevent recurrence.

CAR NO. YM-91-038

DATE: 04-12-91

SHEET: 1 OF 2

CORRECTIVE ACTION REQUEST (continuation sheet)

CORRECTIVE ACTION RESPONSE: CAR YM-91-038

1. CORRECTIVE ACTION FOR DEFICIENT CONDITION # ALL

A. Extent of Deficiency:

Based on a sample review, it appears that many of the record packages submitted may be deficient in their required documentation.

B. Root Cause:

Record Sources have not complied with the records requirements described in the governing procedures as evidenced by their failure to implement the classroom training and guidelines provided.

- C. Remedial Actions: (All Actions To Be Completed By 10/15/91)
 - 1. The submitted Record Packages will be examined by the Record Source and Local Records Center (LRC) Staff to determine what documents, as required by the governing procedure, were included in the packages. If documentation is missing, the Records Source will attempt to obtain and include it in the package. Otherwise documentation will be issued and included in the package acknowledging the missing documentation. An evaluation of the affect on quality of the missing documentation will be performed and included as part of the records package.
 - 2. The completed 1990 Management Assessment was submitted to the LRC on 04/08/91.
- D. <u>Corrective Action to Prevent Recurrence</u>: (Actions To Be Completed By 05/31/91)
 - 1. QPs 5.1 and 5.3 will be revised to distribute procedures to the LRC as part of the mandatory review. This will ensure that the LRC is aware of what records or record packages will be generated by that procedure. These revisions will be completed by 05/31/91.

CAR NO.	<u> Y</u>	M-91	<u> </u>	
DATE: _	04	-12-	<u>91</u>	
SHEET:	2	OF	2	

CORRECTIVE ACTION REQUEST (continuation sheet)

<u>CORRECTIVE ACTION RESPONSE:</u> CAR YM-91-038 (Continued)

- 1. CORRECTIVE ACTION FOR DEFICIENT CONDITION # _ALL_ (Continued)
 - D. Corrective Action to Prevent Recurrence: (Continued)
 - 2. Notification will be made to all YMP support departments identifying the records management deficiencies observed during the DOE audit of the REECo Yucca Mountain Project. Managers will be cautioned to notify their Record Sources and Administrators of the importance of record generation and submittal of completed records/record packages within the 10-day turnover timeframe. This notification will be completed by 05/31/91.
 - 3. Additional support and direction is being provided by the LRC Staff to Records Sources and Administrators through on-site visits, on-the-job training, menu-driven submittal programs and appropriate user's manuals. This is an on-going activity.

Response Approved: _	Brue Sardella For RF Responsible Manager	P 4/12/91 Date
RESPONSE ACCEPTED:	₩ X QAR	Date
RESPONSE ACCEPTED:	OQA	Date
* This response	was amended on A	P 23,91 () 1/24/9

CAR NO. YM-91-038
DATE: 04-23-91
SHEET: 1 of 2

CORRECTIVE ACTION REQUEST (continuation sheet)

AMENDED RESPONSE

CORRECTIVE ACTION RESPONSE: CAR YM-91-038

1. CORRECTIVE ACTION FOR DEFICIENT CONDITION # ALL

A. Extent of Deficiency:

Based on a sample review, it appears that many of the record packages submitted may be deficient in their required documentation.

B. Root Cause:

Record Sources have not complied with the records requirements described in the governing procedures as evidenced by their failure to implement the classroom training and guidelines provided.

C. Remedial Actions: (All Actions To Be Completed By 10/15/91)

- 1. Using the list of packages generated as part of the remedial actions for CAR-YM-91-037, item C 1, those packages which represent current activities which are currently in the LRC will be reviewed by Quality Assurance and the LRC staff to determine the completeness of the records submitted in accordance with the governing procedure. This review will be completed by 6/15/91.
- 2. If documentation is found missing for current activities, Quality Assurance will conduct an evaluation of the affect on quality of the missing documentation and included as part of the package by 7/1/91.
- 3. If the missing documentation is deemed to be critical to the satisfactory performance of quality affecting activities for the licensing of the repository, then the Records source will be requested to provide the missing information to the LRC no later than 8/1/91.
- 4. For all other packages which are not representative of current activities, the review for package completeness and affect on quality determination for missing documentation will be completed by 10/15/91.
- 5. The completed 1990 Management Assessment was submitted to the LRC on 04/08/91.

Str Std 4/23/91-580-01-377

CAR NO.	YM-91-038		
DATE:	04	-23	-91
SHEET:	2	_OF	2

CORRECTIVE ACTION REQUEST (continuation sheet)

AMENDED RESPONSE

CORRECTIVE ACTION RESPONSE: CAR YM-91-038 (Continued)

- CORRECTIVE ACTION FOR DEFICIENT CONDITION # ALL (Continued)
 - D. <u>Corrective Action to Prevent Recurrence</u>: (Actions To Be Completed By 05/31/91)
 - 1. QPs 5.1 and 5.3 will be revised to distribute procedures to the LRC as part of the mandatory review. This will ensure that the LRC is aware of what records or record packages will be generated by that procedure. These revisions will be completed by 05/31/91.
 - 2. Notification will be made to all YMP support departments identifying the records management deficiencies observed during the DOE audit of the REECo Yucca Mountain Project. Managers will be cautioned to notify their Record Sources and Administrators of the importance of record generation and submittal of completed records/record packages within the 10-day turnover timeframe. This notification will be completed by 05/31/91.
 - 3. Additional support and direction is being provided by the LRC Staff to Records Sources and Administrators through on-site visits, on-the-job training, menu-driven submittal programs and appropriate user's manuals. This is an on-going activity.

Response Approved:	127 Prices Responsible Manager	<u>4/23/91</u> Date
RESPONSE ACCEPTED:	Mais Jai	4/24/91 Date
RESPONSE ACCEPTED:	Cathonine Hampton for	4-710-9 Date

VERIFICATION OF CAR YM-91-038

Block 15 - Verification of Corrective Action

Remedial Action

- Item 1 Verified. Completeness review of List of Procedure Record Packages, dated May 30, 1991, was accomplished by 6/15/91.
- Item 2 Verified. Impact evaluation was not required. No missing documentation was identified.
- Item 3 Verified. Missing documentation was not critical to the satisfactory performance of quality affecting activities for the licensing of the repository.
- Item 4 Verified. Review completed on schedule (10/15/91).
- Item 5 Verified. The 1990 Management Assessment was submitted to the LRC on 4/8/91. Checked microfilm RMS# 010776.

Corrective Action

- Item 1 Verified. Reviewed revisions to procedures QP 5.1 and
 QP 5.3.
- Item 2 Verified. Reference Pritchett Memo dated 5/24/91 on Records Management Corrective Actions.
- Item 3 Verified. Reference record submittal computer programs, on-the-job training, and REECo Records Management Manual.

Robert H. Klemen 10/25/11