

#### Department of Energy

Yucca Mountain Site Characterization **Project Office** P. O. Box 98608 Las Vegas, NV 89193-8608

WBS 1.2.11 QA: N/A

JAN 26 1993

Larry R. Haves Technical Project Officer for Yucca Mountain Site Characterization Project U. S. Geological Survey 101 Convention Center Drive Suite 860 Las Vegas, NV 89109

EVALUATION OF AMENDED RESPONSE TO CORRECTIVE ACTION REQUEST (CAR) YM-93-012 RESULTING FROM YUCCA MOUNTAIN QUALITY ASSURANCE DIVISION (YMOAD) AUDIT YMP-93-01 OF U. S. GEOLOGICAL SURVEY

The YMQAD staff has evaluated the amended response to CAR YM-93-012. response has been determined to be satisfactory. Verification of completion of the corrective action will be performed after the effective date provided. Any extension to this date must be requested in writing, with appropriate justification, prior to the date. Please send a copy of extension requests to Nita J. Brogan, Science Applications International Corporation, Las Vegas, Nevada.

If you have any questions, please contact either Robert B. Constable at 794-7945 or Cynthia H. Prater at 794-7742

> Richard E. Spence, Director Yucca Mountain Quality Assurance Division

> > Add: K.R. Hooks
> >
> > All
> >
> > NHOBN
> >
> > 102.1.

YMQAD:RBC-2167

Enclosure: CAR YM-93-012

cc w/encl.

K. R. Hooks, NRC, Washington, DC S. W. Zimmerman, NWPO, Carson City, NV

T. H. Chaney, USGS, Denver, CO R. W. Craig, USGS, Las, Vegas, NV

R. L. Maudlin, MACTEC, Las Vegas, NV

B. J. Verna, YMP, NV

A. V. Gil, YMP, NV

cc w/o encl:

J. W. Gilray, NRC, Las Vegas, NV N. J. Brogan, SAIC, Las Vegas, NV D. D. Porter, SAIC, Golden, CO

010663

WASTE

PDR



# OFFICE OF CIVILIAN

8	CAR NO.:	YM-93-012	
	DATE:	10-23-92	
		1 OF _	1
		Ο.	

		ITE MANAGEM INT·OF ENERG TON, D.C.	1	SHEET: 1 OF 1 QA
	<u>-</u>			
	RECTIVE AC	CTION REQUES		
1 Controlling Document YMP-USGS-QMP-7.01 Rev. 4			2 Related I	
3 Responsible Organization	. 4 D	iscussed With		
USGS	W	. Causseaux		
5 Requirement:  OMP 7.01, R4-M2 Para. 5.1.4 allows list subject to conditions. These	project person conditions inc	nel to use vendors lude:	s not on t	he approved vendors
<ol> <li>Addition to the QA office work;</li> <li>A Nonconformance Report shall happroved Vendors List within 60</li> </ol>	ing vendors lis be written if t calendar days	t by the QA Manage he vendor is not q of addition to th	er, and pualified he working	for the vendors list.
6 Adverse Condition:	<del> </del>			
Contrary to the above				
<ol> <li>There is no QA office working vendors list, and</li> <li>A Nonconformance Report has not been issued after the QA Manager agreed by memo to allow the use of a vendor on July 23, 1992, and the vendors has not been added to the Approved Vendors List.</li> </ol>				
	140	<del></del>		1445
9 Does a significant condition	1	work condition exist?		11 Response Due Date:
adverse to quality exist? Yes No <u>x</u> If Yes, Circle One: A B C		_; If Yes - Attach cop One: A B C D	=	20 working days from issuance
	xtent of Deficienc	y 🗓 Preclude Rec	currence	X Root Cause Determination
13 Recommended Actions:	hal mhala			
7 Initiator 14 Issuance Approved by:				
J. Blaylock and C. Prater	The 149/8-	QADD A.C.	Soln	el Date /1/3/92
15 Response Accepted	<del></del>	16 Response Accep	ted	<del></del>
	ate	QADD		Date
17 Amended Response Accepted	1/4/93	18 Amended Raspo	nse Abtept	ed/)
	)ate	QADDKD (D)	MONKE	+ot. Date 01・26・33
19 Corrective Actions Verified		20 Closure Approved	o by:	
QAR D	)ate	QADD	Et	CLOSURE Date

CAR NO.	YM-93-012
DATE:	
SHEET: _	OF

### CORRECTIVE ACTION REQUEST (continuation sheet)

- 1. CORRECTIVE ACTION RESPONSE FOR CAR No. YM-93-012:
  - A. Remedial Action: 1. No remedial actions are necessary (see corrective actions to preclude recurrence).
    - 2. Initiation of a new Nonconformance Report (NCR) is not warranted at this time. An existing nonconformance report USGS-NCR-92-23 already documents the deficiency for which the vendor was suspended. All usage of the vendor since April 1991 is being evaluated under USGS-NCR-92-23. The results of this evaluation and additional remedial actions, if any, will be outlined in a supplemental response.
  - B. Investigative Action: Not requested.
  - C. <u>Root Cause Determination</u>: 1. The usage of the working vendors list was unclear. The original intent was to track the evaluation of potential vendors, the re-evaluations of approved vendors, and conditionally approved vendors not on the AVL. More useable systems have been developed to track these separate categories independently.
    - 2. The formality of initiating a NCR was not fulfilled. An internal nonconformance report covering Li-Cor procurements had already been initiated and response development was underway. Therefore the QA Office personnel involved with tracking the evaluation/approval based upon the 7/23 memo did not recognize a need for another NCR.
  - D. <u>Corrective Action to Preclude Recurrence:</u> 1. The requirement for a working vendors list is being deleted from QMP-7.01.
    - 2. QA Office personnel through working with this deficiency have been reminded to follow the requirements of QMP-7.01, R4 para.5.1.4.

CAR NO	D. <u>YM-93-012</u>
DATE:	
SHEET:	OF

#### CORRECTIVE ACTION REQUEST (continuation sheet)

- 2. For each action above, identify the name of the individual assigned responsibility for completion and the anticipated (or actual, if complete) completion date.
  - A. Remedial Action:
    - 1. NA
    - 2. 12-16-92 -- K.W.Causseaux will be responsible for completion of the evaluation of calibration documentation and the determination of impact.
    - 12-23-92 -- T.H.Chaney and L.R.Hayes will be responsible for providing a supplemental response to YMQAD.
  - D. Corrective Action to Preclude Recurrence:
    - 1. 1-4-93 (expected effective date) -- A.E. Lykins is responsible for initiating change to QMP-7.01, R4.
    - 2. 12-1-92 -- A.E.Lykins and T.H.Chaney have been reminded of QMP requirements for initiating NCRs.

3.	Response Approved:		
	81 Oh		
	CHOCK!	12/1/92	
	L. R. Hayes	Date <sup>*</sup>	
	Chief, Yucca Mountain Project Branch		
	D 1191		
	Allu Olemal	12/1/92	
	T. H. Chaney	Date	
	YMP-USGS/Quality Assurance Manager		

CAR NO.	YM-93-012
DATE:	1/6/93
SHEET: _	OF

#### CORRECTIVE ACTION REQUEST (continuation sheet)

#### 1. CORRECTIVE ACTION RESPONSE FOR CAR No. YM-93-012:

- A. <u>Remedial Action:</u> 1. No remedial actions are necessary (see corrective actions to preclude recurrence).
  - 2. Initiation of a new Nonconformance Report (NCR) is not warranted at this time. An existing nonconformance report USGS-NCR-92-23 already documents the deficiency for which the vendor was suspended. All usage of the vendor since April 1991 has been evaluated under USGS-NCR-92-23 and corrected if necessary.
- B. Investigative Action: Not requested.
- C. <u>Root Cause Determination:</u> 1. The application and the maintenance of the working vendors list was not clearly defined in QMP 7.01.
  - 2. The formality of initiating a NCR was not fulfilled. An internal nonconformance report covering Li-Cor procurements had already been initiated and response development was underway. Therefore the QA Office personnel involved with tracking the evaluation/approval based upon the 7/23 memo did not recognize a need for another NCR.
- D. Corrective Action to Preclude Recurrence: 1. The requirement for a working vendors list is being deleted from QMP-7.01. The method of tracking the evaluations and suitability of vendors is now a pending file, maintained by vendor name, which includes: the requests for evaluating vendors, notices to vendors that they will be evaluated, results of the evaluations including whether a vendor is or is not qualified and/or what requirements must be met in order to become qualified, and any corrective actions taken by a vendor to become approved for the AVL. The pending file is a working file maintained by the QA Staff and includes a tickler system for tracking activities. Vendor evaluations are audits, surveillances, or desk evaluations.
  - 2. QA Staff, including QA implementation specialists in the field, have been advised to comply with the current QMP 7.01. Upon approval and publication of the revision QMPs 4.01 and 7.01, all personnel involved with using vendors' services will be trained.

CAR NO.	YM-93-012
DATE:	1/6/93
	OF

### CORRECTIVE ACTION REQUEST (continuation sheet)

2.	For each action above, identify the name of the individual assigned responsibility	<u>for</u>
	completion and the anticipated (or actual, if complete) completion date.	

A. Remedial Action:

**Response Approved:** 

1. NA

3.

- 2. 12-31-92 -- USGS-NCR-92-23 was verified by Dan Valega and closed.
- D. Corrective Action to Preclude Recurrence:

YMP-USGS Quality Assurance Manager

- 1. 1-29-93 (anticipated approval date) -- A.E. Lykins is responsible for initiating change to QMP-7.01, R4.
- 2. 12-1-92 -- A.E.Lykins and T.H.Chaney have been reminded of QMP requirements for initiating NCRs.

I Los QM	1/6/93	
L. R. Hayes	Date	
Chief, Yucca Mountain Project Branch		
and the state		
Marca Diller	1// (92	
SHORD ARRIVALLE	//6/12	
T. H. Chaney	Date	