Region I NMSS Licensee Event Report

Licensee Agilent Technologies						
Event Description Notice of General License Device with High Removable						
Activity						
License # 07-28762 Docket # 0300 2988 MLER-RI 2003-03	O					
Event Date 2003 Report Date 4/2//03						
1. REPORTING REQUIREMENT						
10 CFR 20.2201 Theft or Loss 10 CFR 35.33 Misadministration						
10 CFR 20.2203 30 Day Report License Condition						
10 CFR 30.50 Report						
\times Other 10 CFR 31,5						
2. REGION I RESPONSE						
Immediate Site Inspection Inspector/Date	Pit - ATTHOUGHT HA					
Special Inspection Inspector/Date						
Telephone Inquiry Inspector/Date						
Preliminary Report Daily Report						
Information Entered in RI Log Review at next inspection						
Report referred to:						
3. REPORT EVALUATION						
Description of Event Corrective Actions						
Levels of RAM Involved Calculations Adequate						
Cause of Event Additional Information Requested from License	عد					
4. SPECIAL INSTRUCTIONS OR COMMENTS						
The state of the s						
(1) (2) (2) (3) (4) (4) (4) (4) (4) (4) (4) (4) (4) (4						
Public Non-Public						
Initials/Date Initials/Date						
Completed by: Bety Ulling Date 4/30/03	_					
Reviewed by: Date 5/11003						
Location of File: G:\LAS\LER FORM REV A.wpd						



2850 Centerville Road Wilmington, DE 19808 2003 APR 23 PH 1: 17

Division of Nuclear Materials Safety U.S. Nuclear Regulatory Commission Region I 475 Allendale Road, King of Prussia, PA 19406

Re: Notice of General License device with high removable activity (NRC License 07-28762-02G)

April 21, 2003

Dear Sir or Madam,

Per the requirements of 10 CFR 31.5, I am notifying your office of the following devices returned to us by customers from which we have obtained removable activity wipes in excess of 0.005 μ Ci. Both cells were returned from overseas customers. The cells were evaluated by support engineering and their disposition is identified below.

Serial #	Model #	Activity (μCi)	Disposition	Comments
F1420	19233	0.107	Scrapped	ECD was 12 years old. Source was corroded ECD was 11 years old. Source was dark and dirty
F5195	19233	0.010	Scrapped	

and the property of the contract of the contra

and the contribution of th

the first of the f

Please contact me at 302-633-8262 if there are any questions.

Thank you,

David S. Bennett

Radiation Safety Officer

process to proceed the community