

Department of Energy

Washington, DC 20585 BEC 2 4 1996

L. D. Foust, Technical Project Officer for Yucca Mountain Site Characterization Project
TRW Environmental Safety Systems, Inc. Bank of America Center, Suite P-110
101 Convention Center Drive
Las Vegas, NV 89109

EVALUATION OF AMENDED RESPONSE TO DEFICIENCY REPORT (DR) YM-96-D-103 RESULTING FROM OFFICE OF QUALITY ASSURANCE (OQA) SURVEILLANCE YMP-SR-96-027

The OQA staff has evaluated the amended response to DR YM-96-D-103. The amended response has been determined to be satisfactory. Verification of completion of the corrective action will be performed after the effective date provided. Any extension to this date must be requested in writing, with appropriate justification, prior to that date. Please send a copy of extension requests to Deborah G. Sult, OQA/QATSS, P.O. Box 98608, Mail Stop 455, Las Vegas, Nevada 89193-8608.

Donald G. Horton Director Office of Quality Assurance

If you have any questions, please contact either Mario R. Diaz at (702) 794-1489 or John R. Doyle at (702) 794-1465.

OQA:MRD-0600

Enclosure: DR YM-96-D-103

cc w/encl:

T. A. Wood, DOE/HQ (RW-55) FORS
J. O. Thoma, NRC, Washington, DC
S. W. Zimmerman, NWPO, Carson City, NV
B. R. Justice, M&O, Las Vegas, NV
Records Processing Center = "9"

cc w/o encl:

W. L. Belke, NRC, Las Vegas, NV D. G. Sult, OQA/QATSS, Las Vegas, NV J. R. Doyle, OQA/QATSS, Las Vegas, NV R. W. Clark, DOE/OQA, Las Vegas, NV

9701020258 961224 PDR WASTE WM-11 PDR NH33/1 102.7 Lm-11

HIS	A LEGICIAN Meport
	⊠Deficiency Report

NO. <u>YM-96-D-103</u>

PAGE 1 OF 30 QA: L

\$

1/2/

	 	~~!~~!		REPORT
-	 \mathbf{D} and \mathbf{R}	f 'L/I 1L-1	-11.1	
			TOILING I	REFUN

1 Controlling Document:		2 Related Report No.			
Yucca Mountain Site Character	ization Project	YMP-SR-96-027			
Administrative Procedure (YAP		,			
3 Responsible Organization:		4 Discussed With:			
Civilian Radioactive Waste Mar	agement System		a'a aan a	•	
	· ·	Steven C. Smith, Jon	M. White		
Management and Operating Co	ontractor .			•	
5 Requirement/Measurement Criteria:		· · · · · · · · · · · · · · · · · · ·			
YAP-13.1Q, "Borehole Security	and Access " Revision (1			
TAP-13. TQ, Buteriole Security	and Access, Nevision o		·		
1 Paragraph 5 1 1h) etatos:	"The Requestor: comp	lotes and submits a DA	IP to the DOE ET	C or designed for	
1. Paragraph 5.1.1b) states:	•	ieles and submits a dr	IN IO LINE DOE FI	C of designee for	
Democratik 5 4 Oh) staten	approval"		of the boschole I	en to be leaved to the	
Paragraph 5.1.2b) states:	"The DOE FTC: docum				
	Requestor and the date	e the requestor is requi	rea to submit a B	orenoie Status Report	
	(BSR)"				
Paragraph 5.2.1a) states:				OE FTC by completing	
	a BSR in accordance w			•	
Paragraph 5.2.1b) states:	*The Requestor: subm	its the BSR to the DOE	FTC in accorda	nce with the schedule	
,	noted on the BAR"				
(See Page 3)					
6 Description of Condition:					
i '	- Parisate (PAP) resea	la thát a sutanna ta mhai		BODs have not been	
A review of Borehole Acces			re requirements,	BSRs have not been	
submitted as per schedules	provided for the followin	g borenoles:	•		
			.		
Borehole	Date Autho	rized Duration of A	ccess Statu	s Reports Due	
USW H-3, USW H-3, USW H-4					
and USW H-6	5/2/95	Three Ye	ars	Quarterly	
USW G3	5/2/95	Three Ye	ars	Quarterly	
UE-25 NGR#5	<i>5/2/</i> 95	Three Ye		Quarterly	
USW UZ-6s	5/2/95	Three Ye		Quarterly	
UE-25b #1	5/2/95			Quarterly	
Well J 11 and J 12	5/2/95			Quarterly	
1 100.10 17 4.14 5 12	0,2,00			add. torry	
(See Page 3)					
	A				
7 Initiator Richard L.	July you	9 is condition an isolated occ	urrence?		
John R. Doyle	Date 10/4/96	□ Yes ® No	□ Unknown;	Must be Yes if PR	
10 Recommended Actions: (Not required to	x PR)	<u> </u>	<u></u>		
J				•	
 Submit required documents 	ition in accordance with t	he requirements cited	above.		
l <u>.</u>					
- Conduct an evaluation to determine which Affected Organizations have obtained access to boreholes. Verify					
compliance to Yucca Mountain Site Characterization Project Administrative Procedure (YAP)-13.1Q. Provide a					
written report on the results	of this evaluation includi	ng a description of con	rections taken, as	appropriate.	
•					
· .					
11 QA Review: 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1					
Julian a. Willer		· ·			
QAR John R. Doyle	Date 10/4/96	20 Working Days From Issuance			
13 Affected Organization QA manager Issu	ance Approval: (QAR for PR)	·/\/\			
Printed Name Richard	F Spence Signati	ure BA L	dans.	Date 10/9/5/	
/ // // //	4. JOENCE Signal		me		
22 Corrective Action Verified	V	23 Closure Appropred by:	(N/A for PR)	• / •	
LOAD	Data	1 40044		Data	

B ☐Performance Report

Deficiency Report

NO. _YM-96-D-103

PAGE _ OF _ OA: L

PR/DR CONTINUATION PAGE

Block 5 Requirement/Measurement Criteria: (continued)

- 2. Paragraph 5.3.1 states: *Upon the completion of borehole activity, the Requestor:
 - a) ensures that the cap is tightly secured on the borehole after each episode, and that the cap cannot be removed without unlocking
 - b) completes and signs a Borehole Completion Report (Exhibit YAP-13.1.Q.2)(BCR); and
 - c) returns the key and submits the BCR to the DOE FTC when access to the borehole is no longer required"

Block 6 Description of Condition: (continued)

2. A review of BARs reveals that contrary to the above requirements, no keys or BCRs have been submitted to the DOE FTC for the following boreholes:

Date Authorized		Duration of Access
1/25/95	•	4 Weeks
<i>5/25/</i> 95		One Year
8/22/95 ·		One Month
	1/25/95 5/25/95	1/25/95 5/25/95

PR/DR NO. <u>YM-96-D-103</u>			
PAGE	OF _	7 4	
, ,	QA:	L	

PERFORMANCE/DEFICIENCY REPORT RESPONSE

14 Remedial Actions: 1. Issue a notice to the principal manager of refebruary 10, 1997. (NOTE:prior requests to U	• •	_				
occasions) 2. Issue notice to responsible party requesting (extension of BAR or submittal of BCR). 3. Review all open borehole access approvals, call extended access by the appropriate responsible of the Archive all necessary records in accordance (See Continuation Sheet.)	ancelled all expire manager with new	ed access ap	pprovals, and provals.	replaced those i	identified as	needing
15 Extent of Condition: (Not required for PR) Based on examination of the records for borehold. USGS for failure to submit BSRs since July 2 G-2, USW SD-7, USW H-1, USW H-3, USW H UE-25 J-11, UE-25 J-12, UE-25 J-13, UE-25 p# WT-7, USW WT-10, USW WT-11, UE-25 WT- UE-25 WT-18, USW VH-1, UE-25 JF-3, UE-29	4, 1995 for the fo -4, USW H-5, US 1, USW WT-1, U -12, UE-25 WT-13	ollowing bo W H-6, US SW WT-2 B, UE-25 V	oreholes: USV SW G-3, UE-2 , UE-25 WT-1 VT-14, UE-25	W SD-9, USW U 25 NRG#5, USW 3, UE-25 WT-4, 5 WT-15, UE-25	Z-6, USW (UZ-6s, UE UE-25 WT WT-16, UE	UZ-7a, USW -25 b#1, -6, USW -25 WT-17,
16 Root Cause Determination: (Not required for	or PR) F	Required	Yes	☑ No		
						. ,
				•		
7 Action to Preclude Recurrence: (Not require	ed for PR) F	Required	Yes	☑ No		
					•	
					٠	
	·					
18 Corrective Action Completion Due Date:	19 Response by:	Steven S	Smith		A	. DP
01/02/97	✓ Initial ☐ Amended		Date 1	1/07/96	Phone 29	15-4234
20 Response Accepted		21 Respo	onse Accepte	d (N/A for PR):		
QAR Date		AOQAM			Date	, 0745 (00
hihit AP-16 10 2						Rev. 07/15/96

11/7/96 LY. GSD. SCS. 11/96-008

E Deliciency Report
NO. YM-96-D-103
PAGE/2 U OF 2 U OA: L

Performance Report

PR/DR CONTINUATION PAGE

Continuation of box 14, Remedial Actions:

Revise procedure YAP-13.1Q as follows::

- 5. Eliminate Borehole Status Report (BSR) and Borehole Closure Report (BCR) requirement. Reports do not add value to the process and only serve to consume time and budget. The same objective can be accomplished with a log.
- 6. Replace all forms with a simple signout log for access control and closure of access.

Improve operations as follows:

7. Increase aggressiveness in requesting issuance of Deficiency Reports against non-compliant team-mates.

Of the above items, 5 and 6 are based on direct recommendations from the Surface Based Test Coordination Office. See continuation page for responsibility and completion dates.

NOTE: Procedure YAP-13.10 is currently in revision to accomplish, among other things, items 1 and 2 above.

Continuation of box 15, extent of conditions:

UZN boreholes 1 through 84 and 86 through 98. Currently, quarterly BSRs are required for each of the above boreholes until cancellation of access is requested or access approval expires.

2. USGS failed to renew BARs or submit BCRs for the following boreholes: USW SD-9, USW UZ-6, USW UZ-7a, USW G-2, and USW SD-7.

NOTE: Currently, all other participants are covered under procedure NLP-2-4 for the protection and access control of YMP boreholes. Assessment of non-compliance under NLP-2-4 will be executed and steps similar to those identified in box 14 will be implemented as appropriate.

Continuation of box 18, Corrective Action Completion Due Dates:

- Box 14, item 1 -due on or before 11/19/96, Assigned to Steven Smith, compliance by objective evidence.
- Box 14, item 2 -due on or before 11/15/96, Assigned to Steven Smith, compliance by objective evidence.
- Box 14, item 3 -due on or before 11/15/96, Assigned to Steven Smith, compliance by objective evidence.
- Box 14, item 4 -due on or before 11/15/96, Assigned to Steven Smith, compliance by objective evidence.
- Box 14, item 5 -due on or before 1/2/97, Assigned to Steven Smith, compliance by objective evidence.
- Box 14, item 6 -due on or before 1/2/97, Assigned to Steven Smith, compliance by objective evidence.
- Box 14, item 7 -due on or before 11/15/96, Assigned to Steven Smith, compliance by objective evidence.

PR/DR NO. <u>YM-96-D-103</u>						
PAGEL	_ OF	2				
	QA:	L				

PERFORMAN	NCE/DE	FICIENCY RE	PORT RE	SPONSE		
14 Remedial Actions: 1. Issue a notice to the principal manager of respectuary 10, 1997. 2. Issue notice to responsible party requesting a (extension of BAR or submittal of BCR). 3. Review all open borehole access approvals, ca extended access by the appropriate responsible management 4. Archive all necessary records in accordance as See Continuation Sheet.	notificatio incelled al	on of future intention of future intention of future intention of future in the future	ons for bore provals, and provals.	holes whose	access approval is c	expired
15 Extent of Condition: (Not required for PR) Based on examination of the records for borehold 1. USGS for failure to submit BSRs since July 24 G-2, USW SD-7, USW H-1, USW H-3, USW H- UE-25 J-11, UE-25 J-12, UE-25 J-13, UE-25 p#; WT-7, USW WT-10, USW WT-11, UE-25 WT- UE-25 WT-18, USW VH-1, UE-25 JF-3, UE-29	4, 1995 fo -4, USW H 1, USW W 12, UE-25	or the following bo I-5, USW H-6, US VT-1, USW WT-2, WT-13, UE-25 W	reholes: US W G-3, UE- UE-25 WT- /T-14, UE-2	W SD-9, US 25 NRG#5, 3, UE-25 W 5 WT-15, U	SW UZ-6, USW UZ USW UZ-6s, UE-25 /T-4, UE-25 WT-6, E-25 WT-16, UE-2:	-7a, USW 5 b#1, USW 5 WT-17,
16 Root Cause Determination: (Not required fo	r PR)	Required	Yes	☑ No		
		:				
		·: .				
· .	·					
17 Action to Preclude Recurrence: (Not require	d for PR)	Required	Yes	☑ No		
			·			
		·				
18 Corrective Action Completion Due Date: 02/10/97	☐ Initi	ense by: Steven S al ended	Me	2/10/96	milk Phone 295-	4234

21 Response Accepted (N/A for PR):

Exhibit AP 16.10.2

12/10/96 LYYM SOMP 1.505.12/94-218

20 Response Accepted

Rev. 07/15/96

12/20/96

Date

Perform Deficien	iance Report icy Report
	io, rioport
NO. <u>YM-96</u>	-D-103
PAGE 2	OF 2
•	QA: L

PR/DR CONTINUATION PAGE

Continuation of box 14, Remedial Actions:

Revise procedure YAP-13.1Q as follows::

- 5. Eliminate Borehole Status Report (BSR) and Borehole Closure Report (BCR) requirement. Reports do not add value to the process and only serve to consume time and budget. The same objective can be accomplished with a log.
- 6. Replace all forms with a simple signout log for access control and closure of access.

Improve operations as follows:

7. Increase aggressiveness in requesting issuance of Deficiency Reports for non-compliant conditions identified during regular checks.

Of the above items, 5 and 6 are based on direct recommendations from the Surface Based Test Coordination Office. See continuation page for responsibility and completion dates.

NOTE: Procedure YAP-13.1Q is currently in revision to accomplish, among other things, items 1 and 2 above.

Continuation of box 15. extent of conditions:

UZN boreholes 1 through 84 and 86 through 98. Currently, quarterly BSRs are required for each of the above boreholes until cancellation of access is requested or access approval expires.

2. USGS failed to renew BARs or submit BCRs for the following boreholes: USW SD-9, USW UZ-6, USW UZ-7a, USW G-2, and USW SD-7

NOTE: Currently, all other participants are covered under procedure NLP-2-4 for the protection and access control of YMP boreholes. Assessment of non-compliance under NLP-2-4 will be performed and steps similar to those identified in box 14 will be implemented as appropriate.

Continuation of box 18, Corrective Action Completion Due Dates:

- Box 14, item 1 issuance of notice due on or before 12/16/96, Assigned to Steven Smith, compliance by objective evidence.
- Box 14, item 2 issuance of notice due on or before 12/16/96, Assigned to Steven Smith, compliance by objective evidence.
- Box 14, item 3 correction of access approvals due on or before 12/16/96, Assigned to Steven Smith, compliance by objective evidence.
- Box 14, item 4 records archieving due on or before 12/16/96, Assigned to Steven Smith, compliance by objective evidence.
- Box 14, item 5 -due on or before 1/2/97, Assigned to Steven Smith, compliance by objective evidence.
- Box 14, item 6 -due on or before 1/2/97, Assigned to Steven Smith, compliance by objective evidence.
- Box 14, item 7 -evidence of increased vigilence due on or before 12/16/96, Assigned to Steven Smith, compliance by objective evidence.