

NRC 2003-0056

June 10, 2003

U.S. Nuclear Regulatory Commission
ATTN: Document Control Desk
Washington, DC 20555

DOCKET 50-301; LICENSE NO. DPR-27
POINT BEACH NUCLEAR PLANT, UNIT 2
SUBMITTAL OF THE AUXILIARY FEEDWATER ORIFICE ISSUE REGULATORY
CONFERENCE SLIDE PRESENTATION

Ladies/Gentlemen:

On June 6, 2003, a regulatory conference was conducted between representatives of the Nuclear Management Company, LLC (NMC) and members of your Staff to discuss the Auxiliary Feedwater Orifice Issue at Point Beach Nuclear Plant (PBNP). During the presentation, a question was raised regarding the installation date, shown on slide eight, of the "A" motor driven auxiliary feedwater pump recirculation line orifice. A review performed following the conference determined that the date presented was incorrect and should have reflected a November 2000 installation date. This error did not impact the risk analysis discussed at the conference.

The attached slide presentation is provided for your use. Based on the error identified above, three slides; eight, twenty, and twenty-one have been corrected. Additionally, slide eight has been clarified to reflect the "A" and "B" designation of the motor driven auxiliary feedwater pumps.

If you have any questions, please contact Gordon P. Arent at 920/755-6518.

Sincerely,



A. J. Cayia
Site Vice President

GPA/kmd
Enclosure

NRC 2003-0056
June 10, 2003

cc: (w/o enclosure)
Project Manager, Point Beach Nuclear Plant, NRR, USNRC
Regional Administrator, Region III, USNRC
NRC Resident Inspector - Point Beach Nuclear Plant
PSCW