

TITLE:	NUMBER	PP-01-00*
TRANSITION of QUALITY ASSURANCE PROGRAMS	REVISION	0
	PAGE	1 of 3
	EFFECTIVE DATE	12-12-90
	SUPERSEDES	N/A

1.0 PURPOSE

This procedure establishes the Transition Plan whereby the Fenix & Scisson of Nevada (FSN) and Holmes & Narver, Inc. (H&N) QA Programs will be merged in the Raytheon Services Nevada (RSN) Quality Assurance (QA) Program.

2.0 APPLICABILITY

This procedure applies to all RSN employees working on the Yucca Mountain Project (YMP).

3.0 REFERENCES

- 3.1 Quality Assurance Program Plan, QAPP-002 (Fenix & Scisson)
- 3.2 Quality Assurance Program Plan, H.N-10471-1132 (Holmes & Narver, Inc.)
- 3.3 Quality Assurance Requirements Document DOE/RW-0214

4.0 DEFINITIONS

None

5.0 RESPONSIBILITIES

The following personnel or their designated representatives are responsible for approving changes to the existing FSN or H&N QA Program Plan (QAPP) and implementing procedures.

5.1 Fenix & Scisson of Nevada

5.1.1 Project Procedures and Design Control Procedures

Previous Approvals Required

FSN Technical Project Officer (TPO)
FSN Manager, Quality Assurance, YMP (MQA/YMP)
FSN General Manager

Current Approvals

RSN TPO
RSN MQA/YMP
Not Required

*NOTE: This is an Interim Procedure that will be deleted upon establishment of the RSN QA Program.

APPROVED BY:			12/7/90
	MANAGER, Quality Assurance, YMP	TECHNICAL PROJECT OFFICER	Date

5.1.2 Quality Assurance Procedures**Previous Approvals Required**

FSN Manager of QA
FSN General Manager

Current Approvals

RSN MQA/YMP
RSN TPO

5.1.3 Quality Assurance Program Plan**Previous Approvals Required**

FSN Manager of QA
FSN General Manager
Not Required

Current Approvals

RSN MQA/YMP
Manager, QA, RSN
RSN TPO

Also requires Department of Energy Yucca Mountain Project Office QA approval

5.1.4 Other documents which require management approvals**Previous Approvals Required**

FSN Manager of QA
FSN TPO
FSN General Manager

Current Approvals

RSN MQA/YMP
RSN TPO
Not Required

5.2 Holmes & Narver, Inc. (H&N)**5.2.1 Procedures****Previous Approvals Required**

H&N Manager of QA
H&N TPO

Current Approvals

RSN MQA/YMP
RSN TPO

5.2.2 Quality Assurance Program Plan**Previous Approvals Required**

H&N Manager of QA
H&N TPO
H&N General Manager

Current Approvals

RSN MQA/YMP
RSN TPO
Not Required

Also requires Department of Energy Yucca Mountain Project Office QA approval

5.2.3 Other documents which require management approvals**Previous Approvals Required**

H&N Supervisor of YMP QA
H&N Manager of QA
H&N TPO
H&N General Manager

Current Approvals

Not Required
RSN MQA/YMP
RSN TPO
Not Required

6.0 PROCEDURE

6.1 General

6.1.2 RSN shall continue to integrate the FSN and H&N Quality Assurance Program until the RSN QA Program Description (QAPD) is approved. However, in the interim FSN and H&N shall function under their previously approved QAPPs referenced in Section 3.1 and 3.2 of this procedure. Work performed on the Project shall be documented as to what QA Program was applicable.

6.1.3 This procedure formalizes the proposed Transition Plan that was submitted to and approved by DOE YMPO QA. Following are the agreed to milestones.

- a. Submit RSN QAPD for DOE approval - December 14, 1990.
- b. Issue RSN QAPD - 30 days after DOE approval.
- c. Issue necessary RSN Procedures - March 31, 1991.

6.1.4 Quality Assurance Program Description

RSN will develop a Quality Assurance Program Document (QAPD) based on the DOE Quality Assurance Requirements Document (QARD).

6.1.5 Implementing Procedures

RSN will develop procedures to implement the requirements of the QAPD, the DOE Administrative Procedures and other DOE Requirements Documents. Existing FSN and H&N Procedures will be consolidated into RSN procedures. For those activities to be conducted under the RSN QA Program, the RSN Procedures will be issued prior to initiation of the activities.

6.1.6 Training

Appropriate personnel will be trained to the RSN Plans and Procedures prior to implementation.

6.1.7 Additional Work

If RSN is directed to perform additional work prior to DOE approval of the RSN QAPD, the work will be conducted under the FSN or H&N approved QAPP, as appropriate. Work initiated after the implementation of the RSN QAPD will be conducted under the RSN QAPD.

7.0 QUALITY ASSURANCE RECORDS

There are no QA Records generated by this procedure.

1991 JAN 10 10 00 AM

MJR\bjm

1991 JAN -4 A 9 44