AUDIT PLAN DOE-EM/343 QUALITY ASSURANCE AUDIT OF DOE/WEST VALLEY PROJECT OFFICE WEST VALLEY DEMONSTRATION PROJECT

AUDIT NUMBER:

94EA-WV-AU-01

AUDITING ORGANIZATION:

Department of Energy (DOE) Headquarters Environmental Restoration and Waste Management

Office of Waste Management

Vitrification Projects Division (EM-343)

AUDITED ORBANIZATION:

DOE West Valley Project Office (WVPO) West Valley Demonstration Project (WVDP)

AUDIT DATES:

November 1-5, 1993

AUDIT TEAM:

Bel Hentstone	/LILATEAL	fudda Taan Landau
Bob Hartstern	(MACTEC)	Audit Team Leader
Jim Conway	(EH-843)	Auditor/Audit Mgr.
Kriss Grisham	(EN-343)	Auditor
Lou Wade	(MACTEC)	Auditor
Dennis Strother	(MACTEC)	Auditor
Sid Crawford	(BDM/SAIC)	Auditor/Tech. Spec.
John Le Vea	(BDM/SAIC)	Auditor
Bob Jakubik	(BDM/SAIC)	Tech. Spec.
A	/==:4 -:11	

OBSERVERS:

(TBD)

AUDIT SCOPE:

The following program elements will be reviewed during this audit:

1.	Criterion 1	Organization
٤.	Critarion 3	Design Control

3. Criterion 4 Procurement Document Control

. Criterion 6 Document Control

5. Criterion 7 Control of Purchased Items and Services

6. Criterion 15 Nanconformances 7. Criterion 16 Corrective Action

B. Criterion 17 QA Records

9. Criterion 18 Audits

AUDIT OBJECTIVES:

To evaluate the effectiveness of WVPO implementation of their Quality Assurance Program as it applies to the Criteria identified in the audit scope above. Implementation of corrective actions resulting from Audit No. 93-EA-WV-AU-O1 will also be evaluated by the audit team.

9310210112 930929 PDR WASTE WM-1 PDR 10/16/83 12:48

ACTIVITIES TO BE AUDITED:

QA program elements and waste acceptance activities affecting high-level waste form production at the WVDP.

APPLICABLE REQUIREMENTS/CRITERIA:

- 1. ASME NDA-1-1989, "Quality Assurance Requirements for Nuclear Facilities" (including applicable Supplements and Appendices)
- 2. DOE/RW-0214, Rev. 4 w/ICN 4.1. "Quality Assurance Requirements Document"
- 3. DOE/EM/WO/O2, Rev 1. EM-343 HLW "Quality Assurance Program Description"
- 4. WVPD-074, QAPD-2 and 3 "KVDP Quality Assurance Program Description"
- 5. WVPO Implementing QA Program Procedures
 WVNS Implementing Quality Assurance Procedures

PRELIMINARY AUDIT SCHEDULE:

<u>Activity</u>	Pate	<u> Time</u>
Pre Audit Meeting	11/01/93	8:00a - 9:00a
Conduct Audit	11/01/93	9:00a - 4:00p
Conduct Audit	11/02-04/93	8:00a - 4:00p
Post Audit Meeting	11/05/93	11:00a - 12:00p

- Note: 1. Audit Team caucuses will be held daily at 4:00p to discuss daily results and obtain status of the audit progress.
 - 2. Daily briefings will be held with WVDP/WVNS management personnel at 8:00a to discuss the previous days results, both positive and negative.

PREPARED:

Audit Team Leader DATE: 9/25/95/ APPROVED: T. CONUTY DATE: 9/25/93

Audit Team Leader QA Program Manager/Audit Manager