



Entergy Nuclear Northeast
Entergy Nuclear Operations, Inc.
440 Hamilton Avenue
White Plains, NY 10601
Tel 914 272 3200
Fax 914 272 3205

Michael R. Kansler
President

June 24, 2003
NL-03-111

U.S. Nuclear Regulatory Commission
ATTN: Document Control Desk
Mail Stop O-P1-17
Washington, DC 20555-0001

SUBJECT: Indian Point Nuclear Generating Unit No. 2
Docket No. 50-247
Indian Point Nuclear Generating Unit No. 3
Docket No. 50-286
**Annual 10 CFR 50.46 Report for Year 2002-
Emergency Core Cooling System Evaluation Changes**

REFERENCES: (1) Westinghouse letter (IPP-03-26), S. Ira to J. DeRoy, "10 CFR 50.46 Annual Notification and Reporting for 2002", dated March 10, 2003.

(2) Entergy letter (NL-02-057) F. Dacimo to NRC "Annual 10 CFR 50.46 Report for Indian Point Unit 2", dated April 24, 2002.

(3) Westinghouse letter (INT-03-8), S. Ira to J. DeRoy, "10 CFR 50.46 Annual Notification and Reporting for 2002 ", dated March 10, 2003.

(4) Entergy letter (IPN-02-051) M. R. Kansler to NRC "Annual 10 CFR 50.46 Report for 2002- Emergency Core Cooling System Evaluation Changes", dated June 26, 2002.


Dear Sir:

Entergy Nuclear Operations, Inc. has reviewed the 2002 small and large break loss of coolant accident (LOCA) peak clad temperature (PCT) changes described in References (1) and (3) for Indian Point Unit 2 and Indian Point Unit 3, respectively. There are no additional changes to the small or large break PCTs since the submittal of References (2) and (4) for Indian Point Unit 2 and Indian Point Unit 3, respectively. Therefore, the Indian Point Unit 2 and Indian Point Unit 3 PCTs remain below the maximum fuel cladding temperature of 2200°F and Indian Point Unit 2 and Indian Point Unit 3 continue to comply with 10 CFR 50.46. This letter satisfies the reporting requirements of 10 CFR 50.46(a)(3)(ii).

A001

There are no new commitments made by this letter. If you have any questions, please contact Ms. Charlene Faison at 914-272-3378.

Very truly yours,



Michael R. Kansler
President
Entergy Nuclear Operations, Inc.

cc: Regional Administrator
Region I
U.S. Nuclear Regulatory Commission
475 Allendale Road
King of Prussia, PA 19406

Resident Inspector's Office
Indian Point Unit 3
U.S. Nuclear Regulatory Commission
P.O. Box 337
Buchanan, NY 10511-0337

Resident Inspector's Office
Indian Point Unit 2
U.S. Nuclear Regulatory Commission
P.O. Box 38
Buchanan, NY 10511-0038

Mr. Patrick D. Milano, Project Manager
Project Directorate I
Division of Reactor Projects I/II
U.S. Nuclear Regulatory Commission
Mail Stop O 8 C2
Washington, D.C. 20555

Mr. Paul Eddy
New York State Dept. of Public Service
3 Empire Plaza
Albany, NY 12223