




DOE/NRC Quarterly Quality Assurance Meeting







Quality Assurance Overview

Presented to:

DOE/NRC Quarterly Quality Assurance Meeting



Quality Assurance Overview

- Policy and Procedures
 - Quality Assurance Requirements and Description (QARD) status
 - AP-5.1Q review process
 - Organization/interface requirements
 - Procedures (DOE and BSC)




Quality Assurance Overview

- Assessments 3rd Quarter
 - Audit BSCP 03-07 of software
 - 8 Deficiency Reports (DRs) issued
 - Marginally effective
 - BSC specific oversight activities
 - 21 internal surveillances 8 DRs issued
 - 8 external supplier audits 14 DRs issued
 - Integrated internal audits
 - U.S. Geological Survey (USGS) BSC Lead Compliance Audit - 1 Quality Observation (QO) issued
 - Los Alamos National Laboratory (LANL) BSC Lead Compliance Audit - 1 QO issued

Quality Assurance Overview

- DOE Line Management Accountability
 - Quality focus stand down activities continue
 - Monthly operating review
 - Management interface meetings
 - Quality Engineering integrated with line management
 - Corrective action resolution
 - Weekly Condition/Issue Identification and Reporting/Resolution System (CIRS)/DR/Corrective Action Report (CARs) meetings








Model Validation (CAR BSC-01-C-001)

Presented to:

DOE/NRC Quarterly Quality Assurance Meeting



Model Validation Corrective Action Report Actions

- 11 of 11 actions identified in September 24, 2002 response (as modified by amended response) are complete
- One action completed since date of the last Quarterly Quality Assurance (QA) meeting
 - Use of performance indicators to assess the effectiveness of the self-identification process
 - Performance indicators show process of self-identification is effective

Model Validation Corrective Action Report Actions

(Continued)

Status of In-Process Reviews (as of June 30, 2003)

- 65 model reports are being developed under the revised procedure to support the LA
 - Includes models supporting features, events and processes screening and implementation of the criticality methodology
 - Technical Work Plans for each model, including model validation criteria, approved by the Chief Science Officer (CSO)
 - 51 model reports started in-process model validation review
 - 42 model reports approved by CSO during in-process model validation review
 - 22 model reports completed CSO technical review







Software Development (CAR BSC-01-C-002)

Presented to:


DOE/NRC Quarterly Quality Assurance Meeting

Presented by:
Nancy H. Williams
Manager of Projects
Bechtel SAIC Company, LLC

July 15: 2003
Rockville Waryland

Software Code Status (Counts as of June 26, 2003)

Codes (Estimate)



Total Codes: 380

- Qualified and completed IV&V: 39 (10%)
- Submitted for IV&V: 10 (3%)
- Qualified, Need Re-testing (Legacy Software): 306 (80%) estimated
- **Index Index Inde**

Timeline for Completion

7/03 Decision on Lifting Standdown

9/03
Corrective Actions
Complete - Request
Verification

6/03
Start of
Legacy Code
Retesting

8/03 Self Assessment





Management of Data (CAR BSC(B)-03-C-107) and Data Qualification

Presented to:

DOE/NRC Quarterly Quality Assurance Meeting

Presented by:
Nancy H. Williams
Manager of Projects

Bechtel SALE Company LLC

July 15, 2008

Rockville, Mary and

Data Confirmation Project

- Incorporated into checking and review functions
- Separate data checklist developed
 - Phase I addresses compliance issues
 - Phase II will address technical adequacy
- Checklist review will document lessons learned for process improvements

Metrics

- Data Confirmation Project
 - Approximately 120 technical products* support LA
 - 35 products have completed Phase I
 - 4 products completed Phase II

*Analysis/model reports (AMRs) and technical reports








Procedure Implementation (CAR BSC(O)-03-C-097)

Presented to:

DOE/NRC Quarterly Quality Assurance Meeting



Procedure Implementation (CAR BSC(O)-03-C-097)

OQA Evaluation

- OQA provided a write-up of concerns to the CAR response and Root Cause Report - June 19, 2003
- 11 Corrective Action (CA) issues required a response and
 21 issues required clarification to the Root Cause Report
- BSC provided responses to OQA's comments on July 7, 2003








Training and Qualification CAR BSC-02-C-001

Presented to:

DOE/NRC Quarterly Quality Assurance Meeting



Corrective Action Report BSC-02-C-001

- Corrective Action Report (CAR) closure dependent on closer of Deficiency Reports (DRs)
 - DR BSC-01-D-129: Training to procedures not performed within time requirements
 - This DR was closed February 12, 2003
 - DR BSC(B)-02-D-159: VoEE of personnel not located
 - Where required, the VoEE has been documented for all BSC and subcontractor personnel
 - This DR was closed May 14, 2003
 - DR BSC(O)-02-D-176: VoEEs do not meet Position Descriptions, no evidence of Position Descriptions for employees, VoEEs not approved by Functional Manager, and work performed prior to VoEE approval
 - DR is still open with closure scheduled for September 30, 2003






Design Oversight

Presented to:

DOE/NRC Quarterly Quality Assurance Meeting



Design Oversight

Quality Engineering's Reviews Controlled by Checklists

QE C	hecklists					
Engineering Products						
AP-3.11Q, Technical Reports	AP-3.25Q, Design Criteria					
AP-3.12Q, Design Calculations and	 LP-3.26Q, System Description Documents 					
Analyses	 LP-4.5Q, Purchase Requisitions and 					
AP-3.15Q, Managing Technical Product	Procurement Documents					
Inputs	AP-15.3Q, Control of Technical Product Errors					
AP-3.19Q, Specifications						
• AP-3.24Q, Drawings						
Science	e Products					
 AP-2.27Q, Planning for Science Activities 	AP-SIII.7Q, Scientific Investigation Laboratory					
AP-3.11Q, Technical Reports	and Field Testing					
AP-15.3Q, Control of Technical Product	• AP-SIII.9Q, Scientific Analyses					
Errors	• AP-SIII.10Q, Models					
 AP-SIII.2Q, Qualification of Unqualified Data 						
General Check	klist Content Areas					
General Subjects Document Co	•					
Revision/Change Process Software Use	& Control • Approval Process					

Design Oversight Quality Engineering Capability Matrix

Engineering

C=Civil

E&IC≈Electrical/

Instrumentation & Control

G=General Engineering

M=Mechanical

N=Nuclear

Infrastructure

DC=Document Control

L=Licensing

RM=Records Mgmt.

P=Procurement

S=Software

T=Training

Current Assignment	Capability Matrix											
Name	Engineering				Science			Infrast	ructur	9		
Science	С	E&IC	G	M	N		DC	L	RM	P	S	T
Quality Engineer			X									
Quality Engineer						X						
Quality Engineer			X									
Quality Engineer						X						
Quality Engineer						X						
Quality Engineer	Х		<u>x</u>									
Quality Engineer												
Quality Engineer				X	X							
Quality Engineer						X		1			1	
Engineering		. 		<u> </u>	<u>-</u>	-	•	<u> </u>	<u> </u>		<u></u>	<u> </u>
Quality Engineer				X								<u> </u>
Quality Engineer		X										
Quality Engineer			Х									
Quality Engineer				X								
Quality Engineer				X	X							
New Hire		X										
New Hire			X									
New Hire			X									
Infrastructure		<u> </u>			· · · · · · · · · · · · · · · · · · ·			<u> </u>			·•	·
Quality Engineer							X	X	X			X
Quality Engineer				X	X						X	
Quality Engineer							Х		X			X
Quality Engineer							X		X			X
Quality Engineer										X		
Quality Engineer							X	X	X			X
Quality Engineer							X	X	X			X
Quality Engineer			•							X		
Transfer							X		X			

Design Oversight

- Audits and Surveillances
 - Audits
 - Design audit scheduled for August, 2003
 - Surveillances
 - 10 conducted on design activities through 3rd quarter FY2003
 - 10 scheduled for design activities during 4th quarter FY2003

Design Oversight Summary

- Design is a key program activity that is increasing in importance
 - BSC QA has the skill mix and numbers of Quality Engineers to ensure adequate design oversight based on design schedules
- Science oversight will continue







Corrective Action Program

Presented to:

DOE/NRC Quarterly Quality Assurance. Meeting

Presented by:

R. Dennis Brown

Director, Office of Quality Assurance.

Office of Civilian-Radioactive Waste Management

U.S. Department of English

Aldivals ands

Resident len Waley Eust

and the second

- Quality Assurance involvement in the Corrective Action Program (CAP)
 - Quality Assurance still issues Condition Reports, no loss of independence
 - Quality Assurance Representative:
 - Reviews each Condition Report before issuance
 - » Determines significance
 - » Determines if Stop Work Order needed
 - Approves corrective action plan
 - Verifies corrective actions complete




- Improvements (September 30, 2003)
 - Benchmarked program against:
 - Institute of Nuclear Power Operations (INPO's), Principles for Effective Self-assessment and Corrective Action Programs
 - Nuclear Energy Institute (NEI), Corrective Action Program Benchmarking Report (NEI, LP-0002)
 - Communications plan
 - Training plan




(Continued)

Days to Obtain Acceptable DR Response (as of July 3, 2003)



(Continued)

Average Days Open - DRs (as of July 3, 2003)







Trending Program Improvements



Trending Program Improvements

(Continued)

Actions Taken

- Cause codes changed
 - DOE Occurrence Reporting and Processing System (ORPS): cause codes being used
- Condition Reports from May 2002 to May 2003 recoded
- New Condition Reports are being coded
- Open Condition/Issue Identification and Reporting/Resolution System (CIRS) items recoded
- All CIRS items being recoded
- New CIRS items are being coded
- Common coding increases population for trending

Trending Program Improvements

(Continued)

Major Contributor

Major Contributing Factor

Root Cause

Management problem (35%)

Management methods

hods Management policy, guidance,

LTA* (62%)

expectations not well defined, understood or enforced (73%)

Human performance LTA*(34%)

Skill based error (51%)

Check of work LTA* (48%)

Communications LTA* (21%)

Written communications content LTA* (83%)

Ambiguous instructions or requirements (39%)


*LTA = less than adequate



Trending Program Improvements (Continued)

- Changing reporting frequency to quarterly
- Transferred trend reporting to BSC
 - BSC collects and analyzes data
 - BSC identifies corrective actions
 - DOE still responsible for issuing quarterly report
- Continue to improve








Quality Assurance Requirements and Description Document Status

Presented to:

DOE/NRC Quarterly Quality Assurance Meeting



Quality Assurance Requirements and Description Document Status

- QARD Revision 14 approach
 - 24 integrated teams of DOE Office of Quality Assurance (OQA), DOE Line, and contractor personnel
 - Teams to develop positions on aspects of 10 CFR 63 and the YMRP to assure compliance
 - OQA developed crosswalk checklists of YMRP and Part 63 requirements to assure coverage in the QARD

Quality Assurance Requirements and Description Document Status

- Examples of compliance checklists
 - 10 CFR 63 Subpart G, Quality Assurance
 - NUREG-1804, Yucca Mountain Review Plan, final draft,
 Section 2.5.1, Quality Assurance Program

10 CFR 63-Subpart-G^a - QARD^b Compliance Matrix

a- Revised as of January 1, 2003

b-Quality Assurance Requirements and Description, Draft Revision 14

Example

Subpart G - Quality Assurance

[SOURCE DOCUMENT]

10 CFR 63 SECTION	10 CFR 63 REQUIREMENTS	QARD SECTION
.141	Scope	
	As used in this part, quality assurance comprises all those planned and systematic actions necessary to provide adequate confidence that the geologic repository and its structures, systems, and components will perform satisfactorily in service.	
	Quality assurance includes quality control, which comprises quality assurance actions related to the physical characteristics of a material, structure, component, or system to predetermined requirements.	
.142	Quality Assurance Criteria	
(a)	Introduction and Applicability	
	DOE is required by 63.21(c)(20) to include in its safety analysis report a description of the quality assurance program to be applied to all structures, systems, and components important to safety, to design and characterization of barriers important to waste isolation, and to related activities.	
	These activities include: site characterization; acquisition, control, and analyses of samples and data; tests and experiments; scientific studies, facility and equipment design and construction; facility operation; performance confirmation; permanent closure; and decontamination and dismantling of surface facilities.	
	The description must indicate how the applicable quality assurance requirements will be satisfied.	
	DOE shall include information pertaining to the managerial and administrative controls to be used to ensure safe operation in its safety analysis report.	agis sa





Integration and Coordination of Audits

Presented to:

DOE/NRG Quarterly Quality Assurance Meeting.

Presented by:

Kerny Grooms

Office of Civilian Radioactive Waste Management

U.S. Department of Energy

JUKAK532003

frackville Webvieleit

Integration and Coordination of Audits



- After Integration
 - 13 audits scheduled for the remainder of FY-2003
 - 10 are joint audits
 - 3 are OQA only audits
 - » Office of Repository Development (scope)
 - » Software (scheduling)
 - » Annual audit of OQA (scope)



Integration and Coordination of Audits

- Data, Software and Modeling audits coordinated by
 - Sample selection overlap
 - Maintaining team dynamics with consistent team membership
 - Conducting audits in sequence

