

Department of Energy

Nevada Operations Office P. O. Box 98518 Las Vegas, NV 89193-8518 OCT 11 1989

WBS 1.2.9.3 QA

Joseph C. Calovini
Technical Project Officer for Yucca Mountain Project
Holmes & Narver, Inc.
101 Convention Center Drive
Phase II, Suite P-280
Las Vegas, NV 89109

CLOSURE OF STANDARD DEFICIENCY REPORT (SDR) 332, REVISION 0, RESULTING FROM YUCCA MOUNTAIN PROJECT OFFICE QUALITY ASSURANCE AUDIT 89-02 OF HOLMES & NARVER, INC.

SDR 332, Revision 0, has been closed based on satisfactory verification of completed corrective actions. A copy of the SDR is enclosed for your files.

If you have any questions, please contact James Blaylock of my staff at 794-7913, or Frederick J. Ruth of Science Applications International Corporation at 794-7737.

Edwin L. Wilmot, Acting Director Quality Assurance Division Yucca Mountain Project Office

YMP:JB-233

Enclosure: SDR 332, Revision 0

cc w/encl:

Ralph Stein, HQ (RW-30) FORS Dwight Shelor, HQ (RW-3) FORS

J. J. Brogan, SAIC, Las Vegas, NV, 517/T-12

K. A. Hodges, SAIC, Las Vegas, NV, 517/T-06

F. J. Ruth, SAIC, Las Vegas, NV, 517/T-06

J. H. Nelson, SAIC, Las Vegas, NV, 517/T-04

A. E. Gurrola, H&N, Las Vegas, NV

S. W. Zimmerman, NWPO, Carson City, NV

J. E. Kennedy, NRC, Washington, DC

cc w/o encl:

A. L. Temple, SAIC, Las Vegas, NV, 517/T-38

Richard Ivy, H&N, Las Vegas, NV

C. O. Wright, H&N, Las Vegas, NV

J. W. Gilray, NRC, Las Vegas, NV

Mm-11

ORIGINAL THIS IS A RED STAMP

••	Υ	MPO STANDARD DEFICIENCY REPORT	N-QA-038 4/89
Completed by Originating QA Organization	1 Date 4-27-89	2 Severity Level 1 1 2 3	Page 1 of 2
	3 Discovered During Audit 89-2	A 91 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	SDR No. Rev. 0
	5 Organization Holmes & Narver	6 Person(s) Contacted C. Wright	7 Response Due Date is 20 Working Days from Date of Transmittal
	8 Requirement (Audit Checklist Reference, if Applicable) NNWSI/88-9, Rev. 2, Sec. 1, Para. 1.0, Organization, Audit Checklist Reference 1-1, states in part: The organizational structure, lines of communication, authority, and duties of persons or organizations performing activi-		
	Operation of the above requirement, Han's QAPP does not address the organizational structure, lines of communication, and authority and duties of the NTSO organization or the EGG organization. Both organizations perform QA		
	10 Recommended Action(s): A Remedial Investigative A Corrective Develop a method of identifying and defining the NTSO and EG&G functions.		
Aprvl.	11 QAE/Lead Auditor/Da	Holoa Colon All Maril on 10. F	Dject Quality Mgr./Date
eted by Organization in Block 5	14 Remedial/Investigative Action(s) Holmes & Narver, Inc., (H&N) will (1) revise procedures Effective Date 7/7/89 NNWSI-011, Nonconformance Control, by deleting all reference to NTSO and to reflect that all NCR's will be directed to the Yucca Mountain Project Office for further processing, and (2) will revise procedure NNWSI-010, Control of Measuring and Test Equipment, by deleting the reference to REECo or EG&G. Calibration services will be provided by approved sources. (Continued - See Page 2 of 2)		
	16 Cause of the Condition & Corrective Action to Prevent Recurrence 17 Effective Date NO corrective action to prevent recurrence deemed necessary.		
	no corrective action	to prevent recurrence dealled necessary.	
Completed	18 Signature/Date Joseph C. Colonii 4/4/89		
Comp. by Orig	19 Response Accepted 20 Corrective Action	DAE/Lead Auditor/Date Division Manager/Date DAE/Lead Auditor/Date Division Manager/Date Division Manager/Date	
	Verif. Satisfactory 21 Remarks	reduck Kut 19489 labely 10 4	Project Quality Mgr./Date
	amended coponse receiped: - ymp: TPO: 89-392, dated 1/24/89		
	The two above lated projectives (1210 + 1510) work revelved. Reference to NTSD and EGAG have been removed. 22 QAE/Lead Auditor/Date, Division Manager/Date POM/Date.		
	QA CLOSURE PRAIM	ead Auditor/Date, Division Manager/Date PON	Water Shulady 10/4/87

ENCLOSURE

YMPO STANDARD DEFICIENCY REPORT **CONTINUATION SHEET**

N-QA-038 12/88

SDR No. 332

Rev.

Page 2

of 2

8 Requirement (continued) ties affecting quality shall be clearly established and delineated in writing.

9 Deficiency (continued) functions on the Project, and both are referenced in H&N implementing procedures.

14 Remedial/Investigative Action(s) (Continued)

H&N has requested direction from the Yucca Mountain Project Office relating to the responsibilities and authority of NTSO as they relate to the design, construction, and evaluation phases of the project (Letter YMP:TPO:89-343 attached).



Holmes & Narver

Energy Support Division Nevada Operations

YMP:TPO:89-343

WBS 1.2.9.3 OA

June 6, 1989

Carl P. Gertz
Project Manager
Yucca Mountain Project Office
Nevada Operations Office
U.S. Department of Energy
P.O. Box 98518
Las Vegas, NV 89193-8518

REQUEST FOR CLARIFICATION OF THE RESPONSIBILITIES AND AUTHORITY OF NEVADA TEST SITE OPERATIONS WITH REGARDS TO THE YUCCA MOUNTAIN PROJECT

Reference: YMP: WBM-3673 dated May 8, 1989, Subject: Issuance of Standard Deficiency Report (SDR) 332, Resulting from Yucca Hountain Project Office (Project Office) Quality Assurance (QA) Audit 89-2 of Holmes & Narver, Inc. (H&N) (NN1-1989-2173)

Standard Deficiency Report 332 cited that the Holmes & Narver Quality Assurance Plan is deficient in that it does not address the organizational structure, lines of communication, authority, and duties of the NTSO organization, as they relate to Holmes & Narver and the Yucca Hountain Project.

H&N's QAPP was written to meet the requirements of the Project Quality Assurance Plan, 88/9. The Project QA Plan does not define or address the NTSO's responsibilities as relating to the Yucca Mountain Project. H&N requests direction from the Project Office on the structure of the relationship with NTSO. This will be added to the QAPP as appropriate. Until such direction is received, the procedure referencing NTSO will be changed to remove those references. The implementing procedure for Nonconformance Reports (NCR) will have the NCR sent to the YMP Office, not NTSO for processing.

Carl P. Gertz
CLARIFICATION OF RESPONSIBILITIES AND AUTHORITY OF NTSO
YMP:TPO:89-343
June 6, 1989
Page 2

If you have any questions, please contact Mr. Carl O. Wright, Manager, QA, at 794-7066.

1. C/ Calovini

Technical Project Officer Yucca Hountain Project

cc: E. L. Vilmot, DOE/YHP, Las Vegas, NV

J. Blaylock, DOE/YHP, Las Vegas, NV

J. D. Stevart, DOE/NTSO, Hercury, NV

S. Hetta, SAIC, Las Vegas, NV

H. H. Caldvell, SAIC, Las Vegas, NV

F. J. Ruth, SAIC, Las Vegas, NV

R. V. Gray, IMD, Las Vegas, NV

S. Berkel, IMD, Las Vegas, NV

SDR-332 (AMENDED RESPONSE)

14 Remedial/Investigative Action(s)

Holmes & Narver, Inc., (H&N) will (1) revise procedure NNWSI-011, Nonconformance Control, by deleting all reference to NTSO and to reflect that all NCR's will be directed to the Yucca Mountain Project Office for further processing, and (2) will revise procedure NNWSI-010, Control of Measuring and Test Equipment, by deleting the reference to REECo or EG&G. Calibration services will be provided by approved sources.

NOTE: H&N has requested direction from the Yucca Mountain Project Office relating to the responsibilities and authority of NTSO as they relate to the design, construction, and evaluation phases of the project (Letter YMP:TPO:89-343 attached).

Effective Date 7/7/89

16 Cause of the Condition & Corrective Action to Prevent Recurrence

The Project Office has not provided any direction of the NTS Organization's function or authority within the Yucca Mountain Project.

Action to prevent recurrence is the responsibility of the Project Office.

Effective Date N/A

Joseph C. Colonini

7/21/89



Holmes & Narver

Energy Support Division Nevada Operations

YMP:TPO:89-343

WBS 1.2.9.3 OA

June 6, 1989

Carl P. Gertz
Project Hanager
Yucca Hountain Project Office
Nevada Operations Office
U.S. Department of Energy
P.O. Box 98518
Las Vegas, NV 89193-8518

REQUEST FOR CLARIFICATION OF THE RESPONSIBILITIES AND AUTHORITY OF NEVADA TEST SITE OPERATIONS WITH REGARDS TO THE YUCCA HOUNTAIN PROJECT

Reference: YMP: VBM-3673 dated May 8, 1989, Subject: Issuance of Standard Deficiency Report (SDR) 332, Resulting from Yucca Hountain Project Office (Project Office) Quality Assurance (QA) Audit 89-2 of Holmes & Narver, Inc. (H&N) (NN1-1989-2173)

Standard Deficiency Report 332 cited that the Holmes & Narver Quality Assurance Plan is deficient in that it does not address the organizational structure, lines of communication, authority, and duties of the NTSO organization, as they relate to Holmes & Narver and the Yucca Mountain Project.

H&N's QAPP was written to meet the requirements of the Project Quality Assurance Plan, 88/9. The Project QA Plan does not define or address the NTSO's responsibilities as relating to the Yucca Mountain Project. H&N requests direction from the Project Office on the structure of the relationship with NTSO. This will be added to the QAPP as appropriate. Until such direction is received, the procedure referencing NTSO will be changed to remove those references. The implementing procedure for Nonconformance Reports (NCR) will have the NCR sent to the YMP Office, not NTSO for processing.

Carl P. Gertz CLARIFICATION OF RESPONSIBILITIES AND AUTHORITY OF NTSO YMP:TPO:89-343 June 6, 1989 Page 2

If you have any questions, please contact Mr. Carl O. Wright, Manager, QA, at 794-7066.

1. C/ Calovini

Technical Project Officer Yucca Hountain Project

cc: E. L. Vilmot, DOE/YMP, Las Vegas, NV

J. Blaylock, DOE/YMP, Las Vegas, NV

J. D. Stevart, DOE/NTSO, Hercury, NV

S. Hetta, SAIC, Las Vegas, NV

H. H. Caldvell, SAIC, Las Vegas, NV

F. J. Ruth, SAIC, Las Vegas, NV

R. V. Gray, IMD, Las Vegas, NV

S. Berkel, IMD, Las Vegas, NV

SDR-332 (AMENDED RESPONSE)

14 Remedial/Investigative Action(s)

Holmes & Narver, Inc., (H&N) will (1) revise procedure NNWSI-011, Nonconformance Control, by deleting all reference to NTSO and to reflect that all NCR's will be directed to the Yucca Mountain Project Office for further processing, and (2) will revise procedure NNWSI-010, Control of Measuring and Test Equipment, by deleting the reference to REECo or EG&G. Calibration services will be provided by approved sources.

NOTE: H&N has requested direction from the Yucca Mountain Project Office relating to the responsibilities and authority of NTSO as they relate to the design, construction, and evaluation phases of the project (Letter YMP:TPO:89-343 attached).

Effective Date 7/7/89

16 Cause of the Condition & Corrective Action to Prevent Recurrence

The Project Office has not provided any direction of the NTS Organization's function or authority within the Yucca Mountain Project.

Action to prevent recurrence is the responsibility of the Project Office.

Effective Date N/A

Joseph C. Colonia

7/2/89